# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building 78 Shenton Way #08-16 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 079120 Singapore 408933

Attn: Date: 15 Jan 2020

## **Preliminary Advice**

Vehicle No : SKE6183J Accident Date : 13/01/2020 : 1800098325-01 Make : AUDI A6 Policy No.

**Assignment Date** : 14/01/2020 **Excess** : S\$0.00 Date of Inspection : 14/01/2020 Est. Duration of Repair : 10 days

Inspection At : Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	70,805.00
Revised Amount	:S\$	33,128.00
Check Items (Estimated)	:S\$	20,668.00
Total	:S\$	53,796.00

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 152,000.00 COE / PARF Rebate :S\$ 67,665.00

Salvage Value :S\$

Margin for Repair 84,335.00 :S\$

### Remarks

X	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage Kindly let us have your authorisation.
	)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
	)	Other comments :