

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 25973

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0041/2020/NS
Date : 13-Jan-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian,
3 days - ok - Carrine

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Lim Tsen Yong
Address : 89 Pasir Ris Grove
#09-24
Singapore 518214
Telephone : HP +65 90061410
Type of Claim : Own Damage Claims
Policy No. : 2100329576-06
Vehicle No : **SKH 9813 P**
Model Code : Audi A4 1.8T FSI MU 8K203
Model / Year : Jan-13
Engine No : CJE 017590
Chassis No : WAUZZZ8K6DA057923
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-Jan-20
Place of Accident : Slip Road At Bradell Rd Towards Marymount Flyover

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKH 9813 P

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
2	To dismantle and renew front bumper and lhs headlight. Re-organise crash management components. Reinstall all parts removed.		\$ 1,400.00	\$ 750.00
3	To respray front bumper and lhs front fender.		\$ 2,000.00	\$ 550.00
4	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 3,952.00	\$ 1,852.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 9813 P

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	Remarks
1	FRONT BUMPER	\$ 2,041.00	\$ 1,688.00
2	FRONT BUMPER FIXING PARTS	\$ 234.00	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 207.00	
4	FRONT BUMPER GRILLE - LOWER CENTRE	\$ 123.00	
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	\$ 177.00	
6	FRONT BUMPER SUPPORT ELEMENT - UPPER	\$ 54.00	
7	RADIATOR GRILLE	\$ 1,005.00	\$ 804.00
8	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 123.00	\$ 98.00
9	FRONT WHEEL SPOILER - LH	\$ 45.00	
10	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$ 802.00	
11	FRONT BUMPER FOAM FILLER PIECE	\$ 113.00	
12	FRONT BUMPER SUPPORT	2 \$ 23.00	
13	FRONT BUMPER GUIDE SECTION - LH	\$ 33.00	
14	FRONT BUMPER COVER	\$ 116.00	
15	CAUTION SIGN STICKER	NEC \$ 13.00	
16	AIRCON STICKER	NEC \$ 22.00	
17	SIGNAL HORN - LH HIGH TONE	\$ 184.00	
18	SPRING SHACKLE - LH HIGH TONE	\$ 23.00	
19	HEADLIGHT MOUNTING - LH	\$ 107.00	
20	HEADLIGHT BRACKET	\$ 96.00	
SUB TOTAL SPARE PARTS		: \$ 5,541.00	\$ 2,590.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 9813 P

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	Remarks
		b/f	\$ 2,590.00
21	HEADLIGHT COUPLING ELEMENT	\$ 29.00	
22	HALOGEN HEADLIGHT - LH	\$ 994.00	\$ 821.60
23	HALOGEN FOG LAMP - LH	\$ 242.00	
24	RADIATOR AIR GUIDE - LH	\$ 24.00	
25	FRONT NO PLATE	S/N \$ 40.00	\$ 40.00
26	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS CHARGES		: \$ 7,170.00	\$ 3,451.60
TOTAL LABOUR CHARGES		: \$ 3,952.00	\$ 1,852.00
GRAND TOTAL		: \$ 11,122.00	\$ 5,303.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.