

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 25973

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0041/2020/NS
Date : 13-Jan-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Lim Tsen Yong
Address : 89 Pasir Ris Grove
#09-24
Singapore 518214
Telephone : HP +65 90061410
Type of Claim : Own Damage Claims
Policy No. : 2100329576-06
Vehicle No : **SKH 9813 P**
Model Code : Audi A4 1.8T FSI MU 8K203
Model / Year : Jan-13
Engine No : CJE 017590
Chassis No : WAUZZZ8K6DA057923
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-Jan-20
Place of Accident : Slip Road At Bradell Rd Towards Marymount Flyover

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKH 9813 P

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To dismantle and renew front bumper and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,400.00	750
3	To respray front bumper and lhs front fender.	\$ 2,000.00	550
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 3,952.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 9813 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER <i>reld</i>	\$ 2,041.00	<i>✓</i> 1688
2	FRONT BUMPER FIXING PARTS <i>neu</i>	\$ 234.00	<i>+</i>
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>neu</i>	\$ 207.00	<i>+</i>
4	FRONT BUMPER GRILLE - LOWER CENTRE <i>neu</i>	\$ 123.00	<i>+</i>
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>neu</i>	\$ 177.00	<i>+</i>
6	FRONT BUMPER SUPPORT ELEMENT - UPPER <i>neu neu</i>	\$ 54.00	<i>+</i>
7	RADIATOR GRILLE <i>cracked.</i>	\$ 1,005.00	<i>✓</i> 804.00
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>nt</i>	\$ 123.00	<i>✓</i> 98.00
9	FRONT WHEEL SPOILER - LH <i>neu</i>	\$ 45.00	<i>+</i>
10	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>neu</i>	\$ 802.00	<i>+</i>
11	FRONT BUMPER FOAM FILLER PIECE <i>neu</i>	\$ 113.00	<i>+</i>
12	FRONT BUMPER SUPPORT <i>2 neu</i>	2 \$ 23.00	<i>+</i>
13	FRONT BUMPER GUIDE SECTION - LH <i>neu</i>	\$ 33.00	<i>+</i>
14	FRONT BUMPER COVER <i>2</i>	\$ 116.00	<i>+</i>
15	CAUTION SIGN STICKER <i>neu</i>	NEC \$ 13.00	<i>+</i>
16	AIRCON STICKER <i>neu</i>	NEC \$ 22.00	<i>+</i>
17	SIGNAL HORN - LH HIGH TONE <i>2</i>	\$ 184.00	<i>+</i>
18	SPRING SHACKLE - LH HIGH TONE <i>neu</i>	\$ 23.00	<i>+</i>
19	HEADLIGHT MOUNTING - LH	\$ 107.00	<i>+</i>
20	HEADLIGHT BRACKET <i>neu</i>	\$ 96.00	<i>+</i>
SUB TOTAL SPARE PARTS		: \$ 5,541.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 9813 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
21	HEADLIGHT COUPLING ELEMENT <i>Not in</i>	\$ 29.00	+
22	HALOGEN HEADLIGHT - LH <i>Not</i>	\$ 994.00	✓ 821.60
23	HALOGEN FOG LAMP - LH <i>Not in</i>	\$ 242.00	+
24	RADIATOR AIR GUIDE - LH <i>Not in</i>	\$ 24.00	+
25	FRONT NO PLATE <i>Not in</i>	S/N \$ 40.00	✓ 40.00
26	SUNDRIES <i>Not in</i>	\$ 300.00	+

TOTAL SPARE PARTS CHARGES	:	\$ 7,170.00
TOTAL LABOUR CHARGES	:	\$ 3,952.00
GRAND TOTAL	:	\$ 11,122.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling -
Surveyed Date : 14/01/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant