

Date: 14.01.2020
Vehicle No: SMQ3346P
Model: HONDA FIT
Chassis: GK33415713-2019
Reg.Year: 2019

Third Party Insurer: QBE
Third Party Veh No: GBD5129K
Date of Accident: 13.01.2020

*Not with paint
Respray B4 paint*

*\$ 4846.00
5 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE <i>814</i>	1		<i>Re</i> \$1,216.40 ✓
2	REAR TAILGATE "FIT" EMBLEM	1		<i>Re</i> \$58.20 ✓
3	REAR TAILGATE INNER LOCK <i>145.50</i>	1		<i>Re</i> \$368.70 ✓
4	REAR TAILGATE WIPER ARM COVER	1		<i>CM</i> \$69.20 ✓
5	REAR TAILGATE RUBBER	1		<i>Re/CM</i> \$79.60 ✓
6	REAR TAILGATE INNER TRIM CLIPS	8	\$6.50	<i>Re</i> \$52.00 ✗
7	REAR TAILGATE GARNISH COVER <i>232.60</i>	1		<i>CM</i> \$472.80 ✓
8	REAR TAILGATE GARNISH COVER "H" EMBLEM	1		<i>Re</i> \$72.60 ✓
9	REAR TAILGATE GARNISH COVER CLIPS	8	\$7.20	<i>Re</i> \$57.60 ✓
10	REAR WINDSCREEN RUBBER	1		<i>Re</i> \$128.00 ✓
11	REAR TAIL LAMP LH <i>493.30</i>	1		<i>CM</i> \$672.00 ✓
12	REAR TAIL LAMP RH <i>493.30</i>	1		<i>CM</i> \$672.00 ✓
13	REAR END PANEL UPPER COVERING	1		<i>Re</i> \$278.60 ✓
14	REAR END PANEL UPPER COVERING CLIPS	6	\$6.50	<i>Re</i> \$39.00 ✓
15	REAR SPARE TYRE PANEL UPPER BOARD COVER	1		<i>Re/Re</i> \$298.60 ✓
16	REAR BUMPER <i>580</i>	1		<i>Re</i> \$1,103.60 ✓
17	REAR BUMPER CLIPS	10	\$5.80	<i>Re</i> \$58.00 ✓
18	REAR BUMPER SIDE BRACKET LH	1		<i>Dis</i> \$67.20 ✓
19	REAR BUMPER SIDE BRACKET RH	1		<i>Dis</i> \$67.20 ✓
20	REAR BUMPER LOWER GARNISH	1		<i>Re</i> \$138.90 ✗
21	REAR BUMPER LOWER COVER	1		<i>Re</i> \$412.60 ✗
22	REAR END PANEL	1		REPAIR
SUB TOTAL				\$6,382.80 <i>\$5779.30</i>
LESS 20%				-\$1,276.56 <i>\$1155.86</i>
PARTS TOTAL				\$5,106.24 <i>\$4623.41</i>

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>Re</i> \$80.00 <i>4012</i>
2	REAR WINDSCREEN STOPPER	2	\$15.00	<i>Re</i> \$30.00 ✗
3	REARBUMPER REVERSE SENSOR	1		<i>Re</i> \$350.00 <i>20012</i>
S/N TOTAL				\$460.00 <i>\$240</i>

Date: 14.01.2020
Vehicle No: SMQ3346P
Model: HONDA FIT
Chassis: GK33415713-2019
Reg.Year: 2019

Third Party Insurer: QBE
Third Party Veh No: GBD5129K
Date of Accident: 13.01.2020

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX, READJUST REAR ACCIDENT AREAS & ETC.

\$800.00 *500/*

LABOUR CHARGES TO REMOVE, REFIX, REPLACE REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN RUBBER & ETC. TO EFFECT REPLACE AT REAR TAILGATE.

\$150.00 *120/*

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. TO EFFECT REPLACE AT REAR TAILGATE.

\$100.00 *60/*

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$80.00 *50/*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR END PANEL, REAR BUMPER & ETC.

\$800.00 *600/*

LABOUR CHARGES TO CHECK WIRING & ELECTRICAL WIRING SYSTEM & CENTRAL LOCKING SYSTEM.

\$80.00 *20/*

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$100.00 *30/*

LABOUR TOTAL \$2,110.00 *\$1380*

ONG	TOTAL	\$7,676.24
-----	-------	------------

Finalise:

Parts: \$4623.44

Nett: \$240

Labour: \$1380

~~\$6243.44~~ Part by Part & 5 days

7/2/2020

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

