

ASS. REC. BY:

REF:

7/1/1/ CC3/Tm1 20000908/K1f3n2

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

/

SHD 5211J - CC3 / A3415007622 / K29342

SLL 8084A - X

RCA - 0705/2016

15/1- 3:39 - revert & verified to toko via email preli, Gia, estimate
part by part R751.95 (red: 23781.33 96%)

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal.

D.O.I.

Date/Time, File Pass to?

11/12 Typist

Date/Time, File Return to?

7)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 2

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

250

11

261

Report Format:

Lump Sum / I.B.I. (\$)

751.95



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 15/01/2020

Our Ref: CC3/TMI20000908/Ktf3

The Motor Claims Department
TOKIO MARINE INSURANCE SINGAPORE LTD

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SHD 5211J.

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 14/01/2020 at the premises of M/s Transcab and have the following to report: -

Workshop Estimate Amount	: S\$ 24,533.28
Revised Estimate Amount	: S\$ 862.60
"Check" Items Amount	: S\$ 150.00
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the rear portion.



Repair days: 2

Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 15 January 2020 3:39 PM
To: motorclaims@tokiomarine.com.sg
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 11/01/2020, SHD 5211J (TP VEHICLE), SLL 8084A (OI VEHICLE)
Attachments: Police Report.pdf; GIA.pdf; ESTIMATE1.pdf; PRELI ADVISED OF SHD 5211J.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 5211J at M/s: TRANS-CAB AUTO SERVICES PTE LTD, 2 ANG MO KIO ST 63 SINGAPORE 569111 on 14/1/2020.

Enclosed herewith a copy of TP's GIA report, Police Report, Preliminary and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[» Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD5211J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B92968
Chassis No.:	JTDKB3FU203078602
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	19 Dec 2018
First Registration Date:	19 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$14,247.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2026
PARF Rebate Amount:	\$10,685.00
Intended COE Rebate Details	
COE Expiry Date:	18 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$22,057.00
COE Rebate Amount:	\$17,645.00
Total Rebate Amount:	\$28,330.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 13 Jan 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/01/2020 10:15
Date Of Accident	11/01/2020 19:45
Exact Location Of Accident	HILLVIEW AVENUE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD5211J
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	2XXXXX878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

Driver

Name of Driver	TAN SOON LYE
NRIC No	SXXXX390A
Date Of Birth	13/07/1963
Occupation	OUTDOOR
Date Of Driving Pass	05/12/1990
Driving Experience	29 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90691307
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 946 HOUGANG STREET 92 #11-169
Postcode	530946
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOGANG N.P.C
Police Station Address	ROAD: 60 HOUGANG AVE 9 SINGAPORE 538775 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20200112/2015

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL8084A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MR LIM
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAN SOON LYE

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHD5211J

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20200112/2015

1 of 3

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20200112/2015

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/01/2020 04:09		Vide Report No.:		Station Diary No.: 18	
Informant's Particulars					
Name of Informant: TAN SOON LYE			Address: APT BLK 946 HOUGANG STREET 92 #11-169 SINGAPORE 530946		
ID Type / ID No.: NRIC NO / S1588390A			Contact No.: Home/Office:		Mobile: 90691307
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 56	Date of Birth: 13/07/1963	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 11/01/2020 19:45	Type of Location: T-Junction
Location: Junction of Road 1 and Road 2 HILLVIEW AVENUE BUKIT BATOK EAST AVENUE 2 traffic junction				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHD5211J	Car					0
SLL8084A	Car					0



SINGAPORE
POLICE FORCE



T/20200112/2015

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

2 of 3

Report No. T/20200112/2015

CONTINUATION OF REPORT

Brief Details.

On 11/01/2020 at about 1940hrs I was driving my Transcab taxi bearing registration number SHD5211J along Hillview Avenue towards Bukit Batok Street 25 on the most right lane and nothing was amiss.

On the same day at about 1945hrs upon reaching the traffic junction Hillview Avenue and Bukit Batok East Avenue 2 I wanted to make a right turn and it was then I noticed that the traffic light was indicating red. Hence I made a stop.

Not long after I felt a loud impact from the rear portion of my vehicle. I went down to make a check. It was then I discovered that the vehicle behind me bearing registration number SLL8084A had collided onto my vehicle rear portion.

The driver was one namely Mr Lim (Unknown details) who claimed that I had reversed my vehicle resulting to the collision.

No one were injured at that point of time. There is no Traffic Police activated. Both drivers then agreed to pursue personal insurance claim.

I wish to state that both vehicle suffered minor damages and are still able to move off. There is an in-built CCTV installed in my vehicle.

Soon both parties then left scene.

On the same day at 2125hrs, I then went to Singapore General Hospital as my chest were in pain. I was then given 4 days medical leave.

As such I am making this report for Traffic police assistance.

**SINGAPORE
POLICE FORCE**

T/20200112/2015

3 of 3

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20200112/2015

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 3 SYED NAFIS BIN SYED HUSSAIN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

SSI 2 YEO GEAK ENG CECILIA

Contact No.: 65476404

Authentication Stamp

NP158

Signature Of Informant:

Date/Time:

12/01/2020 04:09

Classification Of Case:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5211J**AAD2001-105***Not Authorised
Respray B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 5211J

JTDKB3FU203078602

TOYOTA

PRIUS

11.1.2020

TOKIO MARINE

19/12/2018

PART

- 1 REAR BUMPER
- 1 REAR BUMPER RE-INFORCEMENT
- 1 REAR BUMPER TOWING COVER
- 1 GUARD, REAR BUMPER, CENTER
- 1 REAR BUMPER SIDE RETAINER LH
- 1 REAR BUMPER SIDE RETAINER RH
- 1 REAR TAILGATE
- 1 REAR TAILGATE OUTER GARNISH
- 1 REAR TAILGATE WEATHERSTRIP
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 TAILLAMP LOWER RH
- 1 TAILLAMP UPPER RH
- 1 REAR BUMPER SIDE RH
- 1 REAR BUMPER SIDE LH
- 1 TAILLAMP LOWER LH
- 1 TAILLAMP UPPER LH
- 1 COVER, DECK TRIM, REAR
- 1 COVER, FLOOR UNDER, NO 1
- 1 COVER, FLOOR UNDER, NO 2
- 1 COVER, REAR FLOOR

LIST

\$	<i>Od / An</i>	442.60
\$	<i>R Lm</i>	332.70
\$	<i>Sm</i>	15.40
\$	<i>Sm</i>	576.30
\$	<i>Sm</i>	116.50
\$	<i>Sm</i>	117.70
\$	<i>R</i>	1,147.80
\$	<i>Sm</i>	925.60
\$	<i>Sm</i>	372.30
\$	<i>R</i>	650.30
\$	<i>Sm</i>	502.00
\$	<i>Sm</i>	451.80
\$	<i>Sm</i>	123.70
\$	<i>Sm</i>	123.70
\$	<i>Sm</i>	502.00
\$	<i>Sm</i>	443.30
\$	<i>Sm</i>	126.70
\$	<i>Sm</i>	175.10
\$	<i>Sm</i>	241.90
\$	<i>Sm</i>	229.90

TOTAL	\$	7,617.30
25%	\$	1,904.33
	\$	5,712.98

Special Nett

Trans-cab Auto Services Pte Ltd**AAD2001-105**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5211J

1SET	PARKING AID	\$	700.00	} <i>sum x</i>
1SET	REAR BUMPER CLIP	\$	66.00	
2	REAR WINDSCREEN SEALANT	\$	80.00	
1	WINDSCREEN MOULDING	\$	100.00	
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
1	REAR TAILGATE TOYOTA LOGO	\$	47.00	
1	REAR TAILGATE WORDING 'PRIUS'	\$	52.90	
1	REAR TAILGATE WORDING 'HYBRID'	\$	53.50	
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	80.00	
1	REAR TAILGATE STICKER '6555-3333'	\$	80.00	
1	REAR BUMPER PROTECTOR	\$	100.00	
1	REAR WHEEL RIM	\$	1,879.40	
1	REAR TYRE 195/65/15	\$	350.00	
1	REAR WHEEL RIM COVER	\$	211.50	
1	REAR RH BUMPER RETAINER CLIP	\$	25.00	
1	REAR LH BUMPER RETAINER CLIP	\$	25.00	
TOTAL		\$	3,950.30	
TOTAL PARTS		\$	9,663.28	

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>~</i> 170.00	<i>X</i>
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>~</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>~</i> 170.00	<i>X</i>
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>~</i> 170.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	<i>220</i>

Trans-cab Auto Services Pte Ltd**AAD2001-105**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5211J

To check steering geometry and computer wheel alignment	\$	<i>na</i>	220.00	<i>X</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>4</i>	170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$		170.00	<i>50%</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i>	170.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>4</i>	380.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>4</i>	380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	<i>4</i>	170.00	<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		6,000.00	<i>150%</i>
To supply and re-do rear end panel insulation padding.	\$	<i>4</i>	380.00	<i>X</i>
Towing Fees	\$	<i>B.I/I</i>	150.00	<i>7</i>
TOTAL	\$		14,870.00	
Over All Total	\$		24,533.28	

(PART-BY-PART) Repair Days**~~20~~ Days***2 day*

LKH Auto Consultants hereby notify the Repairer of the following:

- To re-survey before/after spray painting
- To display damaged part(s) during re-survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary report(s) must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI20000908/KTF3N2
 Date: 14/02/2020

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MK000641
Claimant Vehicle No :	SHD5211J	Insured Vehicle No :	SLL8084A
Date of Loss:	11/01/2020	Nature of Claim:	TP
		Claim No:	M2000410

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5211J	Engine No:	2ZR2B92968
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU203078602
Reg. Date:	19/12/2018 (Man. Year: 2018)	Odometer:	85804 km
Colour:	Metallic White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,663.27	331.95	9,331.32	96.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,870.00	420.00	14,450.00	97.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,533.27	751.95	23,781.32	96.93
+ GST 7.00/7.00% (S\$)	1,717.33	52.64	1,664.69	96.93
Nett Amount (S\$)	26,250.60	804.59	25,446.01	96.93

INSPECTION

Date of Assignment:	16/01/2020		
Date Inspected:	14/01/2020	Inspected At:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Feb 2020)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD5211J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Dented/Buckled	442.60 FL	-	*442.60 FL
2	1		*REAR BUMPER RE-INFORCEMENT	Repair	332.70 FL	-	*- FL
3	1		*REAR BUMPER TOWING COVER	Serviceable	15.40 FL	-	*- FL
4	1		*GUARD,REAR BUMPER,CENTER	Serviceable	576.30 FL	-	*- FL
5	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	116.50 FL	-	*- FL
6	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	117.70 FL	-	*- FL
7	1		*REAR TAILGATE	Repair	1,147.80 FL	-	*- FL
8	1		*REAR TAILGATE OUTER GARNISH	Serviceable	925.60 FL	-	*- FL
9	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	372.30 FL	-	*- FL
10	1		*PANEL SUB-ASSY,BODY LOWER BACK	Repair	650.30 FL	-	*- FL
11	1		*TAILLAMP LOWER RH	Serviceable	502.00 FL	-	*- FL
12	1		*TAILLAMP UPPER RH	Serviceable	451.80 FL	-	*- FL
13	1		*REAR BUMPER SIDE RH	Serviceable	123.70 FL	-	*- FL
14	1		*REAR BUMPER SIDE LH	Serviceable	123.70 FL	-	*- FL
15	1		*TAILLAMP LOWER LH	Serviceable	502.00 FL	-	*- FL
16	1		*TAILLAMP UPPER LH	Serviceable	443.30 FL	-	*- FL
17	1		*COVER,DECK TRIM,REAR	Serviceable	126.70 FL	-	*- FL
18	1		*COVER,FLOOR UNDER,NO 1	Serviceable	175.10 FL	-	*- FL
19	1		*COVER,FLOOR UNDER,NO 2	Serviceable	241.90 FL	-	*- FL
20	1		*COVER,REAR FLOOR	Serviceable	229.90 FL	-	*- FL
21	1		*SET PARKING AID	Serviceable	700.00 FS	-	*- FS
22	1		*SET REAR BUMPER CLIP	Serviceable	66.00 FS	-	*- FS
23	2		*REAR WINDSCREEN SEALANT	Serviceable	80.00 FS	-	*- FS
24	1		*WINDSCREEN MOULDING	Serviceable	100.00 FS	-	*- FS
25	1		*REAR WINDSCREEN INNER SPONGE SEAL	Serviceable	100.00 FS	-	*- FS
26	1		*REAR TAILGATE TOYOTA LOGO	Serviceable	47.00 FS	-	*- FS
27	1		*REAR TAILGATE WORDING PRIUS	Serviceable	52.90 FS	-	*- FS
28	1		*REAR TAILGATE WORDING HYBRID	Serviceable	53.50 FS	-	*- FS
29	1		*REAR TAILGATE STICKER TRANS-CAB	Serviceable	80.00 FS	-	*- FS
30	1		*REAR TAILGATE STICKER 6555-3333	Serviceable	80.00 FS	-	*- FS
31	1		*REAR BUMPER PROTECTOR	Serviceable	100.00 FS	-	*- FS
32	1		*REAR WHEEL RIM	Serviceable	1,879.40 FS	-	*- FS
33	1		*REAR TYRE 195/65/15	Serviceable	350.00 FS	-	*- FS
34	1		*REAR WHEEL RIM COVER	Serviceable	211.50 FS	-	*- FS
35	1		*REAR RH BUMPER RETAINER CLIP	Serviceable	25.00 FS	-	*- FS
36	1		*REAR LH BUMPER RETAINER CLIP	Serviceable	25.00 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,567.60	442.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,904.33	110.65
Total Parts (\$\$)	9,663.27	331.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
2	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
3	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
4	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	220.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
8	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
9	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
10	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
11	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00
12	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
13	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	6,000.00	150.00
14	TO SUPPLY AND RE-DO REAR END PANEL INSULATION PADDING	New	380.00	0.00
15	TOWING FEES	New	150.00	0.00
Gross Labour Cost (S\$)			14,870.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >