



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF20000912/Gvf3e2

ACCIDENT CLAIMS SECTION (SPORE POLICE
FORCE) POLICE LOGISTICS BASE (PLB) 1
HEMMANT ROAD SINGAPORE 438675

Date : 04-03-2020



ATTN : HAFIZUL FARHAN RAHMAT

Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 1022C	Veh. Inspected	SJH 1419J
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2019/121	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN RAHMAT	Assign Date	15/01/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALLION 1.5	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	NZT2603030248	Colour	WHITE
Odometer	130456	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	MICHELIN	6 mm
L/H Front Tyre	195/60 R15	MICHELIN	6 mm
R/H Rear Tyre	195/60 R15	MICHELIN	6 mm
L/H Rear Tyre	195/60 R15	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/12/2019	Inspection Date	15/01/2020
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------