

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Vehicle No.: GBH 7090C

Model: Toyota Dyna

Not Allowed
Hhlc
2/5 @ 3500
Hdy.

QTY

DESCRIPTION

AMT S\$

<u>List Items</u>			
1	Rear tailgate	100/serf	\$ 1,465.60 ✓
1	Rear tailgate 'TOYOTA' sticker	net	\$ 290.00 ✓
1	Rear tailgate lower panel	serf	\$ 878.50 ✓
2	Rear tailgate lower stopper rubbers	17	\$ 145.20 X
2	Rear tailgate lower stopper brackets	17	\$ 213.00 X
2	Rear taillamps	C12	\$ 679.40 ✓
2	Rear taillamp panels	12	\$ 599.00 X
1	Rear number plate panel	serf	\$ 98.50 ✓
1	Rear number plate lamp	17	\$ 89.70 X
1	Rear spare tyre carrier	17	\$ 289.70 X
1	Rear spare tyre carrier support	17	\$ 625.00 X
1	Rear exhaust pipe	12	\$ 852.60 X
1	Rear exhaust mounting	17	\$ 48.90 X
			\$ 6,275.10
Discount 25%			\$ 1,568.78
			\$ 4,706.33

3412

Special Nett Items

1	Rear tailgate "13PAX" sticker	net	\$ 25.00 10
1	Rear tailgate "70KM/H" sticker	net	\$ 25.00 10
1	Rear step bar	serf	\$ 250.00 ✓
1	Rear number plate	serf	\$ 50.00 15
1 set	Rear reverse sensor	short	\$ 350.00 200
			\$ 700.00

5.2

S/N.

Labour Charges

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00 20
2	To remove and refit inner garnishes.	\$ 17	150.00 X
3	To remove, refit and replace exhaust silencer and mountings.	\$ 17	150.00 X
4	To apply tuff kote.	\$	180.00 50
5	Panel beating.	\$	1,500.00 680
6	To respray painting on the affected areas.	\$	1,400.00 600
		\$	3,460.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice basis"
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Grand Total : \$ 8,866.33

4394