

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ After-Paint: _____
 Contacts : _____

Vehicle Nos : **SJH 50 U**
 Model : **MERCEDES CLA180**
 Year : _____
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	HEADLAMP LH	1	\$ 2,985.20	\$ 1,567.88	2,985.20 CUT
2	HEADLAMP BALLAST LH	1	\$ 475.30	\$ 475.30	ND
3	HEADLAMP LOWER BRACKET LH	1	\$ 423.50	\$ 423.50	NN
4	FRONT BUMPER	1	\$ 1,958.60	\$ 1,554.00	1,958.60 CUT
5	FRONT BUMPER RETAINER	2	\$ 248.60	\$ 156.00	497.20 NEI
6	FRONT BUMPER TOW CAVER	1	\$ 109.20	\$ 109.20	NN
7	FRONT BUMPER FOG LAMP GARNISH LH	1	\$ 385.20	\$ 385.20	NN
8	FRONT FENDER LH	1	\$ 1,028.60	\$ 996.50	1,028.60 CUT
9	FRONT FENDER INNER COWLING LH	1	\$ 472.30	\$ 184.00	472.30 DL
10	FRONT FENDER INNER SPONGE (Bumper)	1	\$ 286.90	\$ 140.00	286.90 BR
11	FRONT DOOR LH	1	\$ 2,458.60	\$ 2150.00	2,458.60 CUT
12	SIDE MIRROR ASSY LH	1	\$ 1,253.20	\$ 986.00	1,253.20 CUT
13	SIDE MIRROR CAVER LH	1	\$ 385.20	\$ 385.20	NN
14	FRONT DOOR INNER LOCK LH	1	\$ 685.30	\$ 685.30	NN
15	FRONT DOOR STRIKER LH	1	\$ 142.50	\$ 142.50	NN
16	FRONT DOOR WEATHER STRIP LH	1	\$ 896.40	\$ 896.40	NN
17	FRONT DOOR CHANNEL LH	1	\$ 476.30	\$ 476.30	NN
18	FRONT DOOR REGULATOR ASSY LH	1	\$ 1,863.20	\$ 1,863.20	NN
19	FRONT DOOR INNER TRIM BOARD LH	1	\$ 685.70	\$ 685.70	NN
20	FRONT LOWER SKIRT LH	1	\$ 853.20	\$ 853.20	NN
21	FRONT ABSORBER LH	1	\$ 1,852.80	\$ 1,852.80	NN
22	FRONT LOWER ARM LH	1	\$ 547.30	\$ 392.00	547.30 DD
23	FRONT KNUCKLE ARM LH	1	\$ 783.60	\$ 783.60	NN
24	FRONT WHEEL BEARING LH	1	\$ 510.60	\$ 378.00	510.60 JK

Parts Sub Total : \$ 8506.38 22,015.90

Discount 10% : \$ 850.64 2,201.59

PARTS TOTAL : \$ 7655.74 19,814.31

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	SUNDRIES	1	\$ 80.00	\$ 80.00	NN
2	FRONT BUMPER CLIPS	1	\$ 80.00	\$ 30.00	80.00
3	FRONT FENDER SEALANT	1	\$ 100.00	\$ 30.00	100.00
4	FRONT FENDER INNER COWLING FRONT CLIPS	1	\$ 80.00	\$ 30.00	80.00
5	FRONT FENDER INNER COWLING REAR CLIPS	1	\$ 80.00	\$ 80.00	NN
6	FRONT DOOR SEALANT	1	\$ 100.00	\$ 30.00	100.00
7	FRONT DOOR INNER TRIM BOARD CLIPS	1	\$ 80.00	\$ 30.00	80.00
8	FRONT CHANNEL SEAL	1	\$ 80.00	\$ 80.00	NN
9	SIDE MIRROR SEAL	1	\$ 60.00	\$ 60.00	NN
10	FRONT SPORT RIM New	1	\$ 980.00	\$ 700.00	980.00 NEI
11	FRONT TYRE	1	\$ 550.00	\$ 550.00	NN
12	FRONT BUMPER SENSOR 2	2	\$ 380.00	\$ 400.00	1,520.00

SPECIAL NETT TOTAL : \$ 1,250.00 3,790.00

Nos.	LABOUR	S\$	
1	R&R FRONT DOOR COMPONENT	\$ 80.00	200.00
2	R&R FRONT BUMPER SENSOR	\$ 80.00	200.00
3	R&R UNDERCARRIAGE	\$ 200.00	300.00
4	R&R UPHOLSTERY	\$	150.00
5	R&R FRONT TYRE & BALANCING	\$ 80.00	150.00
6	CONDUCT WHEEL ALIGNMENT	\$ 60.00	150.00
7	PANEL BEATING	\$ 600.00	1,400.00
8	RUST PROOFING	\$ 60.00	150.00
9	SPRAY PAINTING	\$ 800.00	1,400.00
10	CHECK WIRING	\$ 50.00	200.00
11	TO RESET AND REPROGRAMME FAULT CODE	\$ 120.00	300.00
LABOUR TOTAL :		\$ 2130.00	4,600.00

Survey 15/1/2020
1600 hrs
Trim in
Lump sum repair

Resurvey 16/1/2020
Trim
1630 hrs
Repair days 7

PARTS TOTAL : \$ 7655.74 19,814.31
SPECIAL NETT TOTAL : \$ 1250.00 3,790.00
LABOUR TOTAL : \$ 2130.00 4,600.00
GRAND TOTAL : \$ 11,035.74 28,204.31
@ 20% 2207.15
8828.59

L/S 8,800/2

Trim 20/1/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: