

ASS. REC. BY:

REF: CS/GAI20000925/Uvd3

Special Instruction:

Surveyor: MARCUS

ASSIGNMENT (Office)

From (Person): Sheny wong

of GAI

Date/Time: 14/01/2020 @ 4:15pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: JHL 4309

Insured: SFQ 7021H

at Workshop m/s: Fastech Auto

Tel: 6746 5405

of 1 Kaki Bukit Avenue 6 # 01-46/48 Autobay

Policy No:

Claim No: CLMOMVP00000T051

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 13/01/2020

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time: 9:23am @ 15/1/2020

Person Contacted:

Lina

Vehicle IN OUT

Date/Time	Action/Instruction	Completed
	JHL 4309 -X	<input checked="" type="checkbox"/>
	SFQ 7021H -X	<input type="checkbox"/>
20/1/2020	Email preli revised to GAI	<input type="checkbox"/>

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **JHL 4309**
 at Workshop m/s **R.**
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: **RM23**
 IDAG Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: **4** days Res.: Yes or No
 Lum Sum: **2** % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **JHL 4309** Yr Regn: **9 04**
 Type: **CA1** / M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or **CA1**
 Make: **Hyundai corallo AHIS c.c 1598**
 Colour: **Silver** A/C: Insured / Std / NI / NA
 Sp. Reading: **172420** TiRadio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **PN1532EC 102900524**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **Good** / Jammed / Leaked / Burnt or
 Brake: **Good** / Jammed / Leaked / Burnt or
 Modl: **NR / SRim / STD A/Rim** or
 Tyre Size: F: **195/60R15**
 R: _____
 BS: **DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /**
 TOYO / YOKO or

Front **5** mm Rear **5** mm
 R/Bal. **5** mm R/Bal. **5** mm
 L/Bal. **5** mm L/Bal. **5** mm
 D.O.A. **13/1/20** D.O.I. **15/1/20**

Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
20/1/20 1/5 @ 4000 confirmed with Alan (Red 9751.86, 719)

RECEIVED 20 JAN 2020

Date/Time: File Pass to? : Prel. Report
 : Final Report

Days Of Repair: **4**
 Resurvey No. of Trip: **1**

Survey Fee:	350
Transportation:	
Photos:	
Others:	
TOTAL:	

2) **20/1 - typist**

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Report Format: **TP**

Lump Sum / I.B.I.: (\$ **4000/2**)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 20 January 2020 9:15 AM
To: 'Motor Claims'; SUR
Cc: 'Ng, Sharon'
Subject: RE: Our Ref:CLMOMVP000001051, REQUEST FOR PRE-REPAIR INSPECTION FOR JHL 4309 DOA: 13.01.2020
Attachments: JHL 4309 PRELI REVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle JHL 4309
Date of survey: 15/1/2020
Number of days (estimated) : 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Wednesday, 15 January 2020 9:26 AM
To: 'Motor Claims' <motorclaims@sg.gaig.com>; assignments <assignments@lkkauto.com>
Cc: 'Ng, Sharon' <sharon.ng@sg.gaig.com>; SUR <sur@lkkauto.com>
Subject: RE: Our Ref:CLMOMVP000001051, REQUEST FOR PRE-REPAIR INSPECTION FOR JHL 4309 DOA: 13.01.2020

Dear Sir/Mdm,

Thank you for the assignment.

Wishing you a Happy and prosperous Lunar New Year



Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Motor Claims [mailto:motorclaims@sg.gaig.com]
Sent: Tuesday, 14 January 2020 4:15 PM
To: shiyong.ong@fastechauto.com.sg; Ong Shiyong <shiyong.ong@fastechauto.com.sg>; admin-d@lkkauto.com; sur@lkkauto.com
Cc: Jason@fastechauto.com.sg; Lina.pang@fastechauto.com.sg; Ng, Sharon <sharon.ng@sg.gaig.com>
Subject: FW: Our Ref:CLMOMVP000001051, REQUEST FOR PRE-REPAIR INSPECTION FOR JHL 4309 DOA: 13.01.2020

Without Prejudice

Hi Shi Ying,

Noted on the request. We will survey on a without prejudice basis.

Dear LKK,

Please accept assignment for TP survey.

Thank you.



Regards

Shery Wong, Executive, Claims | P. +65 68046077 | F. +65 62353354 | shery.wong@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



A+ (Superior)
Affirmed August 17, 2018

Moody's
A1 (Good)
Published December 2018

Standard & Poor's
A+ (Strong)
Affirmed February 23, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Ong Shiyong <shiyong.ong@fastechauto.com.sg>
Sent: 14 January 2020 4:09 PM
To: Motor Claims <motorclaims@sg.gaig.com>
Cc: Jason <Jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>; Ng, Sharon <sharon.ng@sg.gaig.com>
Subject: [External] RE: Our Ref:CLMOMVP000001051, REQUEST FOR PRE-REPAIR INSPECTION FOR JHL 4309 DOA: 13.01.2020

Without Prejudice

Dear Shery,

Please arrange (LKK Auto Consultants) to conduct the pre- repair survey.

Thank you.

Best Regards,
Shiyong
Fastech Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-46/48/50
Autobay Singapore 417883
Tel: 6746 5405
Fax: 6745 8520

From: Motor Claims [<mailto:motorclaims@sg.gaig.com>]
Sent: Tuesday, January 14, 2020 3:07 PM
To: Ong Shiyong <shiyong.ong@fastechauto.com.sg>
Cc: Jason <Jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>; Ng, Sharon <sharon.ng@sg.gaig.com>
Subject: Our Ref:CLMOMVP000001051, REQUEST FOR PRE-REPAIR INSPECTION FOR JHL 4309
DOA: 13.01.2020

Without Prejudice

Dear Sirs,

Our client has not reported accident. Can we have a sketch plan or statement to understand the circumstances of the accident?

We append the following list of our panel surveyors:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. A-PAC Adjusters & Surveyors Pte. Ltd.
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants

Kindly let us know which SJE is selected and furnish the estimates for the survey to be carried out.



Regards

Shery Wong, Executive, Claims | P. +65 68046077 | F. +65 62353354 | shery.wong@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



A+ (Superior)
Affirmed August 17, 2018

Moody's
A1 (Good)
Published December 2018

Standard & Poor's
A+ (Strong)
Affirmed February 23, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Ong Shiyong <shiyong.ong@fastechauto.com.sg>

Sent: 14 January 2020 12:16 PM

To: Motor Claims <motorclaims@sg.gaig.com>

Cc: Jason <Jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>

Subject: [External] REQUEST FOR PRE-REPAIR INSPECTION FOR JHL 4309 DOA: 13.01.2020

Without Prejudice

Dear Sir/Madam

Your insured's vehicle: SFQ 7021H.

Date of accident: 13/01/2020

Please arrange Pre-repair Inspection for my client's vehicle no: JHL 4309.

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, please provide a list of at least 10 motor surveyors within 2 days of the notice.

Thank you.

Best Regards,
Shiyong
Fastech Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-46/48/50
Autobay Singapore 417883
Tel: 6746 5405
Fax: 6745 8520



Auto
Consultants
Pte Ltd

Company Registration No. 19960711

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564

Your Ref: CLMOMVP000001051

Our Ref: CS/GAI20000925/Uvd3

Date: 20/1/2020

The Motor Claims Department
M/s: GREAT AMERICAN INSURANCE COMPANY

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. JHL 4309


We thank you for your instruction on 14/1/2020

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15/1/2020 at the premises of M/s FASTECH AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$13,751.86
Revised Estimate Amount	: S\$4,000.00 (LUMP SUM)
"Check" Items Amount	: S\$
Total	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Nivitha (LKK Auto)

From: Motor Claims <motorclaims@sg.gaig.com>
Sent: Tuesday, 14 January 2020 4:15 PM
To: shiying.ong@fastechauto.com.sg; Ong Shiying; admin-d@lkkauto.com; sur@lkkauto.com
Cc: Jason@fastechauto.com.sg; Lina.pang@fastechauto.com.sg; Ng, Sharon
Subject: FW: Our Ref:CLMOMVP000001051, REQUEST FOR PRE-REPAIR INSPECTION FOR JHL 4309 DOA: 13.01.2020

Without Prejudice

Hi Shi Ying,

Noted on the request. We will survey on a without prejudice basis.

Dear LKK,

Please accept assignment for TP survey.

Thank you.



Regards

Shery Wong, Executive, Claims | P. +65 68046077 | F. +65 62353354 | shery.wong@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



A+ (Superior)
Affirmed August 17, 2018

Moody's
A1 (Good)
Published December 2018

Standard & Poor's
A+ (Strong)
Affirmed February 23, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Ong Shiying <shiying.ong@fastechauto.com.sg>
Sent: 14 January 2020 4:09 PM
To: Motor Claims <motorclaims@sg.gaig.com>
Cc: Jason <Jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>; Ng, Sharon

<sharon.ng@sg.gaig.com>

Subject: [External] RE: Our Ref:CLMOMVP000001051, REQUEST FOR PRE-REPAIR INSPECTION FOR JHL 4309 DOA: 13.01.2020

Without Prejudice

Dear Shery,

Please arrange (LKK Auto Consultants) to conduct the pre- repair survey.

Thank you.

Best Regards,

Shiyong

Fastech Auto Pte Ltd

1 Kaki Bukit Avenue 6 #01-46/48/50

Autobay Singapore 417883

Tel: 6746 5405

Fax: 6745 8520

From: Motor Claims [<mailto:motorclaims@sg.gaig.com>]

Sent: Tuesday, January 14, 2020 3:07 PM

To: Ong Shiyong <shiyong.ong@fastechauto.com.sg>

Cc: Jason <Jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>; Ng, Sharon <sharon.ng@sg.gaig.com>

Subject: Our Ref:CLMOMVP000001051, REQUEST FOR PRE-REPAIR INSPECTION FOR JHL 4309 DOA: 13.01.2020

Without Prejudice

Dear Sirs,

Our client has not reported accident. Can we have a sketch plan or statement to understand the circumstances of the accident?

We append the following list of our panel surveyors:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. A-PAC Adjusters & Surveyors Pte. Ltd.
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants

Kindly let us know which SJE is selected and furnish the estimates for the survey to be carried out.



Regards

Shery Wong, Executive, Claims | P. +65 68046077 | F. +65 62353354 | shery.wong@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



A+ (Superior)
Affirmed August 17, 2018

Moody's
A1 (Good)
Published December 2018

Standard & Poor's
A+ (Strong)
Affirmed February 23, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Ong Shiyong <shiyong.ong@fastechauto.com.sg>

Sent: 14 January 2020 12:16 PM

To: Motor Claims <motorclaims@sg.gaig.com>

Cc: Jason <Jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>

Subject: [External] REQUEST FOR PRE-REPAIR INSPECTION FOR JHL 4309 DOA: 13.01.2020

Without Prejudice

Dear Sir/Madam

Your insured's vehicle: SFQ 7021H.

Date of accident: 13/01/2020

Please arrange Pre-repair Inspection for my client's vehicle no: JHL 4309.

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS

AMENDMENT NO. 1 OF 2016 paragraph 2.3, please provide a list of at least 10 motor surveyors within 2 days of the notice.

Thank you.

Best Regards,

Shiyong

Fastech Auto Pte Ltd

1 Kaki Bukit Avenue 6 #01-46/48/50

Autobay Singapore 417883

Tel: 6746 5405

Fax: 6745 8520

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



CERTIFICATE OF INSURANCE

Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia)
Motor Vehicles (Third Party Risks & Compensation) Act (Cap 189) Republic of Singapore
Motor Vehicles (Third Party Risks& Compensation) Rules 1960 (Republic of Singapore)
Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam

MOTOR - PRIVATE CAR	Comprehensive	RM	23,000.00
MX1 – Private Car - Private Use	Excess All Claims	RM	0.00
Index Mark and Vehicle Registration No.		Policy No.	
JHL4309		CVP-V6163240-J1	
Name of Insured			
KHOO YEE CHONG			
Effective Date of the Commencement of Insurance for the purpose of the Regulations, Ordinance or Enactment		Date of Expiry of Insurance	
10/06/2019		09/06/2020	
Persons or Classes of Persons entitled to drive (a) The Policyholder (b) Any other person who is driving on the Policyholder's order or with his permission. Limitations as to use Use only for social, domestic and pleasure purposes and for the Policyholder's business. The Policyholder does not cover use for hire or reward, racing, pace-making, reliability trial, speedtesting the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade. Limitation rendered inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore or Section 7 of the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam are not included under this heading.			
I / We certify that the Policy to which this Certificate relates is issued in accordance with the provision of Part IV of the Road Transport Act, 1987 (Malaysia), Motor Vehicles (Third Party Risks & Compensation) Act (Cap 189) Republic of Singapore and the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam.			
For and behalf of Etiqua General Insurance Berhad			

Policyholder KHOO YEE CHONG NO 8, JALAN AUSTIN PERDANA 3/6 TAMAN AUSTIN PERDANA JOHOR BAHRU 81100 JOHOR	Policy No : CVP-V6163240-J1 Account No. : V0024092 Agent Name : B.T.YAP AGENCY Product Type : Private Car - Private Use Period of Insurance from 10/06/2019 To 09/06/2020 (both Dates Inclusive). Any subsequent period for which the Insured shall pay and the Company shall agree to accept a renewal premium.
--	---

NRIC No : 750126-10-5581 Business/Occupation : OTHERS Vehicle Information JPJ Document No : Vehicle Reg No : JHL4309 Make : TOYOTA Model : TOYOTA COROLLA ALTIS E Engine No : 3ZZ4309728 Chassis No : PN153ZEC102900524 Year of Manufacture : 2004 Cubic Capacity : 1598 Seating Capacity : 5 Financial Interest : NIL Business Reg No : Other ID No : Log Book No : NIL Cover Type : Comprehensive Vehicle Type : Private Car License Type : Normal Vehicle Use For : Private Use	Vehicle Estimated Value RM 23000.00 Gross Premium RM 947.25 Less: No Claim Discount 25.00% RM 236.81 Legal liability to passengers (driver.s liability) RM 33.75 Legal liability to passenger for act of negligence RM 7.50 Add : Service Tax 6.00 % RM 751.69 Stamp Duty RM 45.10 Stamp Duty RM 10.00 TOTAL AMOUNT DUE RM 806.79 Excess All Claims RM 0.00
Authorised Driver 1 KHOO YEE CHONG 750126-10-5581 2 ANY AUTHORISED DRIVER -	
Subject to the following warranties, endorsements and clauses incorporated herein and forming part of the Policy.	
Clause Code Clause Name B001 EXCESS ALL CLAIMS M003 SANCTION LIMITATION AND EXCLUSION CLAUSE N002 INFORMATION ON ePOLICY M004 IMPORTANT NOTICE B072 LEGAL LIABILITY OF PASSENGERS FOR ACTS OF NEGLIGENCE M007 MINIMUM PREMIUM B113 MARKET VALUATION SYSTEM	

MEMO**INFORMATION ON ePOLICY**

In line with our Group's strategy to promote usage of technology and to help preserve the country's natural resources, we no longer print the full policy/certificate wording. You may view and print the above policy/certificate wording at our website www.etiqa.com.my. Printout may also be obtained from our offices nationwide.

SANCTION LIMITATION AND EXCLUSION CLAUSE

This insurance policy shall not provide cover and the Company shall not be liable to pay any claim or provide any benefit hereunder to the extent that the provision of such cover, payment of such claim, or provision of such benefit would expose the Company to any Sanction, prohibition or restriction under the CISAD Act or United Nations resolutions or trade or economic sanctions, laws or regulations of the European Union, United Kingdom.

Wef 1 Jan 2014, prohibition or restriction under the CISAD Act is replaced by laws or regulations of United States of America


MINIMUM PREMIUM

The Policy is subject to RM50.00 minimum premium



Visit www.etiqa.com.my or our nearest branch to obtain the full policy wordings.
Help preserve the country's natural resources.





SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

KYRASY68

No. Pendaftaran : JHL4309
No. ID : 750126105581
Nama Pemunya Berdaftar : KHOO YEE CHONG
Alamat : NO 143 LORONG 4
42600 JENJAROM SELANGOR

No. Chasis/No. Enjin : PN153ZEC102900524 / 3ZZ-4309728
Buatan>Nama Model : TOYOTA / TOYOTA COROLLA ALTIS 1.6E (A)
Keupayaan Enjin : 1598
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Kelas Kegunaan : PERSENDIRIAN-MOTOKAR INDIVIDU
Jenis Badan/Tahun Dibuat : MOTOKAR / 2004
Tarikh Pendaftaran : 19/04/2004
B. D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -



**SINGAPORE
POLICE FORCE**



T/20200113/2190

2 of 3

Report No. T/20200113/2190

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	KHOO YEE CHONG	ID No.	G7398179X
Related Vehicle	JHL4309 (Car)	Contact No.	91884057
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3C Date of Expiry: NIL
Date Treatment	13/01/2020	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	Goh	ID No.	NIL
Related Vehicle	SFQ7021H (Car)	Contact No.	98411343
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 13th January 2020 at about 5.30 pm, I was driving my vehicle JHL4309 along KJE towards BKE on the extreme right lane. As the traffic was very heavy at the said time, my vehicle was stationary. Out of sudden, another vehicle bearing registration number SFQ7021H had hit me directly from the back. I then came out of my vehicle and spotted another vehicle bearing registration number SLC7937T had hit the back vehicle of SFQ7021H. There was no ambulance or police attended at the scene. There was slight damaged to all the vehicles.

As I continued my drive back, I felt a pain at the back of the neck, lower back and shoulder area. I then proceeded to Mount Alvernia Hospital where I was granted Outpatient Sick leave from the 14 Jan 2020 to the 16 Jan 2020. The medical certificate no is M20000034349. That's all.



Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

Report No. T/20200113/2190

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / SI RANJIT SINGH / S/O SWARANT SINGH
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / AEIT / SSI 2 JUREMAH BINTE AHMAD Contact No.: 65476219

Signature Of Informant: 
Date/Time: 13/01/2020 21:48
Classification Of Case:

Authentication Stamp
NP168

	SINGAPORE POLICE FORCE		SN 170
SIGNATURE			

FASTECH AUTO PTE LTD
 BLK 1 KAKI BIKIT AVE 6
 #01-46,48,50 SPORE 47883

Not Authorized
 15/11/20
 1/5 @ 4000 /
 4 day

JHL 4309

1PC	BOOTLID	R	\$855.10	X
1PC	BOOTLID REAR LOGO	11	\$48.00	X
1PC	BOOTLID 1.6 EMBLEM	NF	\$42.00	X
1PC	BOOTLID COROLLA EMBLEM	NF	\$45.00	X
1PC	BOOTLID ALTIS EMBLEM	NF	\$43.00	X
1PC	BOOTLID VVTI EMBLEM	NF	\$42.00	X
1PC	BOOTLID OUTER GARNISH	11	\$266.10	X
2PCS	BOOTLID REFLECTORS @\$184.10	11	\$368.20	X
1PC	BOOTLID INNER LOCK	1w1	\$109.90	/
1PC	BOOTLID WEATHERSTRIP	10rn	\$195.30	/
1PC	REAR BUMPER	Del/10rn	\$485.10	/
2PCS	REAR BUMPER BRACKETS @\$66.50	o/s 10rn	\$133.00	1PC
2PCS	REAR BUMPER SIDE RETAINERS @\$65.10	10rn	\$130.20	/
1SET	REAR BUMPER CLIPS	10rn	\$50.00	/
2PCS	TAILLAMPS @\$340.10	10rn	\$680.20	/
2PCS	TAILLAMP HOUSING PANELS @\$408.00	10rn	\$816.20	/
2PCS	TAILLAMP LOWER APRON PANELS @\$115.00	o/s 10rn	\$230.00	1PC
1PC	REAR END PANEL	Body 10rn	\$580.10	/
1PC	REAR END PANEL GARNISH	10rn	\$288.10	/
1PC	REAR FLOOR PANEL	R	\$980.90	X
1PC	REAR FLOOR PANEL TOP BOARD	10rn	\$285.10	/
2PCS	REAR FENDERS @\$917.40	R	\$1,834.80	X
2PCS	REAR FENDER INNER TRIMS @\$315.10	11	\$630.26	X
1PC	REAR WINDSCREEN MOULDING	11	\$68.10	X
1PC	REAR EXHAUST	R	\$855.20	X
			\$10,061.86	

25%

1SET	REAR BUMPER REVERSE SENSOR	Shubh	\$280.00	200
1PC	REAR LICENCE PLATE	11	\$50.00	X
1PC	REAR WINDSCREEN SEALANT	11	\$50.00	X

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.00	50
TO TRANSFER BOOTLID COMPONENTS	\$80.00	X
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO DISMANTLE & REFIX REAR EXHAUST	\$100.00	60
TO SPRAY RUST PROOFING	\$100.00	60
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,280.00	800
TO PUTTY & SPRAY PAINTING	\$1,500.00	900

TOTAL \$13,751.86

Auto Consultants Finance
 15/11/20
 TOTAL \$13,751.86
 Approved by Receiver

2,3801.7
 25%
 2851.27
 4017



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI20000925/Uvd3s2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 20-01-2020



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFQ 7021H	Veh. Inspected	JHL 4309
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVP000001051	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	14/01/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2004
Chassis No.	PN153ZEC102900524	Colour	SILVER
Odometer	172420	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	BRIDGESTONE	5 mm
L/H Front Tyre	195/60 R15	BRIDGESTONE	5 mm
R/H Rear Tyre	195/60 R15	BRIDGESTONE	5 mm
L/H Rear Tyre	195/60 R15	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/01/2020	Inspection Date	15/01/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JHL 4309

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID	TO REPAIR SEE LABOUR	855.10	-
1	BOOTLID REAR LOGO	NOT NECESSARY	48.00	-
1	BOOTLID 1.6 EMBLEM	NOT FITTED	42.00	-
1	BOOTLID COROLLA EMBLEM	NOT FITTED	45.00	-
1	BOOTLID ALTIS EMBLEM	NOT FITTED	43.00	-
1	BOOTLID VVTI EMBLEM	NOT FITTED	42.00	-
1	BOOTLID OUTER GARNISH	NOT NECESSARY	266.10	-
2	BOOTLID REFLECTORS @ \$184.10	NOT NECESSARY	368.20	-
1	BOOTLID INNER LOCK	TWISTED	109.90	109.90
1	BOOTLID WEATHERSTRIP	TORN	195.30	195.30
1	REAR BUMPER	DEFORMED / TORN	485.10	485.10
2	REAR BUMPER BRACKETS @ \$66.50	O/S DENTED	133.00	66.50
2	REAR BUMPER SIDE RETAINERS @ \$65.10	BENT	130.20	130.20
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	TAILLAMPS @ \$340.10	CRACKED	680.20	680.20
2	TAILLAMP HOUSING PANELS @ \$408.00	DENTED / BENT	816.20	816.20
2	TAILLAMP LOWER APRON PANELS @ \$115.00	O/S BENT	230.00	115.00
1	REAR END PANEL	BADLY DENTED	580.10	580.10
1	REAR END PANEL GARNISH	TORN	288.10	288.10
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	980.90	-
1	REAR FLOOR PANEL TOP BOARD	CRACKED	285.10	285.10
2	REAR FENDERS @ \$917.40	TO REPAIR SEE LABOUR	1,834.80	-
2	REAR FENDER INNER TRIMS @ \$315.10	NOT NECESSARY	630.26	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	68.10	-
1	REAR EXHAUST	TO REPAIR SEE LABOUR	855.20	-
	LESS 25% DISCOUNT		-	-950.43
			10,061.86	2,851.27



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
SPECIAL NETT ITEMS				
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR LICENCE PLATE (SN)	NOT NECESSARY	50.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	50.00	-
			380.00	200.00
LABOUR				
	TO CHECK WIRING.		50.00	20.00
	TO DSIMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO TRANSFER BOOTLID COMPONENTS.	NOT NECESSARY	80.00	-
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST.		100.00	60.00
	TO SPRAY RUST PROOFING.		100.00	60.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF BOOTLID, REAR FLOOR PANEL, REAR FENDERS AND REAR EXHAUST.		1,280.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	900.00
			3,310.00	1,970.00
GRAND TOTAL			13,751.86	5,021.27
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CS/GAI20000925/Uvd3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.