

ISSUES

ASS. REC. NO.

Surveyor: Sun Pin

REP:

CS / AGI20000930 / Qgd302

Model Instruction:

ASSIGNMENT (Office)

From (Person): Ivy Retilla

of

AGI

Date/Time: 15/01/2020 @ 10:47am

Estimated Cost:

Bill to:

OD / IT / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 4626H

Insured:

SKW 1914E

at Workshop m/s

SMRT

Tel:

68662672

of

Go woodlands Ind. park E4

Policy No:

Claim No:

C10005218 / CH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

02/01/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time: 1135am @ 15/1/2020

Person Contacted:

Shanti

Vehicle IN / OUT

Date/Time	Action/Instruction
	<u>Estimated ✓</u>
	<u>SHC 4626H - CS / LCR 17013859 / R / ph 292</u>
	<u>SKW 1914E - X</u>

JOA / 16/07/2020

ASSIGNMENT

78

14AD

•Nivitha (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Wednesday, 15 January 2020 10:47 AM
To: Nivitha (LKK Auto)
Cc: 'SUR'; Justin Wong; Hansel Ang
Subject: FW: TPPD Survey: Claim ref: C10005218/CH || OI- SKW1914E (Black) TP- SHC4626H || Est:0.00 || SMRT Automotive Services
Attachments: OD report.pdf; TP Report.pdf

Hi Team,

TP PRS for SHC4626H please.

Workshop is SMRT Automotive Services Pte Ltd. Vehicle not in Woodlands.

Please refer to the email trail.

Kindly confirm. Thank you.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee,

confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Shanti B Thaiyal Nayagi (Auto Svcs/Claims & IA/Claims & IA/Taxis) <BThaiyalN@smrt.com.sg>

Sent: Tuesday, 14 January 2020 9:57 AM

To: 'claims@budgetdirect.com.sg'

Cc: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>; Kok Tuck Foo (Auto Svcs/ARC/ARC/Taxis) <TuckFoo@smrt.com.sg>; Koo Yew Chung (Auto Svcs/ARC/ARC) <YewChung@smrt.com.sg>; Phua Zhi Yang (Auto Svcs/ARC/AR & SC/Taxis) <ZhiYang.Phua@smrt.com.sg>; Grace Ng Siu Ching (Auto Svcs/ARC/ARC/Taxis) <ngsiuching@smrt.com.sg>; Chin Kim Ming (Auto Svcs/ARC/ARC/Taxis) <kimming.chin@smrt.com.sg>

Subject: RE: SHC4626H - SURVEY (AUTO & GENERAL INSURANCE)

Dear Sir /Mdm

Kindly arrange to survey the vehicle **SHC4626H** within 48 hours according to GIA guide line, involving your insured **SKW1914E**

Vehicle in Woodlands

Regards

Shanti

SMRT Automotive Services PTE LTD

Accident Reporting Center (Claims Dept)

6866 2671/2 | bthaiyaln@smrt.com.sg



This email is sent by Auto & General Insurance (Singapore) Pte. Limited, Auto & General (SEA) Services Pte. Limited, Easy Compare (Thailand) Co., Ltd or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised. If you are not the intended addressee, please immediately notify the sender and then delete the email. Auto & General does not warrant that this email is error or virus free.

This email is sent by Auto & General Insurance (Singapore) Pte. Limited, Auto & General (SEA) Services Pte. Limited, Easy Compare (Thailand) Co., Ltd or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised. If you are not the intended addressee, please immediately notify the sender and then delete the email. Auto & General does not warrant that this email is error or virus free.

This email is sent by Auto & General Insurance (Singapore) Pte. Limited, Auto & General (SEA) Services Pte. Limited, Easy Compare (Thailand) Co., Ltd or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated

author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised. If you are not the intended addressee, please immediately notify the sender and then delete the email. Auto & General does not warrant that this email is error or virus free.

Oi Sun Pin (LKK Auto)

From: Oi Sun Pin (LKK Auto)
Sent: Wednesday, 12 February, 2020 8:49 AM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Subject: RE: SHC4626H

Hi Poh Suan,

Confirm the finalize amount \$1,500. Repair day 3 days under lump sum repair.

Thank you.

Best Regards,
Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [<mailto:YeoPohsuan@smrt.com.sg>]
Sent: Thursday, 30 January, 2020 2:41 PM
To: Oi Sun Pin (LKK Auto)
Cc: SUR; CS A Team; Leong Chee kwong
Subject: SHC4626H

Hi Sun Pin,

Attached herewith the repair estimate of SHC 4626H having Case No: TAX/01/20/2042.

There is no change to the approved amount of \$1,500 @ 3 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Sent: Thursday, 30 January 2020 2:22 PM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Subject: Scan Data from FX-D421D6

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

369K

Vehicle Details

Vehicle No.:

SHC4626H

Vehicle to be Exported:

No

Intended Deregistration Date:

16 Jan 2020

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS TAXI (SMRT)

Primary Colour:

Maroon

Manufacturing Year:

2014

Engine No.:

2ZR6127774

Chassis No.:

JTDKN36U705748639

Maximum Power Output:

100.0 kW (134 bhp)

Open Market Value:

\$32,920.00

Original Registration Date:

08 Sep 2014

First Registration Date:

08 Sep 2014

Transfer Count:

0

Actual ARF Paid:

\$8,088.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

07 Sep 2022

PARF Rebate Amount:

\$5,661.00

Intended COE Rebate Details

COE Expiry Date:

07 Sep 2022

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$50,704.00

COE Rebate Amount:

\$16,751.00

Total Rebate Amount:

\$22,412.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 16 Jan 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/01/2020 13:28
Date Of Accident	09/01/2020 11:50
Exact Location Of Accident	CAIRNHILL ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4626H
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	1XXXXX369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	TEO TECK LENG
NRIC No	SXXXX053F
Date Of Birth	17/02/1953
Occupation	OUTDOOR
Date Of Driving Pass	06/01/1972
Driving Experience	48 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-800000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	3
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG CAIRNHILL ROAD AT THE SECOND RIGHT LANE WITH TWO PASSENGERS ON BOARD AND HAD STOPPED INSIDE THE YELLOW BOX DUE TO THE FRONT VEHICLES ALL STOPPED AS RED TRAFFIC LIGHT AHEAD. WHEN THE TRAFFIC STARTED TO MOVE, I FOLLOW SUIT. SUDDENLY THE VEHICLE SKW1914E WHICH CAME OUT FROM HULLET ROAD CUT ACROSS LANES INTO MY TRAVEL PATH AND COLLIDED ONTO THE LEFT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKW1914E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SONG WUI PIN CAVIN
NRIC/Passport Number	SXXXX124H
Contact Number	

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

HULLET RD

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION

I/We declare the foregoing particulars are true in every respect:



Policyholder Signature: _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms); which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Case Details

Case Reference Number : TAX/01/20/2042
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4626H

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-10081-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 09/01/2020 03:50 AM
 Vehicle Age(In Months) : 64

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	• / Nec
One Time Key In	Main			HINGE LOWER LHF, DOOR	1	90.10	90.10	25.00	67.57	Replace	0	0	Check	• X Svc
One Time Key In	Main			HINGE UPPER LHF, DOOR	1	80.50	80.50	25.00	60.38	Replace	0	0	Check	• X Svc
One Time Key In	Main			CHECK ASSY, FR DOOR,	1	130.30	130.30	25.00	112.73	Replace	0	0	Check	• X Svc
One Time Key In	Main			DOOR OUTER HANDLE FRT/LH	1	370.80	370.80	25.00	278.10	Replace	0	0	Check	• X Svc
One Time Key In	Main			DOOR WEATHERSTRIP FRT/LH	1	171.20	171.20	25.00	128.40	Replace	0	0	Check	• X Svc
One Time Key In	Main			MIRROR ASSY,LH	1	1,224.90	1,224.90	25.00	918.68	Replace	0	0	Not Give	• X Svc
One Time Key In	Main			MIRROR LAMP LH	1	65.30	65.30	10.00	58.77	Replace	0	0	Not Give	• X Svc
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	107.40	107.40	25.00	80.55	Replace	0	0	Not Give	• X Svc
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	0	0	Not Give	• X Svc

Total Spare Part Cost 11,000.42

Surveyor Total 209.40

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 8,800.34

Final Sur Total 167.52

SMRT Recommendation											Surveyor Approval			
BCM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			FENDER LINER PAD, FR WHEEL, LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			MOULDING BODY, LH	1	673.60	673.60	25.00	505.20	Replace	1	0	Repair	* X R
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	0	Repair	* X R
One Time Key In	Main			BUMPER CLIPS	10	2.10	21.00	25.00	15.75	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	* / NCC
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check	* X SVC
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			UNDER COVER RR SHIELD	1	63.90	63.90	25.00	47.92	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			DOOR RR/LH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair	* X R
One Time Key In	Main			DOOR LOCK RR/LH	1	709.30	709.30	25.00	531.97	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	0	0	Not Give	* X SVC
Total Spare Part Cost									11,000.42	Surveyor Total 209.40				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									8,800.34	Final Sur Total 167.52				

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER CLIPS	10	1.51	15.10	25.00	12.08	Replace	0	0	Not Give	*X SVC
One Time Key In	Main			BUMPER SUPPORT F/RH	1	75.40	75.40	25.00	57.30	Replace	0	0	Not Give	*X SVC
One Time Key In	Main			BUMPER SUPPORT F/LH	1	75.40	75.40	25.00	57.30	Replace	0	0	Not Give	*X SVC
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Give	*X SVC
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Not Give	*X SVC
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give	*X SVC
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give	*X SVC
One Time Key In	Main			BUMPER GRILLE SUB-ASSY,LOWER	1	311.10	311.10	10.00	279.99	Replace	0	0	Not Give	*X SVC
One Time Key In	Main			BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	*X SVC
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Not Give	*X SVC
One Time Key In	Main			HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	0	0	Not Give	*X SVC
One Time Key In	Main			DOOR FRT/LH	1	894.40	854.40	25.00	670.80	Replace	1	0	Repair	*X R
One Time Key In	Main			HINGE LOWER LHR, DOOR	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	*X SVC
One Time Key In	Main			HINGE UPPER LHR, DOOR	1	81.70	81.70	25.00	61.28	Replace	0	0	Not Give	*X SVC
One Time Key In	Main			DOOR REGULATOR MOTOR REAR LH	1	768.90	768.90	10.00	692.01	Replace	0	0	Check	*X SVC
One Time Key In	Main			DOOR REGULATOR SUB-ASSY, FRT/REAR LH	1	224.80	224.80	25.00	168.60	Replace	0	0	Check	*X SVC

Total Spare Part Cost 11,008.42

Surveyor Total 208.40

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 8,800.34

Final Sur Total 167.52

SMRT Recommendation										Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			WIRE LHR,DOOR	1	280.20	280.20	10.00	252.18	Replace	0	0	Not Give • X SUC
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair • X R
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace ✓ Nec
One Time Key In	Main			STICKER DECAL 65558868	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace ✓ Nec
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	0	0	Not Give • X SUC

Total Spare Part Cost	11,000.42	Surveyor Total	209.40
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	8,800.34	Final Sur Total	167.52

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	676.00	450	✓
Total:			676.00	450.00	

13203.70
13953.60

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	0	
2	Main	TO RESPRAY REAR BUMPER	378.00	200	✓
3	Main	TO RESPRAY FRONT DOOR LH	378.00	200	✓
4	Main	TO REPSRAY REAR DOOR LH	378.00	200	✓
5	Main	TO RESPRAY FRONT FENDER LH	378.00	0	
6	Main	TO RESPRAY REAR FENDER LH	378.00	200	✓
7	Main	RESPRAY MIRROR COVER LH	185.00	0	
8	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	100	✓
Total:			2,628.00	900.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TRANSFER DOOR MECHANISM	120.00	0	
2	Main	TO REMOVE AND REFIX WING MIRROR	120.00	0	
3	Main	TO REPLACE SUNDRY PARTS	100.00	0	
4	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
5	Main	TO WASH AND VACUUM	60.00	0	
6	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
Total:			600.00	0.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To survey damaged part(s) during resurvey
- Facts above are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No final modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to prior approval from Insurance Company

Authorised by Repairer
Signature:
Date:

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	8,800.34	167.52
Total Labour Cost	676.00	450.00
Total Spray Painting	2,628.00	900.00
Other	600.00	0.00
Overall Total	12,704.34	1,517.52
Lump Sum Repair Option		
Lump Sum Total	12,700.00	1,500.00
Surveyor Approved Amount		1,500.00
No of Repair Days*	6	3 days
Remarks		Lump Sum repair, Take after spray photo.
Surveyor Name		Sun Pin (LKK)
Signature		 12/2/2020
Survey Date	15/01/2020	

Save Clear


12757.60

Section A - Accident Details

Registration Number	SHC4826H
Case Reference Number	TAX001/20/2042
Registration Date	6/9/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TEO TECK LENG
Type of Accident	Head To Side
Accident Date and Time	9/1/2020 11:50 AM
Accident Reported Date and Time	9/1/2020 1:28 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24105243
Special Instruction to ARC, if any	TP
Prepared Date and Time	9/1/2020 5:54 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$876.00	\$450.00
Total Spray Cost	\$2,628.00	\$900.00
Total Spare Part Cost	\$5,800.34	\$167.52
Total Other Cost	\$500.00	\$0.00
TOTAL COST	\$12,704.34	\$1,517.52
Lump Sum Total	\$12,700.00	\$1,500.00 (L/5)
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Fong Soon Loh	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	15/01/2020 5:23 PM	15/01/2020 4:08 PM
Signature		
Remarks		Lump Sum repair. Take after spray photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2001-0356	Invoice Number	
Quotation Date	24.01.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$676.00	\$450.00
Total Labour	\$676.00	\$450.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO REPSRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
RESPRAY MIRROR COVER LH	\$180.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$2,628.00	\$900.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
Total Other Costs	\$600.00	\$0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		88740-12120	HINGE LOWER LHF, DOOR	0.00	\$90.10	0.00	\$0.00	Replace	Check X
		88720-15151	HINGE UPPER LHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Check X
		68810-47021	CHECK ASSY, FR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Check X
		69210-74030	DOOR OUTER HANDLE FRT/LH	0.00	\$370.80	0.00	\$0.00	Replace	Check X
		67862-47030	DOOR WEATHERSTRIP FRT/LH	0.00	\$171.20	0.00	\$0.00	Replace	Check X
		87940-47310	MIRROR ASSY, LH	0.00	\$1,224.90	0.00	\$0.00	Replace	Not Given X
		81740-52040	MIRROR LAMP LH	0.00	\$65.30	0.00	\$0.00	Replace	Not Given X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park EA, Singapore 737705
TAX Number: 53688552
Estimate Telephone Number: 6862823
Accident Reporting Number: 6862823

Date Generated: 28/11/2018

User ID: PtdBuan

87945-74010	COVER, OUTER MIRROR, LH	0.00	\$107.40	0.00	\$0.00	Replace	Not Given	X
53802-47050	FENDER FRT/LH	0.00	\$723.40	0.00	\$0.00	Replace	Not Given	X
75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X
53878-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given	X
53852-47020	FENDER LINER PAD, FR WHEEL LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X
75852-47900	MOULDING BODY, LH	1.00	\$673.60	100.00	\$0.00	Replace	Repair	R
52159-47905	BUMPER REAR	1.00	\$458.80	100.00	\$0.00	Replace	Repair	R
90467-07211	BUMPER CLIPS	0.00	\$2.10	0.00	\$0.00	Replace	Not Given	X
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	✓
	SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
52578-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Check	X
52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X
76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given	X
76891-47020	BUMPER LIP REAR	0.00	\$226.90	0.00	\$0.00	Replace	Not Given	✓
51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given	Y
67004-47080	DOOR RR/LH	1.00	\$954.50	100.00	\$0.00	Replace	Repair	R
69060-47080	DOOR LOCK RR/LH	0.00	\$709.30	0.00	\$0.00	Replace	Not Given	X
52119-47930	BUMPER FRT	0.00	\$482.00	0.00	\$0.00	Replace	Not Given	X
52161-16010	BUMPER CLIPS	0.00	\$1.61	0.00	\$0.00	Replace	Not Given	✓
52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given	X
52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given	X
52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given	X
52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Not Given	Y
57014-47030	ARM SUB-ASSY,FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X
57013-47030	ARM SUB-ASSY,FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X
53102-47020	BUMPER GRILLE SUB-ASSY,LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given	X
76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	Y
52616-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Not Given	X
81170-47500	HEAD LAMP LH	0.00	\$945.20	0.00	\$0.00	Replace	Not Given	Y
67002-47070	DOOR FRT/LH	1.00	\$894.40	100.00	\$0.00	Replace	Repair	R
68780-52031	HINGE LOWER LHR, DOOR	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X
68760-20122	HINGE UPPER LHR, DOOR	0.00	\$81.70	0.00	\$0.00	Replace	Not Given	Y
85720-47130	DOOR REGULATOR MOTOR REAR LH	0.00	\$766.90	0.00	\$0.00	Replace	Check	X
69802-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR LH	0.00	\$224.80	0.00	\$0.00	Replace	Check	X
82154-47300	WIRE LHR, DOOR	0.00	\$260.20	0.00	\$0.00	Replace	Not Given	X
61602-47091	FENDER RR/LH	1.00	\$766.80	100.00	\$0.00	Replace	Repair	R
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓
	STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓
81581-47170	TAIL LAMP LH	0.00	\$548.40	0.00	\$0.00	Replace	Not Given	X
Total			\$13,860.21		\$209.40			

209.40

- 20%

167.52

+450.00

+900.00

1517.52

45 \$1500/-

3 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL			Ref : CS/AGI20000930/Qqd3e2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			 Date : 13-02-2020 Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKW 1914E	Veh. Inspected	SHC 4626H	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10005218/CH	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	15/01/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTDKN36U705748639	Colour	MAROON	
Odometer	625214	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	5 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	5 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/01/2020	Inspection Date	15/01/2020	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4626H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 65558888 (SN)	NECESSARY	21.60	21.60
1	HINGE LOWER LHF, DOOR	SERVICEABLE	90.10	-
1	HINGE UPPER LHF, DOOR	SERVICEABLE	80.50	-
1	CHECK ASSY, FR DOOR,	SERVICEABLE	150.30	-
1	DOOR OUTER HANDLE FRT / LH	SERVICEABLE	370.80	-
1	DOOR WEATHERSTRIP FRT / LH	SERVICEABLE	171.20	-
1	MIRROR ASSY, LH	SERVICEABLE	1,224.90	-
1	MIRROR LAMP LH	SERVICEABLE	65.30	-
1	COVER, OUTER MIRROR, LH	SERVICEABLE	107.40	-
1	FENDER FRT / LH	SERVICEABLE	723.40	-
1	NAME PLATE (HYBRID)	SERVICEABLE	51.90	-
1	FENDER LINER FRT / LH	SERVICEABLE	171.70	-
1	FENDER LINER PAD, FR WHEEL LH	SERVICEABLE	49.30	-
10	BUMPER CLIPS @\$2.10	SERVICEABLE	21.00	-
1	SENSOR REVERSE	SERVICEABLE	180.00	-
1	BUMPER SIDE RETAINER RR/LH	SERVICEABLE	94.80	-
1	BUMPER SIDE RETAINER RR/RH	SERVICEABLE	94.80	-
1	BUMPER LIP COVER RR/RH	SERVICEABLE	118.10	-
1	BUMPER LIP REAR	SERVICEABLE	228.90	-
1	UNDER COVER RR SHIELD	SERVICEABLE	63.90	-
1	DOOR LOCK RR/LH	SERVICEABLE	709.30	-
1	BUMPER FRT	SERVICEABLE	482.00	-
10	BUMPER CLIPS @\$1.61	SERVICEABLE	16.10	-
1	BUMPER SUPPORT F/RH	SERVICEABLE	76.40	-
1	BUMPER SUPPORT F/LH	SERVICEABLE	76.40	-
1	BUMPER ENERGY ABSORBER FRT	SERVICEABLE	78.80	-
1	BUMPER REINFORCEMENT FRT	SERVICEABLE	498.40	-
1	ARM SUB-ASSY, FR BUMPER LH	SERVICEABLE	250.40	-
1	ARM SUB-ASSY, FR BUMPER RH	SERVICEABLE	250.40	-
1	BUMPER GRILLE SUB-ASSY, LOWER	SERVICEABLE	311.10	-
1	BUMPER LIP FRT	SERVICEABLE	139.60	-

Report Ref No. CS/AGI20000930/Qqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER FRT ABSORBER LOWER	SERVICEABLE	127.70	-
1	HEAD LAMP LH	SERVICEABLE	945.20	-
1	HINGE LOWER LHR, DOOR	SERVICEABLE	72.20	-
1	HINGE UPPER LHR, DOOR	SERVICEABLE	81.70	-
1	DOOR REGULATOR MOTOR REAR LH	SERVICEABLE	768.90	-
1	DOOR REGULATOR SUB-ASSY, FRT / REAR LH	SERVICEABLE	224.80	-
1	WIRE LHR, DOOR	SERVICEABLE	280.20	-
1	TAIL LAMP LH	SERVICEABLE	548.40	-
1	MOULDING BODY, LH	TO REPAIR SEE LABOUR	673.60	-
1	BUMPER REAR	TO REPAIR SEE LABOUR	458.60	-
1	DOOR RR/LH	TO REPAIR SEE LABOUR	954.50	-
1	DOOR FRT / LH	TO REPAIR SEE LABOUR	894.40	-
1	FENDER RR/LH	TO REPAIR SEE LABOUR	766.80	-
			13,953.60	209.40
	LABOUR			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF MOULDING BODY, LH, BUMPER REAR, DOOR RR/LH, DOOR FRT / LH AND FENDER RR/LH.		676.00	450.00
	SPRAY PAINT.		2,628.00	900.00
	TO TRANSFER DOOR MECHANISM.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIX WING MIRROR.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	80.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	-
			3,904.00	1,350.00
	GRAND TOTAL		17,857.60	1,559.40

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,500.00
---	--	--	-----------------

Report Ref No. CS/AGI20000930/Qqd3e2

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.