

ASS. REC. BY:

REF: es/CTI20000939/Egd3er

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

CTI

Date/Time: 15/10/2020 @ 1:58pm

Estimated Cost:

Bill to:

OD - TP - WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMM 3846 J

Insured:

SGL 189 T

at Workshop m/s

Wearnes Automotive

Tel:

9770 4368

of

249 Alexandra Road

Policy No:

DMPCSN 30445619055

Claim No:

SNM20D200177COR

Sum insured:

Excess:

Make of Veh:

D.O.A. 10.1.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:01pm @ 15/11/2020

Person Contacted:

patricia

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate 1

SMM 3846 J - X

SGL 189 T - X

26/02/20 @ 2:17pm Patricia informed that the owner not proceeding the claim with them thru email.

26/2/20 Submit Prelim. report. - The vehicle has not send in for repair.

ASSIGNMENT

From: _____ Date: 16/01/2020

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMM 3846J
at Workshop no: Wearnes Automotive
of 45 Leng Kee Road

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 2pm @ waiting
patricia @ 9770 4368

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. repairs: 1 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMM 3846J Yr Regn: 11/7/15

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Land Rover Evoque G.C. 1999

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 39192 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SALVA 2 A64 FH 046184

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/60R18
R: 11

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. 19/1/20 D.O.I. 16/1/20

Survey held at: Wearnes

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear RH

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV-115 K

RECEIVED 27 FEB 2020

Date/Time, File Pass to:

☒ Prel. Report

11/2/2015

☐ Final Report

Date/Time, File Return to:

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp. (\$)

☐ Interview (\$)

☐ Tech. Insp. (\$)

☐ Wheel stud (\$)

Survey Fee:

Transportation

3 + PG. 34

Phone

Collect

3

3/11

220

220

Report Form: 1

Lump Sum / H.R. (\$)

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 15 January 2020 1:48 PM
To: Patricia Kueh Anak Slin
Cc: Paul Ong Qing Yong; 'assignments'
Subject: RE: OUR REF: SNM20D200177/SGL189T/IRENE - TP CLaim for SMM3846J

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK.

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Patricia Kueh Anak Slin [mailto:patricia.kueh@wearnes.com]
Sent: Tuesday, January 14, 2020 5:51 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: Paul Ong Qing Yong <paul.ong@wearnes.com>
Subject: RE: OUR REF: SNM20D200177/SGL189T/IRENE - TP CLaim for SMM3846J

Dear Chong,

Please arrange for LKK for the survey.

Please advice for confirmation survey.

Thank you.

Patricia Kueh

Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 9770 4368 D (65) 6378 9336
www.wearnesauto.com patricia.kueh@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Patricia Kueh Anak Slin
Sent: Tuesday, 14 January 2020 4:39 pm
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: Paul Ong Qing Yong <paul.ong@wearnes.com>
Subject: RE: OUR REF: SNM20D200177/SGL189T/IRENE - TP CLaim for SMM3846J

Dear Chong,

Please arrange for LKK for the survey.

Thank you.

Patricia Kueh
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 9770 4368 D (65) 6378 9336
www.wearnesauto.com patricia.kueh@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 14 January 2020 4:34 pm
To: Patricia Kueh Anak Slin <patricia.kueh@wearnes.com>
Subject: RE: OUR REF: SNM20D200177/SGL189T/IRENE - TP CLaim for SMM3846J

Without prejudice
Save as to costs

Dear Sir,
LKK
LBS
STA

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Patricia Kueh Anak Slin <patricia.kueh@wearnes.com>
Sent: Monday, January 13, 2020 9:30 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Paul Ong Qing Yong <paul.ong@wearnes.com>
Subject: TP CLaim for SMM3846J

Hi,

Please refer attachments and advise if we can settle direct for this case.

Please arrange for pre repair survey on 14.01.20 at 10am. Location at Land Rover Showroom, 45 Leng Kee Road.
Owner will be waiting.

Please advice for confirmation survey.

Thank you.

Patricia Kueh
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 9770 4368 D (65) 6378 9336
www.wearnesauto.com patricia.kueh@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

Shiau Chan (LKKAUTO)

From: Patricia Kueh Anak Slin <patricia.kueh@wearnes.com>
Sent: Wednesday, 26 February 2020 2:17 PM
To: Shiau Chan (LKKAUTO)
Subject: Re: KINDLY ADVISE THE STATUS OF VEHICLE SMM 3846J (DOA: 10/01/2020)

Dear Shiau Chan,

The owner not proceeding the claim with us.

Thank you.

Get [Outlook for Android](#)

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Wednesday, February 26, 2020 2:14:00 PM
To: Patricia Kueh Anak Slin <patricia.kueh@wearnes.com>
Subject: KINDLY ADVISE THE STATUS OF VEHICLE SMM 3846J (DOA: 10/01/2020)

Dear Patricia,

Kindly advise the status of vehicle SMM 3846J.

If done for repair works, kindly send us the final bill for finalise.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 643H

Vehicle Details

Vehicle No.: SMM3846J
Vehicle to be Exported: No
Intended Deregistration Date: 16 Jan 2020
Vehicle Make: LAND ROVER
Vehicle Model: RANGE ROVER EVOQUE 2.0 T55
Primary Colour: White
Manufacturing Year: 2015
Engine No.: 010914123218204PT
Chassis No.: SALVA2AG4FH046184
Maximum Power Output: 177.0 kW (237 bhp)
Open Market Value: \$53,679.00
Original Registration Date: 22 Jul 2015
First Registration Date: 22 Jul 2015
Transfer Count: 1
Actual ARF Paid: \$68,623.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 21 Jul 2025
PARF Rebate Amount: \$51,467.00

Intended COE Rebate Details

COE Expiry Date: 21 Jul 2025
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$65,501.00
COE Rebate Amount: \$36,113.00
Total Rebate Amount: \$87,580.00

The information contained herein is correct as at 16 Jan 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/01/2020 10:50
Date Of Accident	10/01/2020 20:00
Exact Location Of Accident	ALONG CHANGI VILLAGE AVENUE 5 CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMM3846J
Insured/Policyholder	
Name Of Registered Owner	RAVINDRAN S/O SOMASUNDARAM
NRIC No	SXXXX643H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88789265
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	LAND ROVER
Model	RANGE ROVER EVOQUE-2.0 TSS (A)
Exact Purpose for which vehicle was being used at time of accident	

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5112856162
Cover Note Number	

Driver

Name of Driver	RAVINDRAN S/O SOMASUNDARAM
NRIC No	SXXXX643H
Date Of Birth	15/06/1967
Occupation	INDOOR
Date Of Driving Pass	06/03/1996
Driving Experience	23 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88789265
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	NOEMAIL

Address	BLK 638 PASIR RIS DRIVE 1 #05-558
Postcode	510638
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : SPOUSE GENDER: : FEMALE
Passenger 2	NAME: : SON GENDER: : MALE
Passenger 3	NAME: : DAUGHTER GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PASIR RIS NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 1 PASIR RIS DRIVE 4 , POSTCODE: 519457 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5852999 - FAX NO: 65855261
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN AND NOTICE OF REPORTING ATTACHED.

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGL189T
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please ensure completely and truthfully the accident is reported to the police.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation will be subject to investigation with a view to recovery of the policy. Policy may allow recovery of payment to repudiate policy liability.
4. The usual and accepted practice of fact finding by insurance companies is to interview both policyholder and the driver of the involved company.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be made available by the insurers of the other involved company to their staffs who will be required to provide Association of Surgeons (ASG) for reviewing and that reports of this report will be made available to any appropriate person (ASG).
7. By the signing of this report, the insured is authorizing the insurers to use the information contained in this report and to disclose it to the relevant authorities (ASG).
8. Consent under the Personal Data Protection Act (PDPA).

Accident Sketch Plan

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DECLARATION

NOTICE OF REPORTING

RM100000

ENCLOSURE INFORMATION

This is to confirm that PAVIN NERAN S/O SOMA SUNTHASAM NRIC/PPN S2638643H, HP: 88789265 has reported to the Police a non-injury traffic accident which occurred at CHANGI VILLAGE AVENUE 5 CARPARK on 10/01/2020 at 2000HRS, involving the following vehicles:

SHW638461 (Complainant's vehicle)

SGT189T (Involved vehicle)

2. If this accident was reported to the Police within 24 hours of its occurrence, then the driver has complied with Sec 31(2) of the Road Traffic Act, Cap 376.

Rank/Name of Issuing Officer: Sgt115 EVA SHEBHIENA

Date: 11/01/2020 Time: 0945hrs

S/O Ref: 12

Police Post/Unit: PASIR RIS NPS

18/01/20, 2:15pm
 Steve (LKK) w/rl P/L
 1 chg
 P/P
 By B/L SL

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PO

Mr B Benedict Ravin

638 Pasir Ris Drive 1 (s)510638

#05-558

Singapore 510638

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 13/01/2020

WIP No. : 58342

Veh.In/Out:

*Tel.No. : Work: 92396971

Reg.No. : 3MH3846J

Reg.date : 22/07/2015

Mileage : 0

Chassis No: SALVA2AG4FH046184

Closed by : Patricia Kueh Anak S

Svc Consultant :

Remarks : Mr Benedict Ravin

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	B
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR BUMPER, 1770	0	3600.00	0		3,600.00	\$ 1700
	QUARTER PANEL MOULDING RH,						
	REAR DOOR MOULDING RH,						
	REAR DOOR LOWER MOULDING RH,						
	REPAIR REAR DOOR RH,ETC						
800	TO PUTTY SPRAYPAINT AND	0	3000.00	0		3,000.00	\$ X
	BLENDING OF PAINT ON						
	REAR BUMPER,						
	REAR DOOR RH,ETC						
280	TO CHECK WIRING INCLUDE	0	510.00	0		510.00	\$ X
	RESETING OF ALL ELECTRICAL MODULES						
0031	TO REPLACE REAR RH RH	0	50.00	0		50.00	\$ /
419	WHEEL ALIGNMENT	0	280.00	0		280.00	\$ /
	LLR038060/BUMPER - R x NM	1.0 EA	2705.60			2,705.60	\$
	BRACKET - BUMPER MOU ?	1.0 EA	62.10			62.10	\$
	BUMPER BRACKET REAR ?	1.0 EA	122.80			122.80	\$
	LLR048461/WHEEL - AL / 17	1.0 EA	1830.90			1,830.90	\$

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC

Mr B Benedict Ravin

638 Pasir Ris Drive 1 (s)510638

805-558

Singapore 510638

Closed by : Patricia Kueh Anak S

Svc Consultant :

Remarks : Mr Benedict Ravin

EST Reg.No: M28920628X

Inv.No. : H&P 0 Page 2

Inv.date : 13/01/2020

WIP No. : 58342

Veh.In/Out:

*Tel.No. : Work: 92396971

Reg.No. : 3MH3846J

Reg.date : 22/07/2015

Mileage : 0

Chassis No: SALVA2AG4FH046184

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount S
-------	-------------	----------	-------	-------	-----	----------

DOOR TRIM REAR RH EV	/ M	1.0 EA	64.40			64.40 S
WHEEL MOULDING REAR	/ M	1.0 EA	203.00			203.00 S
LLR053218/MOULDING	- ?	1.0 EA	228.30			228.30 S
ADHESIVE SEALER FL2	X M	1.0 EA	682.50			682.50 S

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour Total	7,440.00
Parts Total	5,899.60
Package Total	0.00

Gross Total : 13,339.60

Net..... 13,339.60

GST @ 7.0% 953.77

Total..... 14,293.35

Paid..... 0.00

Please Pay.. 14,293.35

GST: S=StdRated; O=OutOfScope; I=ZeroRated

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jan 2020		21 Jan 2020 13:20 Edit Adj Rpt	S\$3,628.30 Edit Estimates	S\$3,628.30 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	- Co. Reg. No.: -								
Main Claimant:	RAVINDRAN S/O SOMASUNDARAM , ID: S2638643H								
Vehicle Reg. No.:	SMM3846J	Date of Loss:	10/01/2020 20:00 - :59 [53 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D200177C02	Policy/Cover Note No.:	DMPCSN30445619055						
Vehicle Reg. No. (Insured):	SGL189T	Policy No. (Claimant):	5112856162						
		Excess:	S\$0.00						
Repairer:	Wearnes Automotive Pte Ltd (Leng Kee) 28 Leng Kee Road, 159105 Leng Kee - Tel: 63782680								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 31/01/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMM3846J (SNM20D200177C02)**
[SGL189T]
TP
RAVINDRAN S/O SOMASUNDARAM
Jan 10 2020 8:00PM
[-]
Wearnes Automotive Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Video							1 per page		☒	
No	Finalized On	Abwin Service Pte Ltd (HQ)						Thumbnail	Print	
1	11/01/20 11:25	Video - Accident [Linked Accident Report Documents]						Load MP4		
2	11/01/20 11:25	Video - Accident [Linked Accident Report Documents]						Load MP4		
Assessment Reports							1 per page		☒	
No	Finalized On	Abwin Service Pte Ltd (HQ)						Thumbnail	Print	
1	11/01/20 11:28	Accident Statement						Load HTM		
Photos/Images							3 per page		☒	
No	Finalized On	Abwin Service Pte Ltd (HQ)						Thumbnail	Print	
1	11/01/20 11:24	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
2	11/01/20 11:24	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
3	11/01/20 11:24	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
4	11/01/20 11:24	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
5	11/01/20 11:24	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
6	11/01/20 11:24	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
7	11/01/20 11:24	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
8	11/01/20 11:24	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
9	11/01/20 11:24	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
10	11/01/20 11:24	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
11	11/01/20 11:24	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
12	11/01/20 11:24	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	27/02/20 12:05	General View						Load JPG	☒	
2	27/02/20 12:05	General View						Load JPG	☒	
3	27/02/20 12:05	General View						Load JPG	☒	
4	27/02/20 12:05	General View						Load JPG	☒	
5	27/02/20 12:05	General View						Load JPG	☒	
6	27/02/20 12:05	General View						Load JPG	☒	
7	27/02/20 12:05	General View						Load JPG	☒	
8	27/02/20 12:05	General View						Load JPG	☒	
9	27/02/20 12:05	General View						Load JPG	☒	
10	27/02/20 12:05	General View						Load JPG	☒	
11	27/02/20 12:05	General View						Load JPG	☒	
12	27/02/20 12:05	General View						Load JPG	☒	

Video			1 per page	☒
No	Finalized On	Abwin Service Pte Ltd (HQ)	Thumbnail	Print
				☒
13	27/02/20 12:05	General View	Load JPG	☒
14	27/02/20 12:05	General View	Load JPG	☒
15	27/02/20 12:05	General View	Load JPG	☒
16	27/02/20 12:05	General View	Load JPG	☒
17	27/02/20 12:05	General View	Load JPG	☒
18	27/02/20 12:05	General View	Load JPG	☒
19	27/02/20 12:05	General View	Load JPG	☒
20	27/02/20 12:05	Odometer Reading	Load JPG	☒
21	27/02/20 12:05	Chassis Number	Load JPG	☒
22	27/02/20 12:05	General View	Load JPG	☒
23	27/02/20 12:05	General View	Load JPG	☒
24	27/02/20 12:05	General View	Load JPG	☒
25	27/02/20 12:05	General View	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Abwin Service Pte Ltd (HQ)	Thumbnail	Print
1	11/01/20 11:23	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	☒
2	11/01/20 11:23	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	☒
3	11/01/20 11:23	NOTICE OF REPORTING [Linked Accident Report Documents]	Load JPG	☒
4	11/01/20 11:23	DRIVER'S PARTICULARS [Linked Accident Report Documents]	Load JPG	☒
5	11/01/20 11:23	INSURANCE CERTIFICATE [Linked Accident Report Documents]	Load JPG	☒

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Abwin Service Pte Ltd (HQ)	Thumbnail	Print
1	11/01/20 11:25	Video - Accident	Load MP4	
2	11/01/20 11:25	Video - Accident	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Abwin Service Pte Ltd (HQ)	Thumbnail	Print
1	11/01/20 11:28	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Abwin Service Pte Ltd (HQ)	Thumbnail	Print
1	11/01/20 11:24	Accident Photo	Load JPG	☒
2	11/01/20 11:24	Accident Photo	Load JPG	☒
3	11/01/20 11:24	Accident Photo	Load JPG	☒
4	11/01/20 11:24	Accident Photo	Load JPG	☒
5	11/01/20 11:24	Accident Photo	Load JPG	☒
6	11/01/20 11:24	Accident Photo	Load JPG	☒
7	11/01/20 11:24	Accident Photo	Load JPG	☒
8	11/01/20 11:24	Accident Photo	Load JPG	☒
9	11/01/20 11:24	Accident Photo	Load JPG	☒
10	11/01/20 11:24	Accident Photo	Load JPG	☒
11	11/01/20 11:24	Accident Photo	Load JPG	☒
12	11/01/20 11:24	Accident Photo	Load JPG	☒

Video			1 per page	☒
No	Finalized On	Abwin Service Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Finalized On	Abwin Service Pte Ltd (HQ)	Thumbnail	Print
1	11/01/20 11:23	Accident Sketch Plan	 Load JPG	☒
2	11/01/20 11:23	Accident Sketch Plan	 Load JPG	☒
3	11/01/20 11:23	NOTICE OF REPORTING	 Load JPG	☒
4	11/01/20 11:23	DRIVER'S PARTICULARS	 Load JPG	☒
5	11/01/20 11:23	INSURANCE CERTIFICATE	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20000939/EQD3E2

Date: 03/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN30445619055

Claimant Vehicle
No: SMM3846JInsured Vehicle
No: SGL189T

Date of Loss: 10/01/2020

Nature of Claim: TP

Claim
No: SNM20D200177C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM3846J**
 Make & Model: **LAND ROVER RANGE ROVER EVOQUE, 2.0 TSS (A)** Engine No: **010914123218204PT**
 Reg. Date: **22/07/2015 (Man. Year: 2015)** Chassis No: **SALVA2AG4FH046184**
 Colour: **White** Odometer: **39102 km**
 Engine Capacity: **1999 cc**
 Market Value/New Car Price: **N/A**
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: **235/60 R18** Rear Tyre Size: **235/60 R18**
 Front Left Side: **Bridgestone 6 mm** Rear Left Side: **Bridgestone 6 mm**
 Front Right Side: **Bridgestone 6 mm** Rear Right Side: **Bridgestone 6 mm**

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,899.60	2,098.30	3,801.30	64.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,440.00	1,530.00	5,910.00	79.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,339.60	3,628.30	9,711.30	72.80
+ GST 7.00/7.00% (S\$)	933.77	253.98	679.79	72.80
Nett Amount (S\$)	14,273.37	3,882.28	10,391.09	72.80

INSPECTION

Date of Assignment: 21/01/2020

Date Inspected: 16/01/2020 Inspected At:

45 LENG KEE ROAD

Repairer : Wearnes Automotive Pte Ltd

Estimated Period of Repair: 1.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$413.20 NETT)

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 03 Mar 2020)

Parts: M1-SUV LAND ROVER RANGE ROVER EVOQUE 2.0 TSS (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMM3846J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LLR058060/BUMPER - R	Not Necessary	2,705.60 FS	*- FS
2	1		*BRACKET - BUMPER MOU	* Check	62.10 FS	*- FS
3	1		*BUMPER BRACKET REAR	* Check	122.80 FS	*- FS
4	1		*LLR048461/WHEEL - AL	Cut	1,830.90 FS	*1,830.90 FS
5	1		*DOOR TRIM REAR RH EV	Cut	64.40 FS	*64.40 FS
6	1		*WHEEL MOULDING REAR	Cut	203.00 FS	*203.00 FS
7	1		*LLR053218/MOULDING -	* Check	228.30 FS	*- FS
8	1		*ADHESIVE SEALER FL2	Not Necessary	682.50 FS	*- FS
Total Parts (S\$)					5,899.60	2,098.30

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER, QUARTER PANEL MOULDING RH, REAR DOOR MOULDING RH, REAR DOOR LOWER MOULDING RH, REPAIR REAR DOOR RH, ETC	New	3,600.00	1,200.00
2	TO PUTTY SPRAYPAINT AND BLENDING OF PAINT ON REAR BUMPER, REAR DOOR RH, ETC	New	3,000.00	0.00
3	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	510.00	0.00
4	TO REPLACE REAR RIM RH	New	50.00	50.00
5	WHEEL ALIGNMENT	New	280.00	280.00
Gross Labour Cost (\$\$)			7,440.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >