

EG... LK

Kp

\$ undecarage do alignment 1st



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Not Authorized
11 Sep 2020
Penny Ate Perm

Repair Estimates

SLJ 2624 S

Finalized	
Parts (a) Cost / List Price Items	\$ 7124.91 10,779.48
Plus/Less 25%	\$ 1781.23 2,694.87
Total of Cost / List	\$ 5343.68 8,084.61
(b) Nett Price Items	_____
Less	_____
Total of Nett Item	_____
(c) Special Nett Items	\$ _____ 250.00
Total Parts Cost	\$ _____ 8,334.61
Labour	\$ 1160.00 2,830.00
Total	\$ 6503.68 11,164.61

- 201-1
= \$5207.94
= \$5006.00

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 14/1/20 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 05 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Rc Date: 14/1/20



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLJ 2624 S
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU003538307

Submit By : JENNY
 Year Manufacture : 2016
 Engine No. : _____
 Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front support panel RH	1	\$213.50		X
2	Headlamp panel RH	1	\$89.20		X
3	Headlamp RH	1	\$2,531.60		✓
4	Front bumper	1	\$450.80		✓
5	Front bumper clip	10	\$40.00		✓
6	Front bumper side retainer RH	1	\$107.20		✓
7	Front bumper side retainer LH	1	\$107.20		X
8	Front bumper upper grille	1	\$321.90		X
9	Front bumper lower grille	1	\$148.60		X
10	Fog lamp RH	1	\$910.70		✓
11	Washer tank	1	\$195.60		✓
12	Washer tank motor	1	\$196.74		X
13	Engine under cover RH	1	\$87.70		✓
14	RH front fender	1	\$868.70		✓
15	RH front fender undershield	1	\$185.64		✓
16	RH front fender undershield clip	10	\$25.00		✓
17	RHF fender wording "HYBRID"	1	\$44.17		✓
18	RH front fender quarter garnish	1	\$122.70		✓
19	RH front lower arm	1	\$492.65		?
20	RH front shock absorber	1	\$462.70		?
21	RH front shock absorber top mouting	1	\$195.07		?
22	RH front shock absorber stopper	1	\$37.02		?
23	RH front knuckle arm	1	\$476.75		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
 Company Reg No. 200005485N / GST No. 20-0005485-N

5569.81

Spare Parts

Vehicle No. : SLJ 2624 S
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU003538307

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	RH front knuckle bearing } <i>sn</i>	1	\$573.20		X
25	RH front wheel hub	1			
26	RH front wheel hub lock nut <i>na</i>	1	\$28.02		X
27	RH front tie rod end <i>sn</i>	1	\$116.40		X
28	RH front hub cap <i>sn</i>	1	\$195.62		X
29	RH front rim <i>na</i>	1	\$1,555.10		✓
30	RH front tyre <i>sn</i>	1	\$250.00	S.N	X
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

1524-10



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLJ 2624 S Submit By : Carmen Lim
 Make & Model : TOYOTA PRIUS Year of Manufacture : 2016

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER,RHF FENDER,RHF DOOR, BONNET,SUPPORT PANEL)	\$1,000.00	400
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,RHF FENDER,RHF DOOR, BONNET,SUPPORT PANEL)	\$1,200.00	600
3	To check wiring, focus headlamp	\$50.00	20
4	To remove & refit undercarriage to assist work load. <i>nn</i>	\$250.00	7
5	To do wheel alignment.	\$120.00	60
6	To tuff coat.	\$150.00	30
7	Towing	\$60.00	50

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

1160