

EGY - LKK

Kp

\$ undecarage do alignment 1st



# ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Not Authorized  
11 Bay, Q5200  
Permay Ate Palm

## Repair Estimates

SLJ 2624 S

Finalised

|                                   |            |           |
|-----------------------------------|------------|-----------|
| Parts (a) Cost / List Price Items | \$ 7124.91 | 10,779.48 |
| Plus/Less 25%                     | \$ 1781.23 | 2,694.87  |
| Total of Cost / List              | \$ 5343.68 | 8,084.61  |
| (b) Nett Price Items              |            |           |
| Less                              |            |           |
| Total of Nett Item                |            |           |
| (c) Special Nett Items            | \$         | 250.00    |
| Total Parts Cost                  | \$         | 8,334.61  |
| Labour                            | \$ 1160.00 | 2,830.00  |
| Total                             | \$ 6503.68 | 11,164.61 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

- 2011  
= \$5207.94  
= \$5000.00

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 14/1/20 at \_\_\_\_\_

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 05 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : PC Date: 14/1/20



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Spare Parts

Vehicle No. : SLJ 2624 S  
 Make & Model : TOYOTA PRIUS  
 Chassis No : JTDKB3FU003538307

Submit By : JENNY  
 Year Manufacture : 2016  
 Engine No. : \_\_\_\_\_  
**Cost / List**

| S/No. | Part Description                    | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|-------------------------------------|-----|------------|-------|-------------------------|
| 1     | Front support panel RH              | 1   | \$213.50   |       | X                       |
| 2     | Headlamp panel RH                   | 1   | \$89.20    |       | X                       |
| 3     | Headlamp RH                         | 1   | \$2,531.60 |       | ✓                       |
| 4     | Front bumper                        | 1   | \$450.80   |       | ✓                       |
| 5     | Front bumper clip                   | 10  | \$40.00    |       | ✓                       |
| 6     | Front bumper side retainer RH       | 1   | \$107.20   |       | ✓                       |
| 7     | Front bumper side retainer LH       | 1   | \$107.20   |       | X                       |
| 8     | Front bumper upper grille           | 1   | \$321.90   |       | X                       |
| 9     | Front bumper lower grille           | 1   | \$148.60   |       | X                       |
| 10    | Fog lamp RH                         | 1   | \$910.70   |       | ✓                       |
| 11    | Washer tank                         | 1   | \$195.60   |       | ✓                       |
| 12    | Washer tank motor                   | 1   | \$196.74   |       | X                       |
| 13    | Engine under cover RH               | 1   | \$87.70    |       | ✓                       |
| 14    | RH front fender                     | 1   | \$868.70   |       | ✓                       |
| 15    | RH front fender undershield         | 1   | \$185.64   |       | ✓                       |
| 16    | RH front fender undershield clip    | 10  | \$25.00    |       | ✓                       |
| 17    | RHF fender wording "HYBRID"         | 1   | \$44.17    |       | ✓                       |
| 18    | RH front fender quarter garnish     | 1   | \$122.70   |       | ✓                       |
| 19    | RH front lower arm                  | 1   | \$492.65   |       | ?                       |
| 20    | RH front shock absorber             | 1   | \$462.70   |       | ? } SUC X               |
| 21    | RH front shock absorber top mouting | 1   | \$195.07   |       | ?                       |
| 22    | RH front shock absorber stopper     | 1   | \$37.02    |       | ? } SUC X               |
| 23    | RH front knuckle arm                | 1   | \$476.75   |       | ?                       |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829  
 Company Reg No. 200005485N / GST No. 20-0005485-N

5569-81

**Spare Parts**

Vehicle No. : SLJ 2624 S  
 Make & Model : TOYOTA PRIUS  
 Chassis No : JTDKB3FU003538307

Submit By : Carmen Lim  
 Year Manufacture : 2016  
 Engine No. : \_\_\_\_\_

**Cost / List**

| S/No. | Part Description                      | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|---------------------------------------|-----|------------|-------|-------------------------|
| 24    | RH front knuckle bearing } <i>Sm</i>  | 1   | \$573.20   |       | <i>X</i>                |
| 25    | RH front wheel hub                    | 1   |            |       |                         |
| 26    | RH front wheel hub lock nut <i>nm</i> | 1   | \$28.02    |       | <i>X</i>                |
| 27    | RH front tie rod end <i>Sm</i>        | 1   | \$116.40   |       | <i>X</i>                |
| 28    | RH front hub cab <i>Sm</i>            | 1   | \$195.62   |       | <i>X</i>                |
| 29    | RH front rim <i>Sm</i>                | 1   | \$1,555.10 |       | <i>✓</i>                |
| 30    | RH front tyre <i>Sm</i>               | 1   | \$250.00   | S.N   | <i>X</i>                |
| 31    |                                       |     |            |       |                         |
| 32    |                                       |     |            |       |                         |
| 33    |                                       |     |            |       |                         |
| 34    |                                       |     |            |       |                         |
| 35    |                                       |     |            |       |                         |
| 36    |                                       |     |            |       |                         |
| 37    |                                       |     |            |       |                         |
| 38    |                                       |     |            |       |                         |
| 39    |                                       |     |            |       |                         |
| 40    |                                       |     |            |       |                         |
| 41    |                                       |     |            |       |                         |
| 42    |                                       |     |            |       |                         |
| 43    |                                       |     |            |       |                         |
| 44    |                                       |     |            |       |                         |
| 45    |                                       |     |            |       |                         |
| 46    |                                       |     |            |       |                         |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

*15/10*

