

TP CHINA
12

K. Kim Hin

CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 30958

Vehicle Insured : PA 5005 J
Accident Date : 09-Jan-2020

Date : 09-Jan-2020

Our Ref : 020013 (CHINA) / SANDRA

PAGE : 1

CHAK KUM HOONG (MR)
Singapore

NOT AUTHORIZED
6th Jan @ 3368.20

ESTIMATED COST OF REPAIR FOR SUBARU LEGACY 2.5I (2015) SKS9694H

1 pc	front bumper			R 594.00	✓
1 pc	front bumper sponge			SL 57.60	✓
1 pc	front bumper reinforcement			R 288.30	✓
2 pcs	front bumper side retainer (LH/RH)	@ S\$ 18.30		SL 36.60	✓ 1pc
1 pc	n/s front bumper fog lamp			SL 272.00	X
1 pc	n/s front bumper fog lamp cover			SL 50.40	✓
1 pc	n/s front bumper spray nozzle			CM SL 86.40	✓
1 pc	n/s front bumper spray nozzle pump			CM SL 160.00	✓
1 pc	n/s front bumper spray nozzle cover			SL 54.30	X
1 pc	n/s front bumper top seal			SL 27.00	✓
1 pc	front bumper centre bracket -lower			SL 57.60	✓
10 pcs	front bumper clips	@ S\$ 3.50		SL 35.00	✓
1 pc	n/s head lamp assy			SL 1,870.00	✓
1 pc	n/s head lamp lower bracket			SL 32.80	✓
1 pc	n/s front fender			SL 270.00	✓
1 pc	n/s front fender inner shield			SL 108.00	X
10 pcs	n/s front fender inner shield clips	@ S\$ 3.50		SL 35.00	X
1 pc	n/s front fender top garnish			SL 18.00	✓
1 pc	wiper washer tank			SL 97.20	✓
1 pc	wiper washer tank motor			SL 68.40	✓
1 pc	wiper washer tank motor bush			SL 4.50	✓
1 pc	battery cover			SL 30.40	X
1 pc	battery bracket			R 14.40	X
				4,267.90	
				Less 20% :	-853.58
					3,414.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and is subject to final approval from LKK Auto Consultants Company

Acknowledged by Repairer
Signature:
Date:

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : PA 5005 J
Our Ref : 020013

Page : 2
No. : 30958

1 pc battery

sn 280.00 sn X

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

400.00 360

To putty and respray on affected
portions.

600.00 500

To focus headlamps. To check front
wiring and lighting operation.

30.00 20

Total : S\$ 4,724.32
=====

Singapore Dollars Four Thousand Seven Hundred
and Twenty Four and Cents Thirty Two Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

3111.50
-20%

2489.20 sparts
+ 880.00 Labour

3369.20 ✓ ok
