

TP CHINA
12

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 30958

Vehicle Insured : PA 5005 J
Accident Date : 09-Jan-2020

Date : 09-Jan-2020

Our Ref : 020013 (CHINA) / SANDRA

PAGE : 1

CHAK KUM HOONG (MR)
Singapore

Not Notarise
C/Pay &?

ESTIMATED COST OF REPAIR FOR SUBARU LEGACY 2.5I (2015) SKS9694H

1 pc	front bumper		R	594.00	✓
1 pc	front bumper sponge			57.60	?
1 pc	front bumper reinforcement			288.30	?
2 pcs	front bumper side retainer (LH/RH)	@ S\$ 18.30	n/s/m	36.60	✓
1 pc	n/s front bumper fog lamp		SL	272.00	X
1 pc	n/s front bumper fog lamp cover			50.40	?
1 pc	n/s front bumper spray nozzle		SL	86.40	X
1 pc	n/s front bumper spray nozzle pump		SL	160.00	X
1 pc	n/s front bumper spray nozzle cover		SL	54.30	X
1 pc	n/s front bumper top seal		SL	27.00	✓
1 pc	front bumper centre bracket -lower			57.60	?
10 pcs	front bumper clips	@ S\$ 3.50	SL	35.00	✓
1 pc	n/s head lamp assy		ng	1,870.00	✓
1 pc	n/s head lamp lower bracket		n/s	32.80	✓
1 pc	n/s front fender		R	270.00	X
1 pc	n/s front fender inner shield		SL	108.00	X
10 pcs	n/s front fender inner shield clips	@ S\$ 3.50	SL	35.00	X
1 pc	n/s front fender top garnish		Deform	18.00	✓
1 pc	wiper washer tank			97.20	?
1 pc	wiper washer tank motor			68.40	?
1 pc	wiper washer tank motor bush			4.50	?
1 pc	battery cover		SL	30.40	X
1 pc	battery bracket		R	14.40	X
				4,267.90	
Less 20% :				-853.58	
				3,414.32	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : PA 5005 J
Our Ref : 020013

Page : 2
No. : 30958

1 pc battery

sn 280.00 sn X

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

400.00 360

To putty and respray on affected
portions.

600.00 500

To focus headlamps. To check front
wiring and lighting operation.

30.00 20

Total : S\$ 4,724.32
=====

Singapore Dollars Four Thousand Seven Hundred
and Twenty Four and Cents Thirty Two Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.