

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Jan 2020 Edit Reg		15 Jan 2020 00:00 Edit Adj Rpt	S\$2,100.00 Edit Estimates	S\$2,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: TAN TEIK KEAT , ID: S7876078H									
Main Claimant: GRAB RENTALS PTE LTD									
Vehicle Reg. No.: SLG6061E		Date of Loss: 11/01/2020 17:00 - :59 [39 Months and 5 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 9331456060SG		Policy/Cover Note No.: 1800137161 (Comprehensive)							
Vehicle Reg. No. (Insured): SMG3251G		Policy No. (Claimant):							
		Excess:							
Repairer: Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259, 569536 Ang Mo Kio - Tel: 64841221									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 24/01/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG_EXPRESS (14/07/2020): Alert - Adj Mandate Approved (S\$2614.23) - SLG6061E - Claim Handler: Tan, Bennie...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLG6061E (9331456060SG)
[SMG3251G]
TP
GRAB RENTALS PTE LTD
Jan 11 2020 5:40PM
[TAN TEIK KEAT]
Esteem Performance Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

Letters/Correspondences

1 per page ▼ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit	

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/04/20 21:15	Chassis Number		Load JPG	☒
2	13/04/20 21:15	Odometer Reading		Load JPG	☒
3	13/04/20 21:15	General View		Load JPG	☒
4	13/04/20 21:15	General View		Load JPG	☒
5	13/04/20 21:15	General View		Load JPG	☒
6	13/04/20 21:15	General View		Load JPG	☒
7	13/04/20 21:15	General View		Load JPG	☒
8	13/04/20 21:15	General View		Load JPG	☒
9	13/04/20 21:15	General View		Load JPG	☒
10	13/04/20 21:15	General View		Load JPG	☒
11	13/04/20 21:15	General View		Load JPG	☒
12	13/04/20 21:15	Reinspection Photo		Load JPG	☒
13	13/04/20 21:15	Reinspection Photo		Load JPG	☒
14	13/04/20 21:15	Reinspection Photo		Load JPG	☒

Documentation

1 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/01/20 15:44	ACKNOWLEDGEMENT EMAIL TO AIG DD15012020		Load PDF	
2	15/01/20 15:44	EMAIL FROM AIG DD15012020		Load PDF	
3	15/01/20 15:44	NOTIFICATION FROM WKSP + TP ESTIMATE + TP GIA REPORT		Load PDF	
4	11/02/20 13:15	LETTER TO OI		Load PDF	
5	13/04/20 21:37	TP ESTIMATE - MARKED		Load PDF	
6	21/05/20 12:33	LOD		Load PDF	
7	21/05/20 12:35	TP ESTIMATE MARKED FINALISED		Load PDF	
8	06/07/20 09:53	LTA SEARCH		Load PDF	
9	06/07/20 09:53	RENTAL AGREEMENT		Load PDF	
10	28/07/20 13:05	Authorisation to Act		Load PDF	
11	28/07/20 13:05	Release Voucher		Load PDF	
12	28/07/20 13:05	WORKSHOP INVOICE		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	16/01/20 14:58	OI GIA REPORT		Load PDF	
2	14/07/20 12:41	CLEAR v1		Load XLSX	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#)
[Save](#)
[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMG3251G (Insd veh)	Model:	TOYOTA PRIUS 1.8 HYBRID
	SLG6061E (TP veh)		CVT (A)
Date of Accident:	11/01/2020		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	3,654.67
Final Repair Cost	:	\$	2,247.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	359.75 5 days
LTA / GIA Search Fee	:	\$	7.48
Others:	:	\$	
	:	\$	
Final Settlement Sum	:	\$	2,614.23
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Esteem Performance Pte Ltd	:	\$ 2,614.23
2)		:	\$
3)		:	\$
4)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

28 Jul
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20000951/KBS3S2**Date:** 28/07/2020**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800137161
Claimant Vehicle No :	SLG6061E	Insured Vehicle No :	SMG3251G
Date of Loss:	11/01/2020	Nature of Claim:	TP
		Claim No:	9331456060SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG6061E	Engine No:	2ZRR953803
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU203535781
Reg. Date:	06/10/2016 (Man. Year: 2016)	Odometer:	244653 km
Colour:	Metallic Pearl White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 2 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,533.92	1,789.60	744.32	29.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	881.66	841.66	40.00	4.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,415.58	2,631.26	784.32	22.96
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	3,415.58	2,100.00	1,315.58	38.52
+ GST 7.00/7.00% (S\$)	239.09	147.00	92.09	38.52
Nett Amount (S\$)	3,654.67	2,247.00	1,407.67	38.52
+ Car Rental (5.0 x S\$71.95/day) (S\$)		359.75		
+ Doc/Search Fee (S\$)		7.48		
Nett Liability (S\$)		2,614.23		

INSPECTION

Date of Assignment:	15/01/2020	
Date Inspected:	06/02/2020	Inspected At: Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259 Singapore 569536
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*R/F WING	Bent	868.70 FL	*868.70 FL
2	1		*R/F WING BADGE	Necessary	44.17 FL	*44.17 FL
3	1		*R/F WHEELHOUSE COVER	Distorted	185.64 FL	*185.64 FL
4	1		*RIGHT FRONT DOOR	Bent	1,226.70 FL	*1,226.70 FL
5	1		*R/UPPER DOOR HINGE	Repair	78.34 FL	*- FL
6	1		*R/LOWER DOOR HINGE	Repair	78.34 FL	*- FL
7	1		*R/F DOOR CHECK	Serviceable	156.79 FL	*- FL
8	1		*R/F DOOR SEAL	Serviceable	198.49 FL	*- FL
9	1		*R/F DOOR LOCK	Repair	428.40 FL	*- FL
10	1		*R/F WINDOW CHANNEL	Serviceable	122.95 FL	*- FL
11	1		*RHF HUP CAP	Dented / Scratched	195.65 FL	*195.65 FL
12	1		*FENDER SHIELD CLIP RHF UNDERSHIELD	Necessary	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,609.17	2,545.86
- List Item Discount on L Items 30.00/30.00% (\$)	1,075.25	756.26
Total Parts (\$)	2,533.92	1,789.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TUFF COAT TUFF COAT.	New	100.00	60.00
2	LABOUR: ALIGNMENT.	New	255.00	255.00
3	LABOUR: MEASURING WORK.	New	70.00	70.00
4	PAINT WORK: LABOUR COST.	New	335.00	335.00
5	PAINT WORK: MATERIAL COST.	New	121.66	121.66
Gross Labour Cost (\$)			881.66	841.66

Report was unsubmitted during this print-out.

< END OF ESTIMATES >