

Claim Documents

***SLQ5752Z (6906533322SG)**
[GBB3237E]
TP
LION CITY RENTALS PTE LTD
Jan 10 2020 12:00PM
[I LOGISTICS PTE LTD]
Lion City Rentals Pte Ltd

View

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		<input type="button" value="Edit"/>

Photos/Images
3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/01/20 09:37	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	16/01/20 09:37	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
3	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
4	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
5	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
6	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
7	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
8	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
9	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
10	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
11	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
12	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
13	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
14	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
15	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
16	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
17	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
18	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
19	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
20	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
21	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
22	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
23	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
24	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
25	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
26	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
27	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
28	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
29	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
30	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
31	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
32	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
33	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
34	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
35	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
36	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
37	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
39	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
40	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
41	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
42	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
43	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
44	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
45	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
46	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
47	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
48	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
49	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
50	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
51	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
52	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
53	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
54	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
55	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
56	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
57	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
58	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
59	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
60	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
61	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
62	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
63	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
64	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
65	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
66	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
67	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
68	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
69	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
70	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
71	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
72	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
73	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
74	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
75	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
76	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
77	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
78	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
79	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
80	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
81	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
82	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
83	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
84	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
85	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
86	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
87	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
88	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
89	16/01/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
90	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
91	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
92	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
93	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
94	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
95	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
96	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
97	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
98	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
99	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
100	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
101	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
102	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
103	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
104	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
105	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
106	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
107	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
108	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>
109	16/01/20 09:38	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/01/20 15:51	ACKNOWLEDGEMENT EMAIL TO AIG DD 14.01.2020	Load PDF	
2	15/01/20 15:51	EMAIL FROM AIG DD 14.01.2020	Load PDF	
3	08/02/20 23:38	TP ESTIMATE - MARKED	Load PDF	
4	08/02/20 23:39	TP GIA REPORT	Load PDF	
5	11/02/20 13:35	LETTER TO OI	Load PDF	
6	12/06/20 12:42	TP ESTIMATE - FINALIZED	Load PDF	
7	26/06/20 16:48	LOD	Load PDF	
8	09/10/20 14:06	LTA SEARCH	Load PDF	
9	09/10/20 14:06	Release Voucher	Load PDF	
10	09/10/20 14:06	WORKSHOP INVOICE	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	16/01/20 14:55	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	GBB3237E (Insd veh)	Model:	HONDA VEZEL 1.5 (A)
	SLQ5752Z (TP veh)		
Date of Accident:	10/01/2020		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:\$		28,262.47
Final Repair Cost	:\$		12,700.00
Loss of Use	:\$		12.00 days at \$80.00 per day
Rental (if any)	:\$		days
LTA / GIA Search Fee	:\$		
Others:	:\$		
	:\$		
Final Settlement Sum (GLOBAL SUM)	:\$		12,700.00

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ 0 _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Lion City Rentals Pte Ltd	:\$	12,700.00
2)		:\$	
3)		:\$	
4)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

09 Oct
2020

Date

**Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/
Bill (if any)**

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20000952/QBA3S2**Date:** 09/10/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993960
Claimant Vehicle No :	SLQ5752Z	Insured Vehicle No :	GBB3237E
Date of Loss:	10/01/2020	Nature of Claim:	TP
		Claim No:	6906533322SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ5752Z	Engine No:	LEB5923517
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU31223504
Reg. Date:	14/07/2017 (Man. Year: 2016)	Odometer:	224683 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,823.52	10,530.08	10,293.44	49.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,590.00	3,590.00	2,000.00	35.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,413.52	14,120.08	12,293.44	46.54
Approved Total (Overridden) (S\$)		11,300.00		
(S\$)	26,413.52	11,300.00	15,113.52	57.22
+ GST 7.00/7.00% (S\$)	1,848.95	791.00	1,057.95	57.22
Nett Amount (S\$)	28,262.47	12,091.00	16,171.47	57.22
+ Loss of Use (12.0 x S\$80.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		13,058.45		
Global Sum Settlement (S\$)		12,700.00		

INSPECTION

Date of Assignment:	14/01/2020		
Date Inspected:	14/01/2020	Inspected At:	Lion City Rentals Pte Ltd (HQ) 60 Jalan Lam Huat, #04-01 Carros Centre Singapore 737869
Estimated Period of Repair:	10.0 days		

Adjuster: OI SUN PIN**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,100.00 FL	*1,100.00 FL
2	1		*REAR TAILGATE GLASS	Broken	1,500.00 FL	*1,200.00 FL
3	1		*REAR TAILGATE CENTER HOLDER GARNISH	Cracked	560.00 FL	*267.00 FL
4	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	86.80 FL	*86.80 FL
5	1		*REAR TAILGATE HONDA EMBLEM	Necessary	81.30 FL	*81.30 FL
6	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	86.80 FL	*86.80 FL
7	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*120.00 FL
8	1		*REAR TAILGATE WEATHERSTRIP	Crushed	155.00 FL	*155.00 FL
9	1		*REAR TAILGATE LOCK	Jammed	230.00 FL	*180.00 FL
10	1		*REAR TAILGATE LOCK CATCH	Serviceable	180.00 FL	*- FL
11	1		*REAR RH TAIL LAMP	Cracked	780.00 FL	*450.00 FL
12	1		*REAR RH TAILLAMP REFLECTOR	Cracked	480.00 FL	*400.00 FL
13	1		*REAR LH TAILLAMP	Cracked	780.00 FL	*450.00 FL
14	1		*REAR LH TAILLAMP REFLECTOR	Cracked	480.00 FL	*400.00 FL
15	1		*REAR END PANEL	Dented	780.00 FL	*530.00 FL
16	1		*REAR END PANEL TOP GARNISH	Cracked	155.00 FL	*155.00 FL
17	1		*REAR BUMPER	Crushed	900.00 FL	*900.00 FL
18	1		*REAR BUMPER RH REFLECTOR	Serviceable	180.00 FL	*- FL
19	1		*REAR BUMPER LH REFFLECTOR	Serviceable	180.00 FL	*- FL
20	1		*R/R FENDER WHEEL ARCH MOULDING	Serviceable	300.00 FL	*- FL
21	1		*R/L FENDER WHEEL ARCH MOULDING	Serviceable	300.00 FL	*- FL
22	1		*REAR SPARE TYRE TOOL BOX	Serviceable	480.00 FL	*- FL
23	1		*REAR SPARE TYRE PANEL	Repair	2,000.00 FL	*- FL
24	1		*FRONT BONNET	Repair	1,050.00 FL	*- FL
25	1		*FRONT SUPPORT PANEL	Dented	1,400.00 FL	*600.00 FL
26	1		*FRONT BONNET LOCK	Serviceable	328.00 FL	*- FL
27	1		*FRONT BONNET LOCK CATCH	Serviceable	150.00 FL	*- FL
28	1		*F/L FENDER	Repair	600.00 FL	*- FL
29	1		*F/L HEADLAMP	Broken	2,100.00 FL	*1,250.00 FL
30	1		*F/L HEADLAMP TOP BRACKET	Serviceable	210.00 FL	*- FL
31	1		*F/L HEADLAMP LOWER BRACKET	Serviceable	210.00 FL	*- FL
32	1		*F/R HEADLAMP	Broken	2,100.00 FL	*1,250.00 FL
33	1		*F/R HEADLAMP TOP BRACKET	Serviceable	210.00 FL	*- FL
34	1		*F/R HEADLAMP LOWER BRACKET	Serviceable	210.00 FL	*- FL
35	1		*FRONT BUMPER	Cut	955.00 FL	*955.00 FL
36	1		*FRONT BUMPER REINFORCEMENT	Bent	680.00 FL	*450.00 FL
37	1		*FRONT RADIATOR GRILLE BASE	Crushed	550.00 FL	*550.00 FL
38	1		*FRONT GRILLE MOULDING	Scratched	620.00 FL	*380.00 FL
39	1		*FRONT GRILLE LOWER MOULDING CHROME	Scratched	280.00 FL	*280.00 FL
40	1		*FRONT GRILLE HONDA LOGO	Missing	86.00 FL	*86.00 FL
41	1		*SET REAR BUMPER AND FRONT BUMPER CLIPS	Necessary	100.00 FS	*60.00 FS
42	1		*SET END PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*20.00 FS
43	1		*REVERSE SENSOR	Serviceable	490.00 FS	*- FS
44	1		*SET BODY SEALANT	Necessary	300.00 FS	*40.00 FS
45	1		*WINDSCREEN SEALANT	Necessary	200.00 FS	*40.00 FS
46	1		*DECAL	Necessary	20.00 FS	*20.00 FS
47	1		*REAR TAILGATE INNER TRIM BOARD	Crushed	580.00 FL	*321.70 FL
48	1		*F/L FENDER EMBLEM	Necessary	83.00 FL	*83.00 FL
49	1		*FRONT GRILLE CENTER BRACKET	Cracked	60.00 FL	*60.00 FL
50	1		*REAR SMART BUZZER	Crushed	110.00 FL	*110.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,731.90	13,117.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,908.38	2,587.52
Total Parts (\$\$)	20,823.52	10,530.08

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE, REAR END PANEL, REAR BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS.	New	1,500.00	900.00
2	TO RESPRAY REAR TAILGATE, END PANEL AND SPARE TYRE PANEL, REAR CORNER BUMPER	New	800.00	800.00
3	TO REMOVE AND INSTALL REAR TAILGATE GLASS.	New	160.00	120.00
4	TO APPLY RUSTPROOFING ON ALL DAMAGED PARTS.	New	180.00	40.00
5	TO CHECK WIRING SYSTEM.	New	100.00	30.00
6	TO RESPRAY FRONT BUMPER, F/L FENDER, SUPPORT PANEL AND FRONT BONNET.	New	900.00	700.00
7	TO LABOUR CHARGE FOR REMOVING FRONT BUMPER AND SUPPORT PANEL OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS.	New	1,250.00	800.00
8	TO ACTIVATE AND DEACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A SAFETY PRECAUTION. }	New	300.00	200.00
9	TO CONDUCT A STANDARD OF OPEARING PROCEDURES POST REPAIRS SCAN TEST AS A REQUIREMENT UPON COMPLETION OF COLLISION REPAIRS. }	New	300.00	0.00
10	TO SEND CAR FOR DECAL INSPECTION AT VICOM.	New	100.00	0.00
			Gross Labour Cost (S\$)	5,590.00
				3,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >