

Date: 14.01.2020
 Vehicle No: SLN737S
 Model: HYUNDAI SANTE FE
 Chassis: KMHSH81DR60087927-2006
 Reg.Year: 2007

Third Party Insurer: INDIA
 Third Party Veh No: SHD4833X
 Date of Accident: 13.01.2020

Idasi
ESTIMATE

*Not withaste
 1/1 Imp @?
 Measure After Paint*

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT HEADLAMP LH	1	<i>my cm</i>	\$927.00
2	FRONT BUMPER	1		<i>cm</i> \$677.00
3	FRONT BUMPER SIDE BRACKET LH	1		<i>Di</i> \$45.60
4	FRONT BUMPER CLIPS	10	\$5.80	<i>na</i> \$58.00
5	FRONT FINDER LH	1		<i>Pa</i> \$653.00
6	FRONT FENDER BRACE BRACKET LH	1		<i>diy</i> \$112.00
7	FRONT FENDER INNER LINER LH	1		<i>cm</i> \$146.00
8	FRONT FENDER INNER LINER CLIPS LH	8	\$6.20	<i>na</i> \$49.60
9	FRONT FENDER '4WD' EMBLEM LH	1		<i>na</i> \$38.20
10	FRONT DOOR LH	1	<i>not/wrap</i>	\$1,740.00
11	FRONT DOOR OUTER HANDLE LH	1		<i>my</i> \$116.00
12	FRONT DOOR OUTER HANDLE BASE LH	1		<i>my</i> \$48.00
13	FRONT DOOR OUTER HANDLE COVER LH	1		<i>my</i> \$65.00
14	FRONT DOOR OUTER HANDLE INNER BASE SUPPORT LH	1		<i>my</i> \$96.20
15	FRONT DOOR LOWER PROTECTOR COVER LH	1		\$149.60
16	FRONT DOOR FRAME PROTECTIVE STICKER LH	1		\$65.00
17	REAR DOOR LOWER PROTECTOR COVER LH	1		<i>not</i> \$146.80
18	FRONT ALLOY RIM LH(REPAIR)	1		<i>na</i> \$150.00
19	FRONT WHEEL BEARING LH	1		\$410.00
20	FRONT KNUCKLE ARM LH	1		\$642.00
21	POWER STEERING RACK ASSY	1		<i>su</i> \$2,412.00
22	FRONT DRIVE SHAFT LH	1		<i>R</i> \$1,356.00
23	FRONT SUPPORT PANEL ASSY	1		\$1,230.00
24	REAR DOOR LH	1		REPAIR
25	REAR QUARTER PANEL LH	1		REPAIR
26	REAR BUMPER	1		REPAIR
SUB TOTAL				\$11,333.00
LESS 20%				-\$2,266.60
PARTS TOTAL				\$9,066.40

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	SIDE SILL STEP PANEL ASSY LH	1		<i>R</i> \$980.00
S/N TOTAL				\$980.00

Date: 14.01.2020
Vehicle No: SLN737S
Model: HYUNDAI SANTE FE
Chassis: KMHSH81DR60087927-2006
Reg.Year: 2007

Third Party Insurer: INDIA
Third Party Veh No: SHD4833X
Date of Accident: 13.01.2020

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE,REPLACE,REPAIR,REFIX,READJUST ACCIDENT AREAS & ETC.	\$1,000.00	<i>700</i>
LABOUR CHARGES TO REMOVE,REPLACE,REFIX FRONT KNUCKLE AREA LH,DRIVESHAFT LH,POWER STEERING RACK,WHEEL BEARING,FRONT SUSPENSION FRAME & ETC.	\$380.00	<i>?</i>
LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$100.00	<i>600</i>
LABOUR CHARGES TO CHECK WIRING & DOOR CENTRAL LOCKING SYSTEM & ETC.	\$80.00	<i>200</i>
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER,FRONT FENDER LH,FRONT DOOR LH,REAR DOOR LH, REAR QUARTER PANEL LH,REAR BUMPER & ETC.	\$1,400.00	<i>1200</i>
LABOUR CHARGES TO REMOVE & REPLACE SIDE SILL STEP PANEL ASSY LH & ETC.	\$200.00	<i>~X</i>
TO WHEEL ALIGNMENT & BALANCING.	\$80.00	<i>600</i>
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$200.00	<i>600</i>
LABOUR TOTAL	\$3,440.00	

ONG	TOTAL	\$13,486.40
------------	--------------	--------------------