

Kp

Date: 14.01.2020
Vehicle No: SLN737S
Model: HYUNDAI SANTE FE
Chassis: KMHS81DR60087927-2006
Reg.Year: 2007

Third Party Insurer: INDIA
Third Party Veh No: SHD4833X
Date of Accident: 13.01.2020

*Not with the
1 Pump @ 4000 Flood
Pressure After Repair*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT HEADLAMP LH	1	<i>CM</i>	\$927.00
2	FRONT BUMPER <i>650</i>	1	<i>CM</i>	\$677.00
3	FRONT BUMPER SIDE BRACKET LH	1	<i>DI</i>	\$45.60
4	FRONT BUMPER CLIPS	10	\$5.80	\$58.00
5	FRONT FENDER LH	1	<i>DI</i>	\$653.00
6	FRONT FENDER BRACE BRACKET LH	1	<i>DI</i>	\$112.00
7	FRONT FENDER INNER LINER LH	1	<i>CM</i>	\$146.00
8	FRONT FENDER INNER LINER CLIPS LH	8	\$6.20	\$49.60
9	FRONT FENDER '4WD' EMBLEM LH	1	<i>DI</i>	\$38.20
10	FRONT DOOR LH <i>1335</i>	1	<i>DI / WIP</i>	\$1,740.00
11	FRONT DOOR OUTER HANDLE LH	1	<i>DI</i>	\$116.00
12	FRONT DOOR OUTER HANDLE BASE LH	1	<i>DI</i>	\$48.00
13	FRONT DOOR OUTER HANDLE COVER LH	1	<i>DI</i>	\$65.00
14	FRONT DOOR OUTER HANDLE INNER BASE SUPPORT LH	1	<i>DI</i>	\$96.20
15	FRONT DOOR LOWER PROTECTOR COVER LH	1	<i>DI</i>	\$149.60
16	FRONT DOOR FRAME PROTECTIVE STICKER LH	1	<i>DI</i>	\$65.00
17	REAR DOOR LOWER PROTECTOR COVER LH	1	<i>DI</i>	\$146.80
18	FRONT ALLOY RIM LH(REPAIR)	1	<i>DI</i>	\$150.00
19	FRONT WHEEL BEARING LH <i>230</i>	1	<i>DI</i>	\$410.00
20	FRONT KNUCKLE ARM LH <i>349.20</i>	1	<i>DI</i>	\$642.00
21	POWER STEERING RACK ASSY <i>1853.80</i>	1	<i>DI / WIP</i>	\$2,412.00
22	FRONT DRIVE SHAFT LH	1	<i>DI</i>	\$1,356.00
23	FRONT SUPPORT PANEL ASSY	1	<i>DI</i>	\$1,230.00
24	REAR DOOR LH	1		REPAIR
25	REAR QUARTER PANEL LH	1		REPAIR
26	REAR BUMPER	1		REPAIR
SUB TOTAL				\$11,333.00
LESS 20%				-\$2,266.60
PARTS TOTAL				\$9,066.40

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	SIDE SILL STEP PANEL ASSY LH	1		\$980.00
S/N TOTAL				\$980.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 14.01.2020
 Vehicle No: SLN737S
 Model: HYUNDAI SANTE FE
 Chassis: KMHSH81DR60087927-2006
 Reg.Year: 2007

Third Party Insurer: INDIA
 Third Party Veh No: SHD4833X
 Date of Accident: 13.01.2020

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX, READJUST ACCIDENT AREAS & ETC.	\$1,000.00	<i>700</i>
LABOUR CHARGES TO REMOVE, REPLACE, REFIX FRONT KNUCKLE AREA LH, DRIVESHAFT LH, POWER STEERING RACK, WHEEL BEARING, FRONT SUSPENSION FRAME & ETC.	\$380.00	<i>200</i>
LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$100.00	<i>60</i>
LABOUR CHARGES TO CHECK WIRING & DOOR CENTRAL LOCKING SYSTEM & ETC.	\$80.00	<i>20</i>
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER LH, FRONT DOOR LH, REAR DOOR LH, REAR QUARTER PANEL LH, REAR BUMPER & ETC.	\$1,400.00	<i>1200</i>
LABOUR CHARGES TO REMOVE & REPLACE SIDE SILL STEP PANEL ASSY LH & ETC.	\$200.00	<i>NN X</i>
TO WHEEL ALIGNMENT & BALANCING.	\$80.00	<i>60</i>
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$200.00	<i>60</i>
LABOUR TOTAL	\$3,440.00	

ONG	TOTAL	\$13,486.40
------------	--------------	--------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/inter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: