

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

1chanchan

Claim Type: Third Party
Accident Date: 11/01/2020
TP Veh Reg No: SGP3580E

Estimate No: **EST2000015**
Date: 13 Jan 2020
Veh Reg No: **SLU7535A**
Make/Model: PERODUA BEZZA
PREMIUM X 1.3 5MT
Chasis No: PM2B301S003078734
Reg. Date: 13/12/2017
Your Ref No: SGP3580E

Estimate Repair Cost to Vehicle No :SLU7535A

Quantity	Description	List Price SS	Amount SS
List Price			
1	1 PC BOOT LID <i>Deled</i>	950.00	885
2	1 PC BOOT LID LOGO	78.00	✓
3	1 PC BOOTLID "BEZZA" EMBLEM	80.00	✓
4	1 PC BOOT LID "VVTI" EMBLEM	45.00	✓
5	1 PC BOOTLID "X" EMBLEM	38.00	✓
6	1 PC BOOT LID CHROME <i>new</i>	480.00	+
7	1 PC BOOT LID LOCK <i>Deled</i>	360.00	295
8	1 PC BOOT LID LOCK CHECKER <i>new</i>	69.00	+
9	1 PC BOOT LID RUBBER <i>at</i>	313.00	285
10	2 PCS BOOT LID HINGE <i>new</i>	200.00	+
11	1 PC BOOTLID TRIM <i>new</i>	254.00	+
12	1 PC REAR PANEL <i>Deled</i>	720.00	665
13	1 PC REAR PANEL TRIM <i>Deled</i>	340.00	275
14	1 PC REAR FENDER INNER TRIM LH <i>new</i>	480.00	+
15	1 PC TAIL LAMP LH <i>new</i>	470.00	365
16	1 PC REAR BUMPER <i>Deled</i>	980.00	795
17	2 PCS REAR BUMPER SIDE RETAINER <i>new</i>	380.00	90
18	2 PCS REVERSE SENSORS <i>Deled</i>	672.00	200
19	1 PC REAR BUMPER LOWER SPOILER <i>Deled</i>	750.00	
20	1 PC REAR BUMPER REFLECTOR - LH <i>new</i>	140.00	65
	Tool Tray Sponge <i>Deled</i>	7.799.00	298
	Spore Type Panel Top Cones <i>new</i>	779.90	181
		Less 10%	
Special Net			
21	1 PC REAR NUMBER PLATE <i>new</i>	50.00	+
22	1 SET BOOTLID TRIM CLIPS <i>new</i>	40.00	+
23	1 SET REAR PANEL TRIM CLIPS <i>new</i>	40.00	10
24	1 SET REAR FENDER INNER TRIM CLIPS LH <i>new</i>	40.00	+
25	1 SET REAR BUMPER CLIPS <i>new</i>	48.00	30
		218.00	218.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2000015
Date: 13 Jan 2020
Veh Reg No: SLU7535A
Make/Model: PERODUA BEZZA
PREMIUM X 1.3 5MT
Chasis No: PM2B301S003078734
Reg. Date: 13/12/2017
Your Ref No: SGP3580E

Claim Type: Third Party
Accident Date: 11/01/2020
TP Veh Reg No: SGP3580E

Estimate Repair Cost to Vehicle No :SLU7535A

Quantity	Description	List Price S\$	Amount S\$
Labour			
26	1 TO CHECK WIRING	50.00 30	
27	1 TO REMOVE AND REFIT INNER TRIM	150.00 80	
28	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00 60	
29	1 TO SPRAY UNDERSEAL	150.00 80	
30	1 (REAR) TO SPRAY PAINTING	1,300.00 900	
31	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,400.00 900	
		3,130.00	3,130.00
Total			S\$ 10,367.10
Add GST @ 7%			725.70
Total Amount Payable			<u>S\$ 11,092.80</u>

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND NINETY TWO AND CENTS EIGHTY ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

total 6995

1/5 5.61C

Adrian C.
2/5 14/01/20.

06 Rmp.

(5.61C)

K Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: