

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 26041

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/0055/2020/NS  
Date : 15-Jan-20

## Vehicle IN workshop. Please arrange for survey

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Oh Yam Gim  
Address : 23 Hindhede Drive  
#04-04  
Singapore 589320  
Telephone : HP +65 96740010  
Type of Claim : Own Damage Claims  
Policy No. : 1700052489-02  
Vehicle No : ~~SLS 4925Y~~ SLS 4295Y  
Model Code : Audi A1 SB 1.0 TFSI S TRO  
Model / Year : Sep-17  
Engine No : CHZ 359880  
Chassis No : WAUZZZ8X7HB088657  
Mileage : 56588  
Date In : 12-Jan-20  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 12-Jan-20  
Place of Accident : Sims Avenue Exit 15

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLS 4925 Y

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To tow and recover vehicle from scene of accident.	S/N \$	280.00	X
2	To carry out first measurement test on car o-liner.	S/N \$	800.00	? photo X <sup>nn</sup>
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	✓ ✓
4	To remove and renew aircond condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,200.00	✓ ✓
5	To remove centre console, instrument panels and clusters. Renew dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit.	S/N \$	3,200.00	✓ ✓
<b>SUB TOTAL LABOUR CHARGES</b>			<b>: \$ 5,840.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
 Tel: 6366 2323 Fax: 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle SLS 4925 Y

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
6	To remove and reinstall engine assy with gearbox assy to facilitate car o-liner repairs.	S/N \$	2,800.00	? part X
7	To remove and reinstall front suspension assy with subframe to facilitate car o-liner repairs. Inspect for damages and renew if necessary.	S/N \$	2,400.00	? X
8	To place vehicle on car o-liner.	S/N \$	2,400.00	? part X
9	To remove and transfer both front door's multi-lock system and power window devices. Inspect for damages.	S/N \$	560.00	? X
10	To dismantle both front panel trims. To remove and reinstall both front wing mirror assy.	S/N \$	700.00	? part X
<b>SUB TOTAL LABOUR CHARGES</b>		:	<u><u>\$ 8,860.00</u></u>	

X  
mm

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle SLS 4925 Y

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
11	To dismantle front bumper, bonnet, both front fenders, both headlights and both front doors. Align both front chasis frames to specification of origin. Renew front lock carrier and align to position. Re-organise front crash management components. reinstall all parts removed.	\$ 9,100.00	3500. ✓
12	To respray front bumper, bonnet, hinges, both front fenders, engine compartment, both front upper A-pillars and both front doors. To carry out joint sealant work and stone chip treatment.	\$ 8,400.00	2750 + 550 3300/- ✓
13	To carry out wheel alignment.	S/N \$ 240.00	? × NA
14	To carry out diagnostic check.	S/N \$ 384.00	✓ ✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 32,824.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLS 4925 Y

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER	\$ 1,407.00	de ✓ 1125.60
2	FRONT BUMPER FIXING PARTS	\$ 224.00	? x nn
3	WHEEL HOUSING LINER ADAPTER - LH / RH	2 \$ 30.00	? x nn
4	FRONT BUMPER GRILLE - CENTRE	\$ 178.00	de ✓ 142.40
5	FRONT BUMPER CLOSING ELEMENT	\$ 152.00	de ✓ 121.60
6	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 734.00	? x nn
7	RADIATOR GRILLE	\$ 894.00	an ✓ 715.20
8	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$ 630.00	bl ✓ 504.00
9	FRONT BUMPER FOAM FILLER PIECE	\$ 107.00	de ✓ 85.60
10	EXTERNAL TEMPERATURE SENSOR	\$ 54.00	ms ✓ x nn
11	TEMPERATURE SENSOR BRACKET	\$ 17.00	ms ✓ x nn
12	SIGNAL HORN - RH HIGH TONE	\$ 206.00	? x nn
13	SIGNAL HORN - LH LOW TONE	\$ 206.00	? x nn
14	FRONT FENDER - LH / RH	2 \$ 1,618.00	LH ✓, RH ✓, bf ✓ 647.20
15	FRONT FENDER ATTACHMENT PARTS	\$ 41.00	? x nn
16	FRONT FENDER CENTRE BRACKET - LH / RH	2 \$ 22.00	? x nn
17	FRONT FENDER FRONT BRACKET - LH / RH ✓ bt	2 \$ 108.00	? ✓ 88.96
18	FRONT FENDER FRONT BRACE - LH / RH	2 \$ 98.00	? x } X
19	FRONT FENDER CLOSING ELEMENT - LH / RH	2 \$ 46.00	? x } nn
20	FRONT WHEEL HOUSING LINER SEAL - UPPER	2 \$ 61.00	? x }
<b>SUB TOTAL SPARE PARTS CHARGES</b>		<b>\$</b>	<b><u>6,833.00</u></b>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
 Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLS 4925 Y

S/N	Parts Description			Damage Parts & Prices	
		S/NETT	Remarks	S/NETT	Remarks
21	FRONT WHEEL HOUSING LINER - LH / RH	2	\$	316.00	? x nn
22	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS		\$	36.00	? x nn
23	BONNET		\$	2,063.00	bt / 1650.40
24	BONNET ATTACHMENT PARTS		\$	126.00	? x nn
25	BONNET LID HINGE - LH / RH	2	\$	232.00	bt / 184.80
26	BONNET GAS FILLED STRUT		\$	133.00	? x nn
27	BONNET COVER - LH / RH	2	\$	58.00	? x nn
28	BONNET EDGE PROTECTION - FRONT	2	\$	36.00	? 29.76 de /
29	BONNET CATCH HOOK		\$	60.00	bt / 48.00
30	BONNET LOCK BAR	2	\$	90.00	bt / 72.00
31	BONNET CATCH HOOK		\$	58.00	bt / 46.40
32	BONNET LID LOCK	2	\$	391.00	bt / 317.60
33	MICRO SWITCH	2	\$	133.00	? x nn
34	BONNET BOWDEN CABLE - CENTRE		\$	53.00	? 43.20 dis ✓
35	BONNET LID LOCK CABLE		\$	43.00	? x } nn
36	BONNET BRACKET		\$	53.00	? x }
37	BONNET LID LOCK CABLE GRIP		\$	22.00	? x }
38	BONNET SOUND ABSORBER		\$	185.00	de / 148.00
39	PLENUM CHAMBER COVER		\$	174.00	? x nn
40	HEADLIGHT MOUNTING - LH / RH ✓ Crn	2	\$	214.00	? 178.40 Crn ✓
<b>SUB TOTAL SPARE PARTS CHARGES</b>		:	\$	<b>4,476.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLS 4925 Y

S/N	Parts Description			Damage Parts & Prices	
		S/NETT	Remarks	S/NETT	Remarks
41	HEADLIGHT - LH / RH	2	\$	3,584.00	amt ✓ 2867.20
42	GAS DISCHARGE LAMP CONTROL UNIT ✓ Cut	2	\$	2,102.00	? ✓ 859.20
43	DAY DRIVING LIGHTS POWER MODULE ✓ shorts	2	\$	1,044.00	? ✓ 427.60
44	GAS DISCHARGE LAMP	2	\$	796.00	? x } X
45	LED WITH HEAT SINK - LH / RH	2	\$	714.00	? x } nn
46	GAS DISCHARGE BULB WIRING SET	2	\$	200.00	? x }
47	HEADLIGHT HOSE - LH / RH ✓ Cut LHI-x <sup>nn</sup> 1pc ✓	2	\$	54.00	? ✓ 22.32
48	LIFT CYLINDER - LH / RH ✓ Con	2	\$	256.00	? ✓ 214.40
49	HEADLIGHT HOSE		\$	170.00	? x }
50	HEADLIGHT DISTRIBUTOR		\$	13.00	? x }
51	HEADLIGHT ELBOW FITTING		\$	23.00	? x }
52	HEADLIGHT PUMP		\$	147.00	? x }
53	WINDSCREEN WASHER SYSTEM PUMP		\$	118.00	? x }
54	WASH WATER RESERVOIR		\$	197.00	? ✓ 159.60 dey
55	LOCK CARRIER		\$	936.00	bt ✓ 748.80
56	CROSS MEMBER REINFORCEMENT	2	\$	24.00	bt ✓ 21.52
57	AIRCON CONDENSER		\$	503.00	bt ✓ 402.40
58	REFRIGERANT LINE ✓ Bt		\$	445.00	? ✓ 363.60
59	REFRIGERANT LINE ✓ Bt		\$	342.00	? ✓ 279.60
60	COOLANT LINE BRACKET ✓ Con		\$	23.00	? ✓ 18.40
<b>SUB TOTAL SPARE PARTS CHARGES</b>			<b>:</b>	<b>\$ 11,691.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLS 4925 Y

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
61	RADIATOR	\$	768.00	bt ✓ 614.40
62	RADIATOR BRACKET	2 \$	77.00	bt ✓ 61.60
63	RADIATOR BUSH - LOWER	2 \$	18.00	bt ✓ 14.40
64	READY MIX COOLANT	4 \$	84.00	we ✓ 67.20
65	ADDITIONAL RADIATOR	\$	609.00	bt ✓ 487.20
66	ADDITIONAL RADIATOR SEAL - LOWER	\$	25.00	ne ✓ 20.00
67	RADIATOR SEAL - LOWER	\$	13.00	ne ✓ 10.40
68	RADIATOR SEAL - LH / RH	2 \$	36.00	ne ✓ 28.80
69	RADIATOR FAN RING	\$	127.00	crn ✓ 101.60
70	RADIATOR FAN	\$	690.00	dis ✓ 552.00
71	RADIATOR AIR GUIDE - LH / RH ✓ Crn	2 \$	56.00	? ✓ 46.56
72	AIR INTAKE AIR FILTER	\$	252.00	? × AA
73	AIR INTAKE AIR GUIDE ✓ Crn	\$	47.00	? ✓ 38.16
74	AIR INTAKE WATER DRAINAGE HOSE	\$	19.00	? ×
75	AIR INTAKE MANIFOLD	\$	129.00	? ×
76	VENT HOSE	\$	11.00	? ×
77	AIR INTAKE MANIFOLD	\$	588.00	? ×
78	INTER COOLER GASKET	\$	13.00	? ×
79	CHARGE AIR COOLER	\$	692.00	? ×
80	INTAKE MANIFOLD GASKET	\$	13.00	? ×
<b>SUB TOTAL SPARE PARTS CHARGES</b>		<b>:</b>	<b>\$ 4,267.00</b>	

X  
nh

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLS 4925 Y

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
81	INTER COOLER GASKET	\$	13.00 ? X	
82	THROTTLE VALVE CONTROL ELEMENT	\$	973.00 ? X	} X nn
83	THROTTLE VALVE SEAL	\$	16.00 ? X	
84	THROTTLE VALVE CONNECTING TUBE	\$	307.00 ? X	
85	FRONT DOOR - RH	\$	1,841.00 R X X	
86	FRONT DOOR ATTACHMENT PARTS	\$	121.00 X X nn	
87	FRONT DOOR CATCH	\$	81.00 X X nn	
88	AIRCON STICKER	NEC \$	35.00 ne ✓	28.00
89	CAUTION SIGN STICKER	NEC \$	13.00 w ✓	10.40
90	TYRE PRESSURE DATA PLATE	\$	35.00 ne X	} X nn
91	FRONT DOOR - LH	\$	1,841.00 X X	
92	FRONT DOOR ATTACHMENT PARTS	\$	121.00 X X	
93	FRONT DOOR CATCH	\$	81.00 X X	
94	STEERING WHEEL AIRBAG UNIT	\$	3,242.00 act ✓	2593.60
95	AIRBAG UNIT	\$	3,548.00 act ✓	2838.40
96	AIRBAG CONTROL UNIT	\$	1,480.00 act ✓	1184.00
97	ACCELERATION SENSOR	\$	273.00 ? X nn	
98	CENTRAL PROTECTION	\$	dis ✓ 432.00 ? ✓	act ✓ 357.60
99	SEAT BELT - LH / RH	2 \$	act ✓ 1,904.00 LH ✓ RH act ✓	1523.20
100	SEAT BELT HEIGHT ADJUSTER	2 \$	361.00 X nn	
<b>SUB TOTAL SPARE PARTS CHARGES</b>		:	<u>\$ 16,718.00</u>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
 Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLS 4925 Y

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
101	STEERING WHEEL	\$ 1,749.00	? x nh
102	DASHBOARD	\$ 3,570.00	du ✓ 2856.00
103	AIR VENT - UPPER CENTRE	\$ 105.00	? x } X
104	LOUDSPEAKER MOUNTING	\$ 59.00	? x } nh
105	LOUDSPEAKER COVER	\$ 86.00	? x }
106	FRONT NO PLATE	S/N \$ 40.00	bt ✓
107	SUNDRIES	\$ 800.00	? ✓ 75.04
TOTAL SPARE PARTS CHARGES		:	\$ 50,394.00
TOTAL LABOUR CHARGES		:	\$ 32,824.00
GRAND TOTAL		:	\$ 83,218.00

REC ✓

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
 Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

*[Handwritten signature]*  
16/1/2020

## Telefax

Name :  
Surveyed Date :  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks :

Tanpin 97495749  
Not Authorise  
Ex: to be advise.  
14/1/20.  
Resurvey before paint  
sur @ lkkauto.com.  
16 days. + 3 days

**Please Note** : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

LRS Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

PA/08/0055/2020/NS

## Supplementary Estimate 1

GST Reg No. 19-9902271-W

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept  
Tel: 6841 0055 - Fax: 6256 4315

**Estimate No.**

**Date**

**Service Advisor**

**Pages**

**Regn No**

**Model No**

31-Jan-20

Glory Tan

1 of 1

SL5 4925 Y

Audi A1 SB 1.0 TFSI S TRO

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Parts

1	Bonnet inner top cover LHS <i>cr</i>	\$ 30.00	23.92
2	Holder for filler pipe <i>dis</i>	\$ 27.00	21.60
3	Flat contact housing with contact locking mechanism <i>cr</i>	\$ 30.00	23.36
4	Flat contact housing <i>cr</i>	\$ 24.00	19.04
5	Radiator coolant hose(Flange>coolant radiator) <i>cut</i>	\$ 99.00	<del>X</del> <i>nn</i>
6	Radiator coolant hose <i>dis?</i>	\$ 61.00	<del>✓</del> 48.72 <i>dis ✓</i>
7	Spring band clamp <del>X</del>	\$ 19.00	<del>X</del> <i>nn</i>
8	Mechatronic with software <i>bt</i>	\$ 3,804.00	3043.20
9	Socket head bolt with inner <i>re</i>	\$ 27.00	21.12
10	Round head screw <i>re</i>	\$ 9.00	6.72
11	Transmission fluid <i>re</i>	\$ 119.00	95.04
12	Coolant Pipe <i>dis</i>	\$ 29.00	22.56
		<u>\$ 4,278.00</u>	

Labour

1	To remove and renew mechatronic with software S/N	\$ 980.00	
---	---	-----------	--

**TOTAL**

\$ 5,258.00

For Premium Automobiles Pte Ltd

\_\_\_\_\_  
Authorised Signature

*(Supp 5178, check - \$61/-)*

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

## Supplementary Estimate 1

GST Reg No: 19-9902271-W

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Attn: Mr. Adrian Ling - Motor Claims Dept  
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/00/0055/2020/NS  
Date 3-Feb-20  
Service Advisor Raymond Ting  
Pages 1 of 1  
Regn No ~~SLS 4925 Y~~ **SLS 4295 Y**  
Model No Audi A1 5B 1.0 TFSI S TRO

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Refrigerant line ✓ Bt	\$ 455.00	398.80
		<u>\$ 455.00</u>	
<b>TOTAL</b>		<u>\$ 455.00</u>	

For Premium Automobiles Pte Ltd

\_\_\_\_\_  
Authorised Signature

As a Repairer/Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: