

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nadaraja, Deeban

Date: 24 Feb 2020

Preliminary Advice

Vehicle No	: SLS4295Y	Accident Date	: 12/01/2020
Make	: AUDI A1	Policy No.	: 1700052489
Assignment Date	: 15/01/2020	Excess	: S\$600.00
Date of Inspection	: 14/01/2020	Est. Duration of Repair	: 19 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	88,931.00 (inclusive supp 1 + 2)
Revised Amount	:S\$	50,257.00 (inclusive supp 1 + 2)
Check Items (Estimated)	:S\$	23,033.00 (inclusive supp 1)
Total	:S\$	73,290.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	130,000.00
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	39,294.00
Salvage Value	:S\$	
Margin for Repair (New for old)	:S\$	90,706.00
Margin for Repair	:S\$	28,706.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Amount of supplementary 1 is \$ 5,178.00, check item is \$ 61. Amount of Supplementary 2 is \$ 455.00.