

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD6566D

DATE: 14. Jan. 2020

MAKE : HYUNDAI

MODEL : IONIQ

DOA: 14. Jan. 2020

CHINA

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|-----|--|------|------------|------------|
| 1 | Front Bumper Cover (G3) xxxx x(R) | | | \$418.30 |
| 1 | Front Bumper Bracket - LH xmm | | | \$28.00 |
| | Front Bumper Top Bracket - LH xmm | | | \$12.00 |
| 10 | Front Bumper Clips xxxx xmm | | \$2.20 | \$22.00 |
| 1 | Front Fender - LH x(R) | | | \$490.70 |
| 1 | Front Bumper Side Grille - LH xmm | | | \$186.60 |
| 1 | Headlamp - LH x(R) | | | \$2,110.30 |

SUB TOTAL

\$3,267.90

LESS 20%

\$653.58

DISCOUNTED TOTAL

\$2,614.32

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour Charge

- 1 Panel Beating
- 1 Spray Painting Charge
- 1 Wiring Charge
- 1 Tuff Kote

TOTAL LABOUR

\$700.00 \$640

\$500.00 \$400

\$80.00 \$50

\$80.00 \$30

ESTIMATE TOTAL

\$1,360.00

\$3,974.32

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Larry Ng

ROM (LKK)

14/1/2020

1515hrs

Pave Suran@lkkauto.com

88622728

(3 repair days)

(P/P)

aft repair photo