



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC2005248  
INV Date 28/07/2020  
Reference CC3/CTI20000964/Fea3n2  
Code CTI



### PROFESSIONAL SERVICE FEE

Vehicle No. SH 6105A  
Insured Veh. SKP 4652C  
Claim No. SNM20D200405C02  
Policy No. DMPCSN3062551900  
Accident Date 09/01/2020  
Inspection Date 14/01/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI20000964/Fea3n2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 28-07-2020



Code : CTI

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKP 4652C	Veh. Inspected	SH 6105A
Policy No.	DMPCSN3062551900	Coverage (\$)	0.00
Claim No.	SNM20D200405C02	Excess (\$)	0.00
Assign From		Assign Date	14/01/2020

#### 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KMHLB41UMGU080271	Colour	BLUE
Odometer	674393	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R16	WEST LAKE	7 mm
L/H Front Tyre	205/65 R16	WEST LAKE	7 mm
R/H Rear Tyre	205/65 R16	WEST LAKE	7 mm
L/H Rear Tyre	205/65 R16	WEST LAKE	7 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT AND FRONT PORTION.

DAMAGES SEE DETAILS

#### 5. General Information

Accident Date	09/01/2020	Inspection Date	14/01/2020
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

#### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6105A**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BUMPER W LIP & FOG	CRACKED	1,052.20	1,052.20
1	BRKT ASSY-FR BPR UP	NOT NECESSARY	22.40	-
1	BRACKET -FR BUMPER S	NOT NECESSARY	24.60	-
10	HYUNDAI BUMPER COVER CLIP	NECESSARY	22.00	22.00
1	GRILLE ASSY -RADIATO	SCRATCHED	1,110.10	1,110.10
1	LAMP ASSY -HEAD LH	SCRATCHED	693.80	693.80
1	PANEL FENDER LH	DENTED	663.00	663.00
	LESS 20% DISCOUNT		-717.62	-708.22
			2,870.48	2,832.88
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRT FENDER ADVERTISEMENT LOGO LH (SN)	NECESSARY	100.00	100.00
			100.00	100.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		600.00	560.00
	SPRAYPAINT ON AFFECTED AREA.		450.00	400.00
	CHECK ALL LIGHTING.		50.00	50.00
	TUFF COAT ON AFFECTED PARTS.		50.00	30.00
			1,150.00	1,040.00
<b>GRAND TOTAL</b>			<b>4,120.48</b>	<b>3,972.88</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,150.00</b>

Report Ref No. CC3/CTI20000964/Fea3n2

**PARASURAM S/O SHANMUGAM**

Asst. Automotive Assessor

**HO LEONG CHUAN**

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.