

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

No spare parts

DATE: 10/1/2020

MODEL: HYUNDAI IONIQ

INSURANCE: India LKK

VEHICLE NO.: SHD4438D

MVA: _____

PART NO.	Description	Qty	List Price	Amount	
	Bonnet <i>Dental</i>			\$ 2,253.80	✓
	Bonnet Rubber (LH) <i>NH</i>			\$ 12.40	X
	Bonnet Rubber (RH) <i>NH</i>			\$ 12.40	X
	Bonnet Hinge (LH) <i>KT</i>		\$118.70	\$ 118.70	✓
	Bonnet Lock <i>NH</i>			\$ 127.30	X
	Bonnet Absorber <i>NH</i>			\$ 35.70	X
	Bonnet Seal <i>NH</i>			\$ 38.30	X
	Bonnet Insulator Clips <i>NH</i>			\$ 8.40	X
	Radiator Grille <i>Cut</i>			\$ 1,227.50	✓
	Unit Assy-SMART CRU (Radar Sensor) <i>NH</i>			\$ 2,910.90	X
	Antenna Assy-SMARTK (LH) <i>NH</i>			\$ 689.50	X
	Assy BSD Blind Spot Radar (LH) <i>NH</i>			\$ 758.50	X
	Wiring Harness BWS Ext <i>NH</i>			\$ 988.90	X
	Front Bumper Cover <i>turn</i>			\$ 418.30	✓
	Front Bumper Sponge/Absorber <i>2 torn</i>			\$ 86.90	✓
	Front Bumper Reinforcement <i>2 NH</i>			\$ 1,075.10	X
	Front Bumper Grille (LH) <i>Cut</i>			\$ 186.90	✓
	Front Bumper Moulding Centre Upper (LH) <i>Cut</i>			\$ 108.50	✓
	Front Bumper Lower Stiffener <i>2 NH</i>			\$ 85.10	X
	Front Bumper Lip <i>NH</i>			\$ 35.10	X
	Front Bumper Bracket Top (LH) <i>NH</i>			\$ 35.00	X
	Front Bumper Bracket (LH) <i>broken</i>			\$ 28.00	✓
	Front Bumper Side Bracket Support <i>NH</i>			\$ 12.00	X
	Front Bumper Clips 10 pcs <i>NH</i>			\$ 22.20	✓
	Front Bumper Strip Assy <i>NH</i>			\$ 29.40	X
	Front Bumper Centre Grille <i>2 1st</i>			\$ 318.80	✓
	Headlamp Support Panel Assy <i>2 broken</i>			\$ 949.30	✓
	Headlamp(LH) <i>broken</i>			\$ 1,198.80	✓
	Headlamp Halogen Bulb (LH) <i>NH</i>			\$ 14.40	X
	Day Light ,LH <i>2 mouldy broken</i>			\$ 642.50	✓
	Day Light Wire, LH <i>NH</i>			\$ 585.50	X
	Radiator Inverter <i>NH</i>			\$ 884.80	X
	Radiator <i>NH</i>			\$ 510.50	X
	Radiator Shroud <i>NH</i>			\$ 275.50	X
	Front Fender(LH) <i>turn/Dental</i>			\$ 490.70	✓
	Front Fender Apron Panel (LH) <i>Dental repair</i>			\$ 756.20	X
	Front Fender Apron Panel Upper(LH) <i>NH</i>			\$ 129.60	X
	Front Fender Shield (LH) <i>dental</i>			\$ 114.70	✓
	Flap Assy Active Air Upper, (LH) <i>NH</i>			\$ 356.00	X

PART NO.	Description	Qty	List Price	Amount	
	Actuator Active Air(LH) <i>NW</i>		\$	257.10	X
	Front Fender Mudflap (LH) <i>NW</i>		\$	85.00	X
	Front Fender Retainer <i>NW</i>		\$	41.40	X
	Aircon Condenser <i>NW</i>		\$	663.60	X
	Front Door Hinge Upper (LH) <i>NW</i>		\$	41.10	X
	Front Door Hinge Lower (LH) <i>NW</i>		\$	41.10	X
	Front Door Check (LH) <i>NW</i>		\$	45.60	X
	Front Door Protector(LH) <i>NW</i>		\$	116.20	X
	Front Wheel Bearing <i>2 Done</i>		\$	454.00	2.1
	Front Shock Absorber(Assy)(LH) <i>2 distal</i>		\$	372.50	2.1
	Front Shock Absorber Mounting (LH) <i>NW</i>		\$	206.90	X
	Front Drive Shaft (LH) <i>NW</i>		\$	936.70	X
	Rack & Pinion Assy <i>1/2 Done</i>		\$	887.40	2.1
	STG Tie Rod <i>2 distal</i>		\$	125.00	2.1
	STG Tie End <i>2 distal</i>		\$	120.00	2.1
	Stabilizer Bar <i>NW</i>		\$	246.80	X
	Stabilizer Bar Bush (LH) <i>NW</i>		\$	22.30	X
	Stabilizer Bar Link <i>NW</i>		\$	92.10	X
	Front Suspension Lower Arm (LH) <i>2 distal</i>		\$	296.80	2.1
	Knuckle Arm (LH) <i>2 distal</i>		\$	363.60	2.1
	Engine Crossmember <i>NW</i>		\$	1,803.90	X
	Wiring-Front <i>2 broken</i>		\$	3,802.10	2.1
	Inverter Assy, w/Convertor <i>NW</i>		\$	5,390.20	X
	Hybrid Spare Tank <i>NW</i>		\$	371.30	X
	Hybrid Cooling Pipe Motor <i>NW</i>		\$	432.20	X
	Hybrid Inverter Bypass Hose-inlet <i>NW</i>		\$	42.60	X
	Hybrid Inverter Bypass Hose-Outlet <i>NW</i>		\$	29.30	X
	Fuse box assy <i>broken NW</i>				2.1
	Boot Lid <i>Done</i>		\$	2,480.40	1
	Boot Lid Rubber <i>NW</i>		\$	127.40	1
	Boot Lid Lock Upper <i>Done</i>		\$	224.00	1
	Boot Lid Key Lock <i>NW</i>		\$	141.00	X
	Boot Lid 'H' Emblem <i>NW</i>		\$	28.00	1
	Emblem-Hybrid <i>NW</i>		\$	24.30	1
	Emblem-Ioniq <i>NW</i>		\$	31.30	1
	ASSY BSD-Blind Spot Radar <i>2 Done</i>		\$	758.50	1
	Wiring Harness BWS Ext <i>1/2</i>		\$	988.90	1
	Rear Spoiler <i>NW</i>		\$	665.40	X
	Boot Lid Trimboard <i>NW</i>		\$	159.70	X
	Boot Lid Trimboard Clips (10pcs) <i>NW</i>		\$	11.00	X
	Boot Lid Trimboard, Centre <i>NW</i>		\$	69.60	X
	Rear Bumper <i>1/2</i>		\$	459.40	1
	Rear Bumper Reinforcement <i>broken</i>		\$	294.80	1
	Rear Bumper Reinforcement Bracket (LH) <i>2/2</i>		\$	138.10	1
	Rear Bumper Centre Moulding Assy <i>1/2</i>		\$	451.25	1
	Rear Bumper Lower Centre Moulding Assy <i>mostly work</i>		\$	47.50	1
	Rear Bumper Stay <i>NW</i>		\$	138.10	X

PART NO.	Description	Qty	List Price	Amount	
	Rear Bumper Side Bracket (LH) NW			\$ 33.10	X
	Rear Bumper Cover Clips Nec			\$ 22.00	✓
	Rear Bumper Side Under(LH) minority broken			\$ 27.50	✓
	Rear Bumper Reflector Lamp(LH) dislodged / broken			\$ 31.90	✓
	Rear Bumper Fog Lamp Socket broken NW			\$ 201.50	X
	Rear Bumper Towing Cover dislodged			\$ 98.80	✓
	Rear Bumper Reserve Light (Parking Brake Light) Socket broken			\$ 257.10	✓
	Rear Bumper Reverse Sensor Broken NW			\$ 1.00	XXXX
	Tail Lamp(LH) minority cable			\$ 870.40	✓
	Tail Lamp Quarter Panel(LH) NW			\$ 208.90	X
	Rear Fog Lamp NW			\$ 201.50	X
	Rear Bumper Reflector Lamp(LH) dislodged / broken			\$ 31.90	✓
	Rear Panel Dislodged			\$ 532.00	✓
	Rear Panel Lower Panel NW			\$ 39.40	X
	Spare Tyre Flip Board NW			\$ 338.80	X
	Exhaust Pipe Insulator NW			\$ 35.00	X
	Exhaust Pipe Hanger NW			\$ 29.20	X
	Rear Fender(LH) Removal			\$ 1,768.30	X
	Flap Assy-Active Air UPR (LH) NW			\$ 356.00	X
	Actuator-Active Air(LH) NW			\$ 257.10	X
	Rear Windscreen Moulding Nec			\$ 28.20	✓
	Rear Wheelbearing ING & Hub Not Done			\$ 454.00	X
	Rear Trailing Arm(LH) Not dislodged			\$ 121.00	X
	Rear Assist (LH) Not dislodged			\$ 92.80	X
	Rear shock Absorber(LH) Not dislodged			\$ 230.50	X
	Rear Shock Absorber Mounting (LH) NW			\$ 61.40	X
	Rear Crossmember Not dislodged			\$ 756.40	X
	Stabilizer Bar Not dislodged			\$ 224.00	X
	Stabilizer Link NW			\$ 92.10	X
	Rear Upper Arm(LH) Not dislodged			\$ 112.20	X
	Rear Lower Arm(LH) Not dislodged			\$ 393.10	X
	Rear Knuckle Arm (LH) Not dislodged			\$ 386.90	X
	SUB TOTAL			\$ 51,351.55	
	LESS 20%			\$ 10,270.31	
	DISCOUNTED TOTAL			\$ 41,081.24	
	Boot Lid Comfort Logo & Tel No. Sticker Nec			\$ 30.00	Nett ✓
	Boot Lid Comfort Logo Sticker Nec			\$ 8.60	Nett ✓
	Boot Lid Comfort Cablink Tel No. Sticker Nec			\$ 9.00	Nett ✓
	Boot Lid Advertisement Logo NR			\$ 100.00	Nett X
	Front Door Comfort Logo (LH) NW			\$ 75.00	Nett X
	Emblem-Blue Drive (LH) Nec			\$ 26.60	Nett ✓
	Rear Windscreen Sealant Nec			\$ 46.00	Nett ✓
	Rear Fender Air-Duct NW			\$ 95.00	Nett X
	Rear Fender Mudflap (LH) NW			\$ 80.00	Nett X
	SUB TOTAL			\$ 470.20	

PART NO.	Description	Qty	List Price	Amount
	Labour Charge			
	Panel Beating		\$	2,200.00
	Spray Painting Charge		\$	1,600.00
	Wiring Charge		\$	250.00
	Tuff Kote		\$	180.00
	Towing Charge		\$	60.00
	Remove/Refix Rear Windscreen Glass		\$	120.00
	Remove/Refix Reverse Sensor		\$	120.00
	Remove/Refix Undercarriage(FRT)		\$	400.00
	Remove/Refix Fuel Tank		\$	150.00
	Remove/Refix Exhaust Pipe		\$	150.00
	Remove/Refix Undercarriage(RR)		\$	400.00
	Rear Wheel Alignment		\$	120.00
	Remove/Refix Radiator		\$	90.00
	Remove/Refix Aircon & Refill Gas		\$	150.00
	Remove/Refix Fuse Box		\$	180.00
	Diagnostic & Resetting To Erase Fault Code		\$	480.00
	TOTAL LABOUR		\$	6,650.00
	ESTIMATE TOTAL		\$	48,201.44

1200/-
1800/-
30/-
40/-
24/-
80/-
40/-
150/-
24/-
60/-
250/-
60/-
50/-
80/-
120/-
320/-

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared

14/01/2020 @ 1500hrs
NA Author
L/Sum ¹⁴ days.

J. Man

LKK Auto



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 14-Jan-20

INSURANCE: India

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHD 4438 D SUPPLEMENTARY

Description	Qty	List Price	Amount
Spare Tyre Panel <i>req</i>	1	\$ 892.50	X
SUB TOTAL		\$ 892.50	
LESS 20%		\$ 178.50	
DISCOUNTED TOTAL		\$ 714.00	
Rear Number Plate <i>crack</i> NETT	1	\$ 25.00	✓
Rear No Plate Trim Cover <i>broken</i> NETT	1	\$ 30.00	✓
Rear Bumper Reverse Sensor <i>Down</i> NETT	1	\$ 180.00	✓
TOTAL		\$ 235.00	
ESTIMATE TOTAL		\$949.00	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

I ngn
2Kk Auto
8

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 6-Feb-20

INSURANCE: _____

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHD4438D

Description	Qty	List Price	Amount
Buzzer Assy - PIEZO (LH/RH) <i>Soclat broken n/s o/s n/w</i>	2	\$ 338.00	\$ 676.00
SUB TOTAL			\$ 676.00
LESS 20%			\$ 135.20
DISCOUNTED TOTAL			\$ 540.80
ESTIMATE TOTAL			\$ 540.80
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Jan

2kk Auto

[Signature]