

ASS. REC. BY: Steve

REF: FCI

ASSIGNMENT

From: Date: 16/01/2020

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SFZ 2686A
at Workshop m/s performance Motor
of 303 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Foong shiuh Jye

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 10% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1DS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SFZ 2686A Yr Regn: 13/5/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 1160 C.C. 1496

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 43216 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA1V722X05C07942

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 705/55R16

R: 4

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO/YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 6/1/20 D.O.I. 16/1/20

Survey held at Performance Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MR- 68K

C 11P \$3,265.55 / red \$842.70 / 2.1.)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

Report Format:

Lump Sum / I.E.T. (\$)

☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Weekend (\$)

TOTAL

New Dealer

Performance Motors Limited

A Elm Darty Motors Company
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X
Toll-Free Number: (1800-2255269)

303, Alexandra Road
Elm Darty Performance Centre
Singapore 159941
Fax: 64747770

280, Esplanade Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Elm Darty Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

Survey on 16.01.2020 (Thursday)
Coming in at 3pm



GST REG. NO : M2 - 0020081 - X

09 JAN 2020

ESTIMATE

Estimate No. : b1 54042	Page No. : 1 of 5
Date Estimated : 08/01/2020	
Prepared By : Foong Shiuh Jye	

- ESTIMATE REPAIR FOR -
Tan Chin Kiong
76 Lorong Marican

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 417269

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFZ2686A	WBA1V720X05C07042	13/05/2016	116d	0

DESCRIPTION

To replace bumper front panel and attachments.

850 1,275.00

To spray paint bumper front panel

934 1,038.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

Sundries. *Nu*

80/? 40.00

Total Labour 1: 2,707.00

DESCRIPTION

CLAMP / *MC*
RH CLOSED GRID (BASIS) / *CU*
GRILLE MIDDLE BOTTOM / *X NN*
FRT BUMPER LH INSERT / *X NN*
FRT BUMPER RH INSERT / *X NN*
FRONT BUMPER TOWING COVER PRIMED / *X NN*
FRT BUMPER PANEL PRIMED / *GO*
SET PDC HOLDER FRONT / *MC*
SET PMA HOLDERS FRT/REAR / *X NN*
RH DEFLECTOR LIP / *MC*
(DG/SL) ADHESIVE SET K6 / *MC*

QTY	PRIC	VALUE
1	3.35	3.35
1	88.00	88.00
1	125.70	125.70
1	60.45	60.45
1	60.45	60.45
1	39.15	39.15
1	829.65	829.65
1	25.75	25.75
1	23.25	23.25
1	20.85	20.85
1	53.05	53.05

Total Parts : 1,329.65

37.50

URGENT

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559H GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kaepong Arany Road
East Coast Centre
Singapore 438180
Fax: 63445773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 54042
Date Estimated : 08/01/2020
Prepared By : Foong Shiuh Jye

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFZ2686A	WBA1V720X05C07042	13/05/2016	116d	0

Steve (LKK) WR ML
18/1/20, 300pm
3 days

P/P
Ry Del SK

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	2,707.00
Parts	:	1,329.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	282.57
Grand Total	:	4,319.22

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : b1 54042
Date Estimated : 08/01/2020
Prepared By : Foong Shiuh Jye

- ESTIMATE REPAIR FOR -
Tan Chin Kiong
76 Lorong Marican

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 417269

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFZ2686A	WBA1V720X05C0704	13/05/2016	116d	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments including to remove and install body parts in order to carry out painting job.	850.00	0	850.00 ✓
To respray front bumper.	934.00	0	934.00 ✓
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00	0	150.00 ✓
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00	0	150.00 ✓
Sundries.	80.00	0	80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
CLAMP	3.35	10.00	0	33.50 ✓
RH CLOSED GRID (BASIS)	88.00	1.00	0	88.00 ✓
FRT BUMPER PANEL PRIMED	829.65	1.00	0	829.65 ✓
SET PDC HOLDER FRONT	25.75	1.00	0	25.75 ✓
# PLAQUE 82MM	71.60	1.00	0	71.60 ✓
(DG/SL) ADHESIVE SET K6	53.05	1.00	0	53.05 ✓

(Supp) nec

SUPPLEMENTARY ITEMS

Total Labour : 2,164.00
Total Parts : 1,101.55
Total Labour & Parts : 3,265.55 ✓
GST @7%: 228.59
Grand Total : 3,494.14

LOSS OF USE = \$100 X 1 DAY
CAR RENTAL = \$200.00 (2 DAYS)

URGENT

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : b1 54042
Date Estimated : 08/01/2020
Prepared By : Foong Shiuh Jye

- ESTIMATE REPAIR FOR -
Tan Chin Kiong
76 Lorong Marican

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 417269

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFZ2686A	WBA1V720X05C0704	13/05/2016	116d	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# PLAQUE 82MM / REC	71.60	1.00	0	71.60

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	71.60
Total Labour & Parts :	71.60