

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 26312

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0052/2020/NS
Date : 14-Jan-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Rajat Nag
Address : 1 Sin Min Walk
#02-40
Singapore 575574
Telephone : (HP) 98204245
Type of Claim : Own Damage Claims
Policy No. : 1900021536
Vehicle No : **SMJ 3816 L**
Model Code : Audi A5 SB 2.0 TFS
Model / Year : 28/2/2019
Engine No : CVK 074456
Chassis No : WAUZZZF55KA015107
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Jan-20
Place of Accident : PIE Towards Tuas Before Dunearn/Clementi Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMJ 3816 L

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	✓
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00	X
3	To renew rear windscreen for rear lid renewal.	S/N \$ 480.00	X
4	To install rear windscreen solar film.	S/N \$ 400.00	X
5	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$ 1,400.00	X
SUB TOTAL LABOUR CHARGES		: \$ 2,920.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMJ 3816 L

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	To dismantle rear bumper and rear lid. Cut out and reweld end panelling outer and inner, lhs bottom plate and connecting plate. Re-organise rear crash management components. Reinstall all parts removed. ✓ ✓	\$ 7,200.00	500 .
7	To respray rear bumper, rear lid, lhs rear fender, spare wheel housing, lhs bottom plate and connecting plate and end panelling. To carry out joint sealer works and stone chip treatment.	\$ 6,700.00	1100 .
8	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00	X
9	To renew lhs rear exhaust silencer and align to position.	S/N \$ 480.00	?
10	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 17,772.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 3816 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER Distorted	\$ 2,311.00	✓
2	REAR BUMPER FIXING PARTS New	\$ 150.00	+
3	REAR BUMPER SECURING STRIP ?	\$ 203.00	?
4	TRIM MOULDING Carved	\$ 928.00	✓
5	REAR LIGHT REFLECTOR - LH Carved	\$ 38.00	✓
6	REAR BUMPER CARRIER ?	\$ 819.00	?
7	REAR BUMPER SEAL ?	2 \$ 25.00	?
8	REAR BUMPER GUIDE SECTION - LH	\$ 40.00	+
9	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 40.00	+,
10	AERIAL RETAINER - LHG 2 bt ✓	\$ 23.00	+
11	TELEPHONE AERIAL New ✓	\$ 164.00	+
12	BOOT LID CONTROL UNIT	\$ 381.00	+
13	VENT TRIM New	\$ 64.00	+
14	REAR PARKING AID SENSOR - INNER / OUTER New	2 \$ 462.00	+
15	REAR PARKING AID SEAL RING New	4 \$ 12.00	+
16	REAR BUMPER WIRING SET New	\$ 618.00	+
17	REAR LID Repair	\$ 2,903.00	+
18	REAR LID ATTACHMENT PARTS New	\$ 139.00	+
19	REAR LID FLAP GASKET New	\$ 218.00	+
20	PACKING ADHESIVE New	\$ 18.00	+

SUB TOTAL SPARE PARTS CHARGES

: \$ 9,556.00

[Signature]

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 3816 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	AUDI EMBLEM	\$ 127.00	✓
22	A5 INSCRIPTION	\$ 87.00	✓
23	REAR WINDSCREEN	\$ 1,062.00	+
24	PRIMER	\$ 19.00	+
25	REAR CROSS PANEL	\$ 329.00	+
26	REAR CROSS PANEL REINFORCEMENT	\$ 577.00	+
27	FLOOR EXTENSION - LH OUTER	\$ 439.00	+
28	REAR CONNECTING PLATE - LH	\$ 51.00	+
29	REAR SILENCER - LH	\$ 813.00	?
30	REAR SILENCER DUAL CLIP	\$ 45.00	?
31	EXHAUST SILENCER BRACKET	\$ 38.00	?
32	EXHAUST TAILPIPES TRIM	\$ 153.00	✓
33	LED TAIL LIGHT - LH OUTER	\$ 1,044.00	+
34	TAIL LIGHT TRIM - LH OUTER	\$ 27.00	+
35	LED TAIL LIGHT - LH INNER	\$ 931.00	+
36	TAIL LIGHT TRIM - LH INNER	\$ 27.00	+
37	REAR SILENCER HEAT SHIELD - LH	\$ 139.00	?
38	HEAT SHIELD - CENTRE	\$ 62.00	+
39	REAR ALUMINIUM RIM - LH	\$ 943.00	+
40	REAR NO PLATE	\$ 40.00	+
SUB TOTAL SPARE PARTS CHARGES		: \$ 6,953.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 3816 L

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
41	REAR WINDSCREEN SEALANT <i>Not in</i>	S/N	\$ 200.00	<i>+</i>
42	ACRYLIC SEALANT <i>Not in</i>	S/N	\$ 180.00	<i>+</i>
43	CAVITY WAX <i>Not in</i>	S/N	\$ 140.00	<i>+</i>
44	STONE CHIP <i>Not in</i>	S/N	\$ 180.00	<i>+</i>
45	SUNDRIES		\$ 400.00	

TOTAL SPARE PARTS CHARGES : \$ 17,609.00

TOTAL LABOUR CHARGES : \$ 17,772.00

GRAND TOTAL : \$ 35,381.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 15/01/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 26312

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0052/2020/NS
Date : 14-Jan-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

*5 days exclude 1 Sunday - ok
jb 9 Mar 20*

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Rajat Nag
Address : 1 Sin Min Walk
#02-40
Singapore 575574
Telephone : (HP) 98204245
Type of Claim : Own Damage Claims
Policy No. : 1900021536
Vehicle No : **SMJ 3816 L**
Model Code : Audi A5 SB 2.0 TFS
Model / Year : 28/2/2019
Engine No : CVK 074456
Chassis No : WAUZZZF55KA015107
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Jan-20
Place of Accident : PIE Towards Tuas Before Dunearn/Clementi Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMJ 3816 L

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$	360.00	\$ 360.00
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$	280.00	
3	To renew rear windscreen for rear lid renewal.	S/N \$	480.00	
4	To install rear windscreen solar film.	S/N \$	400.00	
5	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$	1,400.00	
SUB TOTAL LABOUR CHARGES		:	<u>\$ 2,920.00</u>	<u>\$ 360.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMJ 3816 L

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
	<i>c/f</i>		\$ 360.00
6	To dismantle rear bumper and rear lid. Cut out and reweld end panelling outer and inner, lhs bottom plate and connecting plate. Re-organise rear crash management components. Reinstall all parts removed.	\$ 7,200.00	\$ 500.00
7	To respray rear bumper, rear lid, lhs rear fender, spare wheel housing, lhs bottom plate and connecting plate and end panelling. To carry out joint sealer works and stone chip treatment.	\$ 6,700.00	\$ 1,100.00
8	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00	
9	To renew lhs rear exhaust silencer and align to position. <i>(Repair and align, replace chrome)</i>	S/N \$ 480.00	\$ 280.00
10	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 17,772.00	\$ 2,432.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 3816 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER	\$ 2,311.00	\$ 1,848.80
2	REAR BUMPER FIXING PARTS	\$ 150.00	
3	REAR BUMPER SECURING STRIP	\$ 203.00	\$ 162.40
4	TRIM MOULDING	\$ 928.00	\$ 742.40
5	REAR LIGHT REFLECTOR - LH	\$ 38.00	\$ 29.68
6	REAR BUMPER CARRIER	\$ 819.00	
7	REAR BUMPER SEAL	2 \$ 25.00	
8	REAR BUMPER GUIDE SECTION - LH	\$ 40.00	
9	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 40.00	
10	AERIAL RETAINER - LHG	\$ 23.00	\$ 18.08
11	TELEPHONE AERIAL	\$ 164.00	\$ 130.80
12	BOOT LID CONTROL UNIT	\$ 381.00	
13	VENT TRIM	\$ 64.00	
14	REAR PARKING AID SENSOR - INNER / OUTER	2 \$ 462.00	
15	REAR PARKING AID SEAL RING	4 \$ 12.00	
16	REAR BUMPER WIRING SET	\$ 618.00	
17	REAR LID	\$ 2,903.00	
18	REAR LID ATTACHMENT PARTS	\$ 139.00	
19	REAR LID FLAP GASKET	\$ 218.00	
20	PACKING ADHESIVE	\$ 18.00	\$ 13.92
SUB TOTAL SPARE PARTS CHARGES		: \$ 9,556.00	\$ 2,946.08

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 3816 L

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remarks
		c/f		\$ 2,946.08
21	AUDI EMBLEM	\$	127.00	\$ 101.60
22	A5 INSCRIPTION	\$	87.00	\$ 69.28
23	REAR WINDSCREEN	\$	1,062.00	
24	PRIMER	\$	19.00	
25	REAR CROSS PANEL	\$	329.00	
26	REAR CROSS PANEL REINFORCEMENT	\$	577.00	
27	FLOOR EXTENSION - LH OUTER	\$	439.00	
28	REAR CONNECTING PLATE - LH	\$	51.00	
29	REAR SILENCER - LH	\$	813.00	
30	REAR SILENCER DUAL CLIP	\$	45.00	
31	EXHAUST SILENCER BRACKET	\$	38.00	
32	EXHAUST TAILPIPES TRIM	\$	153.00	\$ 122.40
33	LED TAIL LIGHT - LH OUTER	\$	1,044.00	
34	TAIL LIGHT TRIM - LH OUTER	\$	27.00	
35	LED TAIL LIGHT - LH INNER	\$	931.00	
36	TAIL LIGHT TRIM - LH INNER	\$	27.00	
37	REAR SILENCER HEAT SHIELD - LH	\$	139.00	
38	HEAT SHIELD - CENTRE	\$	62.00	
39	REAR ALUMINIUM RIM - LH	\$	943.00	
40	REAR NO PLATE	S/N \$	40.00	
SUB TOTAL SPARE PARTS CHARGES		:	\$ 6,953.00	\$ 3,239.36

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 3816 L

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remarks
				\$ 3,239.36
41	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	
42	ACRYLIC SEALANT	S/N	\$ 180.00	
43	CAVITY WAX	S/N	\$ 140.00	
44	STONE CHIP	S/N	\$ 180.00	
45	SUNDRIES		\$ 400.00	\$ 1.60
TOTAL SPARE PARTS CHARGES			\$ 17,609.00	\$ 3,240.96
TOTAL LABOUR CHARGES			\$ 17,772.00	\$ 2,432.00
GRAND TOTAL			\$ 35,381.00	\$ 5,672.96

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant