

ASSIGNMENT

menmen

From:

Date:

15/01/2020

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SME 8661J

at Workshop m/s

Premium

of

55 ubi Road 1

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

BAE 007
waived.

(Client's Record)


Make of Veh:

11am

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

96.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SME 8661J

Yr Regn:

2018 / Oct

Type:

M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A3

C.C

1395

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

23633

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAU22Z8V7J1080892

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

Inorder / Jammed / Leaked / Burnt or

Brake:

Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / ☒ Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

205/55R16

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

15/01/20

Survey held at

Premium

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Front n/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
00ALG.	16/1 - Revert via menmen
SME 8661J	16/1 - 14:51 - Authorise repair by victor koh
	16/1 - 3:23pm - inform premium authorise repair
MV: 96K.	excess \$0
PV: 46.5K	
Nett: 49.5K	
	Part by Part \$1602 (Red. 4485 : 73%)

Date/Time, File Pass to?



Preli. Report

1) 13/4 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

\$ + PS. \$

Photos

Others

TOTAL

Report Format:

Lump Sum / L&L

OD

1602

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 25986

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0043/2020/NS
Date	:	13-Jan-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

*Hi Adrian,
3 days - ok - Jy - 30 Mar 20*

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Yazid Bin Ismail
Address	:	37 Loyang Rise Singapore 507564
Telephone	:	HP +65 83454845
Type of Claim	:	Own Damage Claims
Policy No.	:	1800125008
Vehicle No	:	SME 8661 J
Model Code	:	Audi A3 Sedan 1.4 TF
Model / Year	:	Oct-18
Engine No	:	CZE 697822
Chassis No	:	WAUZZZ8V7J1080892
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	10-Jan-20
Place of Accident	:	Jalan Kayu Car Park (J0122)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 8661 J

<u>S/N</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	✓
2	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.		\$ 1,050.00	SSO ✓
3	To respray front bumper.		\$ 900.00	SSO ✓
4	To carry out diagnostic check.	S/N	\$ 192.00	✓ ✓
TOTAL LABOUR CHARGES			: \$ 2,502.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 8661 J

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Regis</i>	\$ 1,830.00	X,
2	FRONT BUMPER FIXING PARTS	\$ 170.00	+
3	FRONT BUMPER GUIDE SECTION - LH <i>2 new</i>	\$ 35.00	+
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 488.00	+
5	FRONT BUMPER CLOSING ELEMENT - LH <i>new</i>	\$ 270.00	+
6	FRONT BUMPER COVER TRIM - LH <i>new</i>	\$ 148.00	+
7	WHEEL HOUSING LINER ADAPTER - LH <i>new</i>	\$ 34.00	+
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	\$ 171.00	+
9	WHEEL HOUSING LINER - LH <i>new</i>	\$ 158.00	+
10	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$ 81.00	+
11	SUNDRIES <i>?</i>	\$ 200.00	+
TOTAL SPARE PARTS CHARGES		: \$ 3,585.00	
TOTAL LABOUR CHARGES		: \$ 2,502.00	
GRAND TOTAL		: \$ 6,087.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 15/01/20
Authorised Date :
Excess Cost :
Liability :
Remarks : XE Authorised, 03 Days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 25986

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0043/2020/NS
Date : 13-Jan-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

*Hi Adrian,
3 days - ok - Jy - 30 Mar 20*

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Yazid Bin Ismail
Address : 37 Loyang Rise
Singapore 507564
Telephone : HP +65 83454845
Type of Claim : Own Damage Claims
Policy No. : 1800125008
Vehicle No : **SME 8661 J**
Model Code : Audi A3 Sedan 1.4 TF
Model / Year : Oct-18
Engine No : CZE 697822
Chassis No : WAUZZZ8V7J1080892
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-Jan-20
Place of Accident : Jalan Kayu Car Park (J0122)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 8661 J

S/N Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	\$ 360.00
2	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00	\$ 500.00
3	To respray front bumper.	\$ 900.00	\$ 550.00
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 2,502.00	\$ 1,602.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 8661 J

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 1,830.00	
2	FRONT BUMPER FIXING PARTS	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - LH	\$ 35.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 488.00	
5	FRONT BUMPER CLOSING ELEMENT - LH	\$ 270.00	
6	FRONT BUMPER COVER TRIM - LH	\$ 148.00	
7	WHEEL HOUSING LINER ADAPTER - LH	\$ 34.00	
8	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 171.00	
9	WHEEL HOUSING LINER - LH	\$ 158.00	
10	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 81.00	
11	SUNDRIES	\$ 200.00	
TOTAL SPARE PARTS CHARGES		\$ 3,585.00	\$ -
TOTAL LABOUR CHARGES		\$ 2,502.00	\$ 1,602.00
GRAND TOTAL		\$ 6,087.00	\$ 1,602.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant