

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pang Xiu Shi

Date: 12 Mar 2020

Preliminary Advice

Vehicle No	: SLE8285Z	Accident Date	: 13/01/2020
Make	: LEXUS ES250	Policy No.	: A80436762QMY
Assignment Date	: 17/01/2020	Excess	: S\$800.00
Date of Inspection	: 16/01/2020	Est. Duration of Repair	: 21 days
Inspection At	: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear & rooftop portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	64,158.10 (inclusive supp)
Revised Amount	:S\$	29,612.41 (inclusive supp)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	29,612.41

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	115,000.00
COE / PARF Rebate	:S\$	74,581.00
Salvage Value	:S\$	
Margin for Repair	:S\$	40,419.00

Remarks

(X) The vehicle is economical for repair. Supplementary amount is \$ 3,214.52.

() The above survey was conducted on a 'without prejudice' basis.