

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SGY3862U

TP/AMK

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 14/01/2020

TP Veh Reg No: GBE4810C

Estimate No: ES2090059/AMK

Date: 16 Jan 2020

Policy No: GA493023/1

Veh Reg No: SGY3862U

Make/Model: TOYOTA WISH 1.8 A

Chassis No: JTDGG20W80J007721

Engine No: 2ZR0A00429

Reg. Date: 24/08/2017

Estimate Repair Cost to Vehicle No :SGY3862U

PAGE:1/3

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 FRONT RH DOOR	1,540.90	1 PC	1,540.90	✓
2 FRONT RH DOOR INNER RUBBER	175.40	1 PC	175.40	X
3 FRONT RH DOOR OUTER CHANNEL	141.07	1 PC	141.07	?
4 FRONT RH DOOR WINDOW GLASS	611.75	1 PC	611.75	✓
5 FRONT RH DOOR WINDOW GLASS REAR GARNISH	99.80	1 PC	99.80	✓
6 FRONT RH DOOR FRAME STICKER	83.12	1 SET	83.12	✓
7 FRONT RH DOOR SIDE MIRROR ASSY	799.87	1 PC	799.87	✓
8 REAR RH DOOR	1,511.79	1 PC	1,511.79	✓
9 REAR RH DOOR TOP HINGE	78.34	1 PC	78.34	X
10 REAR RH DOOR BOTTOM HINGE	78.34	1 PC	78.34	?
11 REAR RH DOOR CHECKER	141.07	1 PC	141.07	?
12 REAR RH DOOR INNER RUBBER	184.06	1 PC	184.06	506.50
13 REAR RH DOOR INNER LOCK	377.80	1 PC	377.80	✓
14 REAR RH DOOR FRAME STICKER	71.07	1 SET	71.07	✓
15 REAR RH DOOR OUTER CHANNEL	156.09	1 PC	156.09	✓
16 REAR RH DOOR POWER WINDOW MOTOR	788.40	1 PC	788.40	✓
17 REAR RH DOOR POWER REGULATOR	191.75	1 PC	191.75	✓
18 REAR RH DOOR STRIKER	39.08	1 PC	39.08	?
19 REAR RH DOOR OUTER GARNISH	66.97	1 PC	66.97	✓
20 REAR RH DOOR INNER TRIM BOARD	1,221.75	1 PC	1,221.75	?
21 REAR RH DOOR SPEAKER	299.80	1 PC	299.80	?
22 REAR RH DOOR STEP GARNISH	211.67	1 PC	211.67	?
23 REAR RH DOOR INNER RUBBER (FRAME)	397.60	1 PC	397.60	?
24 REAR RH DOOR AIRBAG SENSOR	402.90	1 PC	402.90	✓
25 RH SIDE SKIRT	1,377.80	1 PC	1,377.80	✓
26 RH CENTRE PILLAR	394.76	1 PC	394.76	?
27 REAR RH FENDER	921.60	1 PC	921.60	✓
28 REAR RH FENDER GLASS MOULDING	175.20	1 SET	175.20	✓
29 REAR BUMPER	551.95	1 PC	551.95	✓
30 REAR BUMPER SIDE RETAINER	87.54	2 PC	175.08	✓
31 REAR BUMPER CORNAL RETAINER	61.67	2 PC	123.34	✓
32 REAR BUMPER PARKING SENSOR	350.00	1 SET	350.00	✓
33 REAR BUMPER CLIP	3.89	5 PC	19.45	✓
34 REAR BUMPER RH INNER SHIELD	65.60	1 PC	65.60	✓
35 TAILGATE LOGO	66.86	1 PC	66.86	✓
36 TAILGATE EMBLEM 'VALVEMATIC'	51.40	1 PC	51.40	✓
37 FRONT WINDSCREEN GLASS	1,640.90	1 PC	1,640.90	✓
38 FRONT WINDSCREEN GLASS MOULDING	107.40	1 PC	107.40	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department
 WS Ref: TP/AIG/AMK
 Claim Type: Third Party
 Accident Date: 14/01/2020
 TP Veh Reg No: GBE4810C

Estimate No: ES2090059/AMK
 Date: 16 Jan 2020
 Policy No: GA493023/1
 Veh Reg No: SGY3862U
 Make/Model: TOYOTA WISH 1.8 A
 Chassis No: JTDGG20W80J007721
 Engine No: 2ZR0A00429
 Reg. Date: 24/08/2017

Estimate Repair Cost to Vehicle No :SGY3862U

PAGE:2/3

Description	U/Price	Quantity	List Price	Amount
			SS	SS
39 REAR SPORT RIM	1,824.20	2 PC	Red 3,648.40	✓
40 REAR SHOCK ABSORBER	221.65	2 PC	443.30	✓
41 REAR SHOCK ABSORBER SPRINGS	311.60	2 PC	623.20	?
42 REAR TOP MOUNTINGS	140.70	2 PC	281.40	?
43 REAR STOPPERS	33.99	2 PC	67.98	?
44 REAR AXLE ASSY	2,543.00	1 PC	Re 2,543.00	✓
45 REAR AXLE BUSHES	120.60	2 PC	Re 241.20	✓
46 REAR STABILIZER BAR	311.95	1 PC	311.95	?
47 REAR AXLE DAMPER	180.70	1 PC	180.70	?
48 REAR WHEEL HUB ASSY	692.75	1 PC	Re 692.75	✓
49 REAR RH ABS SENSOR WIRE	146.30	1 PC	146.30	?
50 REAR HANDBRAKE CABLE	1,091.10	1 SET	1,091.10	?
51 DASHBOARD ASSY	921.75	1 PC	Ta 921.75	✓
52 PASSENGER AIR BAG	3,990.70	1 PC	Re 3,990.70	✓
53 PASSENGER AIR BAG WIRE	61.70	1 PC	Re 61.70	✓
54 AIR BAG ECU	1,007.00	1 PC	Re 1,007.00	✓
55 STEERING AIRBAG	2,997.40	1 PC	Re 2,997.40	✓
56 STEERING SPIRAL CABLE	754.90	1 PC	Re 754.90	✓
57 AIRBAG SENSOR RH	402.95	1 PC	Re 402.95	✓
58 FRONT SEAT BELT	1,700.40	2 PC	Ta 3,400.80	✓
59 SEAT BELT LOWER CENTRE GARNISH	303.70	1 PC	Re 303.70	✓
60 ROOF LINING	2,957.40	1 PC	Ta 2,957.40	✓
61 RH SIDE CURTAIN AIRBAG	3,003.95	1 PC	Re 3,003.95	✓
62 DASHBOARD CENTRE RADIO CONSOLE	621.70	1 PC	621.70	?
63 FRONT RH WINDSCREEN PILLAR GARNISH	265.40	1 PC	265.40	?
64 REAR LH HEIGHT CONTROL SENSOR	600.79	1 PC	600.79	?
65 REAR MUFFLER	1,087.40	1 PC	Re 1,087.40	✓
66 REAR MUFFLER HEAT SHIELD	125.40	1 PC	125.40	?
67 REAR MUFFLER MID PIPE	3,028.95	1 PC	3,028.95	?
			51,494.90	
		Less 25%	12,873.73	38,621.18
Special Net				
68 FRONT RH DOOR WINDOW GLASS TINTED FILM	90.00	1 PC	Re 90.00	60.00
69 DOOR CHROME MOULDING	360.00	1 SET	Red 360.00	✓
70 REAR RH TYRE	110.00	1 PC	Re 110.00	✓
71 ERP BRACKET	25.00	1 PC	Re 25.00	✓
72 FRONT WINDSCREEN GLASS SEALANT	40.00	1 PC	Re 40.00	✓
73 REAR RH FENDER GLASS SEALANT	40.00	1 PC	Re 40.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
TEL: 64193000 **FAX:** 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 14/01/2020
TP Veh Reg No: GBE4810C

Estimate No: ES2090059/AMK
Date: 16 Jan 2020
Policy No: GA493023/1
Veh Reg No: SGY3862U
Make/Model: TOYOTA WISH 1.8 A
Chassis No: JTDGG20W80J007721
Engine No: 2ZR0A00429
Reg. Date: 24/08/2017

Estimate Repair Cost to Vehicle No :SGY3862U

PAGE:3/3

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			665.00	665.00
Labour				
74 TOWING	100.00	1 LA	100.00	7
75 REMOVE & REFIX REAR RH FENDER GLASS	60.00	1 LA	60.00	✓
76 REMOVE AND REFIX FRONT WINDSCREEN GLASS	120.00	1 LA	120.00	✓
77 REMOVE & REFIX BOTH RH DOORS & ATTACHMENTS,RH SIDE MIRROR,REAR BUMPER,TO CUT,WELD & RENEW REAR RH FENDER,RH CENTRE PILLAR,RH ROCKER PANEL;KNOCKING & REPAIR REAR END PANEL,REAR RH FENDER INNER PANEL & REALIGN THE SAME	1,600.00	1 LA	1,600.00	1400
78 PUTTY & RESPRAY REAR BUMPER,TAILGATE,REAR BOTH FENDERS,RH FENDER INNER PANEL,BOTH RH DOORS & CENTRE PILLAR,RH ROCKER PANEL,RH SIDE MIRROR,REAR END PANEL & ALL AFFECTED AREAS	1,500.00	1 LA	1,500.00	1400
79 REMOVE & REFIX REAR SEAT,CARPETS,GARNISH TO FACILITATE REPAIR	150.00	1 LA	150.00	120
80 REMOVE & REFIX BOTH RH WINDOW GLASSES & RESET CENTRAL LOCKING	120.00	1 LA	120.00	✓
81 TO MOUNT ON CAR-O-LINER,JACK & STRAIGHTEN	250.00	1 LA	250.00	7
82 REMOVE & REFIX ROOF LINING & REALIGN THE SAME	120.00	1 LA	120.00	100
83 REMOVE & REFIX REAR AXLE ASSY,BOTH UNDERCARRIAGE & REALIGN THE SAME	300.00	1 LA	300.00	240
84 REMOVE & REFIX DASHBOARD ASSY & REALIGN THE	250.00	1 LA	250.00	✓
85 REMOVE & REFIX FRT SEAT BELTS,STEERING AIRBAG,PASSENGER AIRBAG,AIRBAG ECU,RH CURTAIN AIRBAG & REALIGN THE SAME	350.00	1 LA	350.00	250
86 RESET & REPROGRAMME FAULT CODE	200.00	1 LA	200.00	180
87 REMOVE & REFIX BOTH REAR RIMS,TYRES,BALANCE & REALIGN THE SAME	50.00	1 LA	50.00	40
88 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
89 RUSTPROOFING	180.00	1 LA	180.00	120
90 REMOVE & REFIX REAR MUFFLER,MID PIPE & REALIGN THE SAME	150.00	1 LA	150.00	120

5,560.00 5,560.00

Total S\$ 44,846.18

Add GST @ 7% 3,139.23

Total Amount Payable S\$ 47,985.41

* SURVEY VEHICLE AT ANJUN MOKIO WORKSHOP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE