



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2201535

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 18/03/2022
Reference CC4/LPC20000997/Kea3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SJJ 1111K
Insured Veh. GBE 1485C
Claim No. 19/20/20/VC05/022912
Policy No. Z19VC05003349
Accident Date 14/01/2020
Inspection Date 15/01/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC20000997/Kea3q2 Date: 18/03/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBE 1485C	Veh. Inspected	SJJ 1111K
	Policy No.	Z19VC05003349	Coverage (\$)	0.00
	Claim No.	19/20/20/VC05/022912	Excess (\$)	0.00
	Assign From	ONG LI LI	Assign Date	15/01/2020
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C180 (A)	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WDD2050402R045041	Colour	METALLIC BLACK
	Odometer	34132 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R17	MICHELIN	7 mm
	L/H Front Tyre	225/50 R17	MICHELIN	7 mm
	R/H Rear Tyre	225/50 R17	MICHELIN	7 mm
	L/H Rear Tyre	225/50 R17	MICHELIN	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/01/2020	Inspection Date	15/01/2020
	Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 1111K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER RH	BENT	985.00	985.00
1	FRONT HEADLAMP RH	CRACKED	3,470.00	3,470.00
1	FRONT BONNET HINGE ACTUATOR LH	ACTIVATED	110.00	110.00
1	FRONT BONNET HINGE ACTUATOR RH	ACTIVATED	110.00	110.00
15	FRONT BUMPER RIVETS @\$8.00 (ORIGINAL) (ADDITIONAL)	NECESSARY	120.00	120.00
1	FRONT BUMPER (ADDITIONAL)	MTG CRACKED	1,670.00	1,670.00
1	BONNET HINGE LH (ADDITIONAL)	DISTORTED	210.00	210.00
1	BONNET HINGE RH (ADDITIONAL)	DISTORTED	210.00	210.00
1	FRONT BUMPER CORNER BRACKET RH (ADDITIONAL)	CRACKED	80.00	80.00
1	FRONT BUMPER SIDE RETAINER RH (ADDITIONAL)	CRACKED	28.00	28.00
	LESS 10% DISCOUNT		-699.30	-699.30
			6,293.70	6,293.70
	<u>LABOUR</u>			
	TO CHECK /CLEAR FAULT CODES.		80.00	80.00
	TO DISMANTLE +RENEW BONNET HINGE ACTUATORS LH & RH +RESET ACTIVE BONNET SYSTEM.		200.00	180.00
	TO REPAIR FRONT BUMPER ,TO DISMANTLE +RENEW ABOVE PARTS.		500.00	450.00
	TO SPRAY PAINT.		600.00	500.00
	TO DISMANTLE +REFIX BONNET IN ORDER TO RENEW BONNET HINGE LH & RH . (ADDITIONAL)	NOT NECESSARY	120.00	-
			1,500.00	1,210.00
	GRAND TOTAL		7,793.70	7,503.70
RECOMMENDED COST OF REPAIRS				7,503.70

Report Ref No. CC4/LPC20000997/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJJ 1111K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJJ 1111K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

