

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No : EST0024241
Chan Khoo Kang Kelvin

Page : 1 of 1
Your ref. : TP-GBE 1485C Lonpac
Job No. : 71205
Our ref. : 20.01.17
Payment :
Date : 15/1/2020

Attn :

Vehicle No : SJJ 1111K
Vehicle Model : Mercedes Benz C180
Accident on : 14/1/2020

Not Authorized

Resurvey B4 pain

4 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
1.00	Pc	Front fender RH	985.00	10.00	886.50 <i>Bu</i>
1.00	Pc	Front headlamp RH	<i>CM</i> 3,470.00	10.00	3,123.00
1.00	Pc	Front bonnet hinge actuator LH	110.00	10.00	99.00
1.00	Pc	Front bonnet hinge actuator RH	110.00	10.00	99.00
Labour & Misc:					
1.00		To check/clear fault codes	80.00		80.00
1.00		To dismantle + renew bonnet hinge actuators LH & RH + reset active bonnet system	200.00		200.00
1.00		To repair front bumper, to dismantle + renew above parts	500.00		500.00
1.00		To spray paint	600.00		600.00
Sub-Total					5,587.50
GST 7.00%					391.13
Total					5,978.63

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."