

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0024241
Chan Khoo Kang Kelvin

Page: 1 of 1
Your ref.: TP-GBE 1485C Lonpac
Job No.: 71205
Our ref.: 20.01.17
Payment
Date: 15/1/2020

Attn

Vehicle No: SJJ 1111K
Vehicle Model : Mercedes Benz C180
Accident on ...: 14/1/2020

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
1.00	Pc	Front fender RH	<i>Ry</i> 985.00	10.00	886.50 ✓
1.00	Pc	Front headlamp RH	<i>CM</i> 3,470.00	10.00	3,123.00 ✓
1.00	Pc	Front bonnet hinge actuator LH	<i>Act</i> 110.00	10.00	99.00 ✓
1.00	Pc	Front bonnet hinge actuator RH	<i>Act</i> 110.00	10.00	99.00 ✓
Labour & Misc:					
1.00		To check/clear fault codes	80.00		80.00 ✓
1.00		To dismantle + renew bonnet hinge actuators LH & RH + reset active bonnet system	200.00		200.00 180
1.00		To repair front bumper, to dismantle + renew above parts	500.00		500.00 450
1.00		To spray paint	600.00		600.00 500
Sub-Total					5,587.50
GST 7.00%					391.13
Total					S\$ 5,978.63

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267

GST No: M2-0128609-3

UEN: 199407592C

SUPPLEMENTARY ESTIMATE


EST. No : EST0024241
Chan Khoo Kang Kelvin

Page : 1 of 1
Your ref. : TP-GBE 1485C Lonpac
Job No. : 71205
Our ref. : 20.01.17
Payment :
Date : 17/1/2020

Attn :

Vehicle No : SJJ 1111K
Vehicle Model : Mercedes Benz C180
Accident on : 14/1/2020

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
SUPPLEMENTARY ITEM:					
15.00	Pcs	Front bumper rivets (Original)	8.00	10.00	108.00
1.00	Pc	Front bumper	1,670.00	10.00	1,503.00
1.00	Pc	Bonnet hinge LH	210.00	10.00	189.00
1.00	Pc	Bonnet hinge RH	210.00	10.00	189.00
1.00	Pc	Front bumper corner bracket RH	80.00	10.00	72.00
1.00	Pc	Front bumper side retainer RH	28.00	10.00	25.20
Labour & Misc:					
1.00		To dismantle + refix bonnet in order to renew bonnet hinge LH & RH	120.00		120.00



Sub-Total 2,206.20
GST 7.00% 154.43
Total S\$ 2,360.63

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."