

ASS. REC. BY:

REF: CS31/ALG 2000/005/Fsf302

Special Instruction:

Surveyor: Rom

ASSIGNMENT (Office)

From (Person): Winnie Pan

of

ALG

Date/Time: 16.1.2020 12:57p.m

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JRR 3703

Insured:

SJZ 973L

at Workshop m/s

Equator Brotherhood

Tel:

63846939 / 90113391

of

25 Kaki Bukit Road 4 #03-79 Synergy

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 5.1.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 16.1.2020 1:15pm

Person Contacted:

Elton

Vehicle IN / OUT

H.O.D. Endorsement:

Date/Time

Action/Instruction (X) Estimate

JRR 3703- X

SJZ 973L - (CS31/ALG 2000/005/Fsf302)

D.O.A. - 05/01/2020

14:56pm

27/02/20

@ checked with Willie, no estimate.

ASSIGNMENT

From: PRM Date: 14/08/2016
 Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: JRR 3703
 at Workshop in/s: Equator Brotherhood
 of 25 Kaki Bukit rd A # 03-79

Insured:

Policy No.

Claims No.

Sum Insured

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value:

IDAC Accident Rpt Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: JRR 3703 Regn: 14/08/2016
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Yamaha Y15ZR CC: 150

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: -

C/No: PMYUG0510600286A9

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70/80 R17 maxxis

R: 110/70 R17 maxxis

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 05/1/2020 D.O.I. 16/1/2020

Survey held at Equator Brotherhood

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt & O/S Frt & Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

DAR: completed
 NO. OF DAYS: 4 days

AG

MV: Rm 7700

convert to sg

\$2655.17

RECEIVED 20 FEB 2020

Date/Time: File Pass to:

28/02/20

By: Typist

Date/Time: File Return to:



: Preli. Report



: Final Report

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. fee (\$)



Final report

Survey Fee:

Transportation:

SARS (\$)

Phone:

Other:

180

11

191

PRS

Summer Lee (LKK Auto)

From: Fan, Winnie-LW <Winnie-LW.Fan@aig.com>
Sent: Thursday, 16 January, 2020 12:57 PM
To: Admin A; assignments
Cc: Fong, Andy-SY
Subject: Aigencypt RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJZ 973L AND JRR 3703 ON 05/01/2020
Attachments: 16012020094323.pdf

Hi LKK,

Kindly assist to survey, vehicle in.

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Hui Ling <riaz@justice.com.sg>
Sent: Thursday, January 16, 2020 10:44 AM
To: Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>
Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJZ 973L AND JRR 3703 ON 05/01/2020

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE

Dear sirs,

We refer to your fax on even date.

On behalf of our client, we disagree your list of surveyor.

Please choose one out of the surveyor from the list below:-

1. Chang Fuh Keong, Dave
2. Ho Joo Loong, Danny

3. Dennis Yap Teck Wee
4. Michael Yap
5. Lee Kok Weng
6. Winson Goh
7. Ong Ah Keng, Kent
8. Ong Poh Meng
9. Seah Kwang Boon
10. Thor Teck Soon, David

Thanks & Best Regards,

Hwiling

RIAZ LLC

Advocates and Solicitors

133 NEW BRIDGE ROAD

09-09 CHINATOWN POINT

SINGAPORE 059413

TEL : 6534-0110 FAX : 6534-0220

Disclaimer: This message is privileged and confidential and is intended solely for the named recipient. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is strictly prohibited. If this e-mail has reached you in error, please delete the e-mail immediately and inform us of the error by sending an e-mail to riaz@justice.com.sg. though internet communications cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost or infected with viruses, we have scanned this message to minimise the possibility of corruption.


RIA Z
L.L.C.
ADVOCATES AND SOLICITORS
COMMISSIONER FOR OATHS

ACRA NUMBER : 200911678H

GST REGISTRATION NUMBER : 200911678H

16/01/20/2

Our Ref: JRR 3703 (V) EQUATOR

Your Ref: SJZ 973L

RIAZ QAYYUM (LLB HONS) NUS

DIRECTOR

ABDUL HALIM BIN ROSALAN (LLB HONS) LITAS

ASSOCIATE

MUHD RIDHWAN ABDUL RAHIM (LLB HONS) LEEDS

ASSOCIATE

TO: AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
Tower 2 #07-16
Singapore 079120
Attn: Motor Claims Department

BY FAX (6415-3727) ONLY

NOTICE OF ACCIDENT

Dear Sirs,

We are instructed by our client to *notify* you of a road traffic accident on 05 January 2020 at about 1340 hours along Ghim Moh Road involving our client's vehicle registration number JRR 3703 and vehicle registration number SJZ 973L driven by you or your authorized driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:


Name of workshop : EQUATOR BROTHERHOOD

Address : 25 KAKI BUKIT ROAD 4
#03-79 SYNERGY @ KB
SINGAPORE 417800

Telephone no. : 6384 6939/9011 3391 (Wille)

Please let us hear from you by the stipulated time.

Yours faithfully



cc Client

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor
(Name & signature)

Date & time of inspection



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

HXZBQEHL

No. Pendaftaran : JRR3703
No. ID : 911014016263
Nama Pemunya Berdaftar : CHEN LI CHAO
Alamat : NO 1431 JALAN SRI PUTRI 4/4 TAMAN SRI PUTRI
KULAIJAYA
81000 KULAI JOHOR
No. Chasis/No. Enjin : PMYUG0510B0028649 / 63D3E-027840
Buatan/Nama Model : YAMAHA / YAMAHA Y15ZR
Keupayaan Enjin : 150
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Keles Kegunaan : MOTOSIKAL
Jenis Badan/Tahun Dibuat : MOTOSIKAL / 2016
Tarikh Pendaftaran : 14/08/2016
B. D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -

Kon Tar

0509245

NOTA PENTING

Semak butir-butir kenderaan di muka ini dan laporkan dengan segera kepada Pengerah IPJ jika terdapat sebarang perubahan. Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran milikan telah disempurnakan dan kenderaan telah didaftarkan dengan nama pemilik baru.



Yamaha Y15ZR 2016 Biru



Penang

RM 7,700 NEGOTIABLE PRICE

CONTACT SELLER



Brand	Yamaha	Model	Y15ZR
Type	Moped	Year	2016
Color	Blue	Engine	150 Cc
Gearbox	Manual	Kilometers	16000 Km
Engine Type	Petrol	Warranty	0 Year(S)

Description

Motor STANDARD ingin dilepaskan. Condition marvelous. Reason jual, kembali kepada scooter. Serious buyer only. Saya 1st owner dan tiada hutang.

Mirul

Related Products

 2016 Honda RS 150 Fuel RM 7,780 Johor	 2016 2016 - Honda RS 150 RM 7,980 Inhor	 2016 Honda PCX RM 8,500 Penang	 2016 2016 - Honda RS 150 RM 7,980 Inhor	 2016 2016 - Honda RS 150 RM 7,980 Inhor	 2016 2016 - Honda RS 150 RM 7,980 Inhor
 Yamaha Y15ZR 2016 Biru RM 7,700 Panana	 2016 2016 - Yamaha Y15 RM 7,880 Inhor	 Motor Yamaha Lc150 RM 7,000 Salangor	 2016 Yamaha Y15ZR Seco RM 6,890 Inhor	 Yamaha Y15ZR RM 7,950 Inhor	 2016 Yamaha Y15ZR Lc150 RM 7,500 Salangor





2016 YAMAHA Y15ZR MOVISTAR USED BIKE BMM

Kapar - Selangor

RM 7,980 FIXED PRICE

CONTACT SELLER

VISIT STORE



Brand	Yamaha	Model	Y15ZR MOVISTAR
Type	Moped	Year	2016
Color	Blue	Engine	150 Cc
Gearbox	Manual	Kilometers	0 Km
Engine Type	Petrol	Warranty	0 Year(S)

Description

? SALAM SEJAHTERA SALAM 1 MALAYSIA ?

Model: YAMAHA Y15ZR Movistar

YEAR: 2016

Details of Bike :

- Condition Tip top
- Low milleage
- Cover set original
- Engine standard
- uma racing Exhaust system
- Free Accident
- VIP No. Plate
- Up side down fork
- Winglet



SINGAPORE POLICE FORCE



T/20200108/2158

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20200108/2158

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/01/2020 18:53	Vide Report No.: 9/20200108/0074	Station Diary No.:
--	-------------------------------------	--------------------

Informant's Particulars

Name of Informant: KASSIM BIN HAMZAH			Address: 12 JALAN BUKIT KEMPAS 1/7 TAMAN BUKIT KEMPAS 81200 JOHOR BAHRU JOHOR		
ID Type / ID No.: FIN NO / G0688504M			Contact No.: Home/Office: Mobile: 98978538		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 42	Date of Birth: 29/12/1977	Type of Informant: Driver		
Race: Malay			Language:		Institution / School Name:
Occupation: BUS CAPTAIN			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 05/01/2020 13:40	Type of Location:
Location: Along Road 1 GHIM MOH ROAD ALONG GHIM MOH ROAD AT T-JUNCTION.				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JRR3703	Motorcycle					0
SJZ973L	Car	AUDI	A5 SPORTBAC K 2.0 TFSI QU			0



**SINGAPORE
POLICE FORCE**



T/20200108/2158



2 of 2

Police Station
Traffic Division

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20200108/2158

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	KASSIM BIN HAMZAH	ID No.	G0688504M
Related Vehicle	SJZ973L (Car)	Contact No.	98978538
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE STATED DATE, TIME AND LOCATION,

I WAS RIDING ALONG GHIM MOH ROAD NEAR SINGAPORE POST. THERE WAS VEHICLE RIDING ON THE OPPOSITE TRAFFIC FLOW ON THE TWO-WAY LANE. THE CAR TRIED TO MAKE A RIGHT TURN INTO THE CARPARK FROM GHIM MOH ROAD. I WAS RIDING RATHER SLOWLY. THE DRIVER DID NOT SLOW DOWN AND JUST MADE THE TURN. AS A RESULT, I DID NOT EXPECT A SUDDEN TURN AND THUS, GOT HIT BY THE CAR. I FELL TO THE GROUND AND THE AMBULANCE WAS CONTACTED BY THE PASSER-BY. THE AMBULANCE ARRIVED AND I WAS CONVEYED TO HOSPITAL. THAT'S ALL.

158
2 of 2
T/20200108/2158

**SINGAPORE
POLICE FORCE**



T/20200108/2158

3 of 3

Report No. T/20200108/2158

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
MUHAMMAD AMIRUL M

Signature Of Interpreter:
Not applicable


Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt CHONG GUAN FATT
Contact No . 65476083

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
08/01/2020 18:53

Classification Of Case:



Motorcycle

Vehicle No: JRR 3703

NAC	INC	Item	CON	AC	Qty
3001	991886	Front Number Plate			
3001	995065	Front Tyre			
3002	995095	Front Rim	scr		
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard	cra		
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy	Bt		
3008	991787	Front Fork Inner Tube	rec		
3009	991789	Front Fork Outer Tube	rec		
3010	991167	Front Fork Bracket	Bt		
3011	991182	Front Fork Oil Seal	rec		
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp	scr		
3015	992337	Front Headlamp Bracket	cra		
3016	992345	Front Headlamp Fairing	Br		
3017	992130	Front Windshield			
3018	992134	Front Wing Mirror	Bt		
3019	995245	Front LH Signal Lamp			
3020	995246	Front RH Signal Lamp			
3021	992556	Meter Casing			
3022	992553	Meter Assy	sc		
3023	991019	ERP Bracket			
3024	991020	ERP Unit			
3025	992446	Ignition Switch			
3026	992442	Ignition Key Assy			
3027	990706	Cowling Stay			
3028	994470	Steering Stem	Bt		
3029	994427	Steering Cone	rec		
3030	992299	Handle Bar	Bt		
3031	992312	Handle Bar Switch			
3032	992310	Handle Bar Grip			
3033	995184	Handle Bar Balancer LH			
3034	992300	Handle Bar Balancer RH			
3035	992179	Fuel Tank			
3036	990438	Brake Reservoir			
3037	990621	Clutch Lever	scr		
3038	992293	Hand Brake Lever			
3039	991119	Side Fairing	Br		
3040	994220	Side Fairing Top Garnish			
3041	994219	Side Fairing Inner Garnish			
3042	991118	Fairing Shield	cra		
3043	992047	Front Top Fairing Inner Garnish	Br		
3044	991123	Fairing Top Garnish			
3045	990538	Center Fairing	Br		
3046	993378	Rear Fairing			
3047	991121	Fairing Stopper	rec		
3048	991117	Fairing Lower			

NAC	INC	Item	CON	AC	Qty
3049	995074	Radiator	Bt		
3050	992738	Radiator Cowling	Bt		
3051	994146	Seal Assy			
3052	990915	Engine Crash Bar			
3053	990928	Engine Guard			
3054	990219	Battery			
3055	990224	Battery Cover			
3056	990223	Battery Bracket			
3057	991144	Foot Brake			
3058	991154	Front Foot Rest	scr		
3059	991779	Front Foot Rest Bracket	Bt		
3060	994269	Side Stand	scr		
3061	992549	Main Stand			
3062	990615	Clutch Engine Cover	scr		
3063	992478	Kick Starter Rubber			
3064	992477	Kick Starter Lever			
3065	991145	Foot Gear Shifter	sc		
3066	993500	Rear Foot Rest			
3067	993501	Rear Foot Rest Bracket			
3068	992581	Exhaust Muffler Heat Shield	scr		
3069	991058	Exhaust Muffler Assy	Bt		
3070	993719	Rear LH Shock Absorber			
3071	993720	Rear RH Shock Absorber			
3072	995065	Rear Tyre			
3073	991200	Rear Rim			
3074	994872	Rear Tyre Rim Spoke			
3075	993474	Rear Fender Wheel Guard			
3076	993443	Rear Fender Mudflap			
3077	992940	Rear Brake Disc			
3078	992936	Rear Brake Caliper			
3079	995236	Rear Spocket			
3080	990585	Chain			
3081	990580	Chain Guard			
3082	994530	Swing Arm			
3083	993819	Rear Sub frame			
3084	995245	Rear LH Signal Lamp			
3085	995246	Rear RH Signal Lamp			
3086	995251	Rear Taillamp			
3087	993626	Rear Number Plate			
3088	994192	Side Box			
3089	992927	Rear Box	scr		
3090	992928	Rear Box Bracket	Bt		
3091	991328	Emblem			
3092	990247	Sticker			
3093		Front LH Footrest	cut		
3094		ENGINE Brake Pump	cra		
3095		ENGINE top hard	cra		
3096		Clutch Cable	cut		
3097		Centre compartment box	Br		
3098		ENGINE side cover	scr		

No of Items:

Assessor:

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jan 2020 Edit Reg		16 Jan 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Szepvolgyi Robert Joseph , Co. Reg. No.: -								
Main Claimant:	KASIM								
Vehicle Reg. No.:	JRR3703	Date of Loss:	05/01/2020 00:00 - :59 [40 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7046821101SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SJZ973L	Policy No. (Claimant):							
		Excess:							
Repairer:	Equator Brotherhood (HQ) 25 kaki bukit rd 4 #03-79 synergy @ kb, 417800 Kaki Bukit - Tel: 63846939 / 90113391								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 28/01/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (17/01/2020): TP GIA report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									















Claim Documents

*JRR3703 (7046821101SG)
[SJZ973L]
TP
KASIM
Jan 5 2020 12:00AM
[Szepvolgyi Robert Joseph]
Equator Brotherhood

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
2	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
3	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
4	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
5	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
6	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
7	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
8	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
9	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
10	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
11	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
12	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
13	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
14	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
15	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
16	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
17	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
18	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
19	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
20	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
21	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
22	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
23	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
24	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
25	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
26	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
27	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
28	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
29	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
30	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
31	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
32	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
33	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
34	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
35	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
36	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			
37	27/02/20 17:29	General View														Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
39	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
40	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
41	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
42	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
43	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
44	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
45	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
46	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
47	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
48	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
49	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
50	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
51	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
52	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
53	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
54	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
55	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
56	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
57	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
58	27/02/20 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>
59	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	27/02/20 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/02/20 15:21	POLICE REPORT.pdf	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/01/20 15:54	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20001005/FSF3E2

Date: 02/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : JRR3703

Insured Vehicle No : SJZ973L

Date of Loss: 05/01/2020

Nature of Claim: TP

Claim No: 7046821101SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JRR3703

Make & Model: YAMAHA Y15ZR, 150cc

Engine No: G3D3E027840

Reg. Date: 14/08/2016 (Man. Year: 2016)

Chassis No: PMYUG0510G0028649

Colour: Red

Odometer: 0 km

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/80 R17

Rear Tyre Size: 110/70 R17

Front Left Side: Maxxis 5 mm

Rear Left Side: Maxxis 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/01/2020

Date Inspected: 16/01/2020 Inspected At:

Equator Brotherhood (HQ)
25 kaki bukit rd 4 #03-79 synergy @ kb
Singapore 417800

Estimated Period of Repair: 8.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIM	Scratched	0.00 F	*- F
2	1		*FRONT FENDER WHEEL GUARD	Cracked	0.00 F	*- F
3	1		*FRONT FORK ASSY	Bent	0.00 F	*- F
4	1		*FRONT FORK INNER TUBE	Necessary	0.00 F	*- F
5	1		*FRONT FORK OUTER TUBE	Necessary	0.00 F	*- F
6	1		*FRONT FORK BRACKET	Bent	0.00 F	*- F
7	1		*FRONT FORK OIL SEAL	Necessary	0.00 F	*- F
8	1		*FRONT HEADLAMP	Scratched	0.00 F	*- F
9	1		*FRONT HEADLAMP BRACKET	Cracked	0.00 F	*- F
10	1		*FRONT HEADLAMP FAIRING	Broken	0.00 F	*- F
11	1		*FRONT WING MIRROR	Bent	0.00 F	*- F
12	1		*METER ASSY	Short Circuit	0.00 F	*- F
13	1		*STEERING STEM	Bent	0.00 F	*- F
14	1		*STEERING CONE	Necessary	0.00 F	*- F
15	1		*HANDLE BAR	Bent	0.00 F	*- F
16	1		*CLUTCH LEVER	Scratched	0.00 F	*- F
17	1		*SIDE FAIRING	Broken	0.00 F	*- F
18	1		*FAIRING SHIELD	Cracked	0.00 F	*- F
19	1		*FRONT TOP FAIRING INNER GARNISH	Broken	0.00 F	*- F
20	1		*CENTER FAIRING	Broken	0.00 F	*- F
21	1		*FAIRING STOPPER	Necessary	0.00 F	*- F
22	1		*RADIATOR	Bent	0.00 F	*- F
23	1		*RADIATOR COWLING	Bent	0.00 F	*- F
24	1		*FRONT FOOT REST	Scratched	0.00 F	*- F
25	1		*FRONT FOOT REST BRACKET	Bent	0.00 F	*- F
26	1		*SIDE STAND	Scratched	0.00 F	*- F
27	1		*CLUTCH ENGINE COVER	Scratched	0.00 F	*- F
28	1		*FOOT GEAR SHIFTER	Short Circuit	0.00 F	*- F
29	1		*EXHAUST MUFFLER HEAT SHIELD	Scratched	0.00 F	*- F
30	1		*EXHAUST MUFFLER ASSY	Bent	0.00 F	*- F
31	1		*REAR BOX	Scratched	0.00 F	*- F
32	1		*REAR BOX BRACKET	Bent	0.00 F	*- F
33	1		*FRONT LH FOOTREST	Cut	0.00 F	*- F
34	1		*ENGINE WATERPUMP	Cracked	0.00 F	*- F
35	1		*ENGINE TOP HEAD	Cracked	0.00 F	*- F
36	1		*CLUTCH CABLE	Cut	0.00 F	*- F
37	1		*CENTRE COMPARTMENT BOX	Broken	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >