

MS First Capital Insurance Ltd
6 Raffles Quay #21-00
Singapore 048580
Tel:62222311 Fax:62223547

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO : SLB3823U
CHASSIS NO : SALCA2AG7FH541714
ENGINE NO : 015053202234204PT
MAKE / MODEL : LAND ROVER / DISCOVERY SPORT 2.0 SI4 SE 7STR
DATE OF ACCIDENT : 11.01.2020 @ 0725HRS
YOUR INSURED VEHICLE NUMBER : SHD6897Z

<u>PARTS DISCRIPTION</u>		<u>QTY</u>	<u>List Price</u>	<u>Total List Price</u>
1	REAR BOOT LID / <i>DD</i>	1	\$ 3,200.00	\$ 3,200.00 ✓
2	REAR BOOT LID SPORT EMBLEM / <i>APC</i>	1	\$ 100.00	\$ 100.00 ✓
3	REAR BOOT LID DISCOVERY EMBLEM / <i>APC</i>	1	\$ 100.00	\$ 100.00 ✓
4	REAR BOOT LID LAND ROVER EMBLEM / <i>APC</i>	1	\$ 180.00	\$ 180.00 ✓
5	REAR WINDSCREEN GLASS MOULDING / <i>APC</i>	1	\$ 250.00	\$ 250.00 ✓
6	REAR BOOT RELFECTOR LAMP LH X <i>MM</i>	1	\$ 980.00	\$ 980.00 X
7	REAR TAILLAMP LH ? / <i>BR</i>	1	\$ 1,300.00	\$ 1,300.00 ✓ <i>957.20</i>
8	REAR BUMPER / <i>BR</i>	1	\$ 2,800.00	\$ 2,800.00 ✓ <i>2606.40</i>
9	REAR BUMPER REINFORCEMENT ? X <i>MM</i>	1	\$ 1,050.00	\$ 1,050.00 X
10	REAR BUMPER RETAINER LH / <i>BR</i>	1	\$ 120.00	\$ 120.00 ✓
11	REAR UPPER END PANEL ? X <i>MM</i>	1	\$ 1,300.00	\$ 1,300.00 X
12	REAR END PANEL ? X <i>MM</i>	1	\$ 1,150.00	\$ 1,150.00 X
13	REAR FLOOR END PANEL ? X <i>MM</i>	1	\$ 950.00	\$ 950.00 X
14	REAR FENDER LH / <i>DD</i>	1	\$ 2,550.00	\$ 2,550.00 ✓
15	REAR FENDER AIR GRILLE LH ? X <i>MM</i>	1	\$ 150.00	\$ 150.00 X
16	REAR TAILLAMP PANEL LH ? X <i>MM</i>	1	\$ 480.00	\$ 480.00 X
17	REAR FENDER UNDER-DUST COVER LH / <i>CRV</i>	1	\$ 680.00	\$ 680.00 ✓ <i>380</i>
18	REAR FENDER WHEEL ARCH- MOULDING LH / <i>CRV</i>	1	\$ 550.00	\$ 550.00 ✓ <i>297</i>
19	REAR WHEEL-HOUSE INNER PANEL LH ? X <i>MM</i>	1	\$ 3,450.00	\$ 3,450.00 X
20	REAR LOWER ARM LH ? X <i>MM</i>	1	\$ 860.00	\$ 860.00 X
21	REAR DRIVE SHAFT LH X <i>MM</i>	1	\$ 2,800.00	\$ 2,800.00 X
22	REAR WHEEL BEARING LH ? X <i>MM</i>	1	\$ 350.00	\$ 350.00 X
23	REAR KNUCKLE LH ? X <i>MM</i>	1	\$ 1,400.00	\$ 1,400.00 X
24	REAR LH CONTROL ARM REAR ? X <i>MM</i>	1	\$ 460.00	\$ 460.00 X
25	FRONT LH CONTROL ARM REAR ? X <i>MM</i>	1	\$ 450.00	\$ 450.00 X
26	SHOCK ABSORBER LH ? X <i>MM</i>	1	\$ 1,100.00	\$ 1,100.00 X
27	REAR STABILISER X <i>MM</i>	1	\$ 980.00	\$ 980.00 X
28	REAR EXHAUST SILENCER ? / <i>BT</i>	1	\$ 4,100.00	\$ 4,100.00 ✓ <i>2380</i>
29	REAR DOOR LH / <i>DD</i>	1	\$ 3,100.00	\$ 3,100.00 ✓ <i>2800</i>
		1	\$ 380.00	\$ 380.00 X
Total			\$	\$ 37,320.00
LESS 10%			\$	\$ 3,732.00
TOTAL PARTS			\$	\$ 33,588.00

SPECIAL NETT ITEM

1	REAR WINDSCREEN SEALANT / <i>APC</i>	1	\$ 100.00	\$ 100.00 ✓ <i>40</i>
2	REAR BUMPER CLIPS / <i>APC</i>	1	\$ 250.00	\$ 250.00 ✓ <i>30</i>
3	REVERSE SENSORS (<i>APC</i>) / <i>SLI</i>	1	\$ 380.00	\$ 380.00 ✓
4	REAR FENDER WHEEL ARCH- MOULDING CLIPS / <i>MM</i>	1	\$ 250.00	\$ 250.00 ✓ <i>30</i>
5	REAR FENDER UNDER-DUST COVER CLIPS / <i>APC</i>	1	\$ 250.00	\$ 250.00 ✓ <i>30</i>
6	REAR SPORT RIM LH / <i>CRV</i>	1	\$ 2,400.00	\$ 2,400.00 ✓ <i>1800</i>
7	REAR TYRE LH / <i>BR</i>	1	\$ 2,400.00	\$ 2,400.00 ✓ <i>1000</i>
8	REAR DOOR WHEEL ARCH MOULDING LH CLIPS / <i>MM</i>	1	\$ 80.00	\$ 80.00 ✓ <i>30</i>
9	REAR FENDER GLASS SEALANT / <i>APC</i>	1	\$ 60.00	\$ 60.00 ✓ <i>30</i>
			\$	\$ 6,170.00

3370

LABOUR CHARGES

1	TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE STRAIGHTEN.	\$	3,800.00	1250 1750
2	TO PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	\$	2,200.00	1950 1250
3	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS.	\$	180.00	50
4	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	\$	180.00	80
5	REMOVE & REFIT REAR WINDSCREEN GLASS	\$	180.00	170
6	TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS.	\$	180.00	30
7	TO CARRY OUT DIAGNOSTIC TEST	\$	500.00	100
8	TO REMOVE AND REPLACE EXHAUST SILENCER AND PIPES	\$	580.00	200
9	TRANSFER DOOR MECHANISM	\$	180.00	50
10	REMOVE & REPLACE FENDER 1/4 GLASS	\$	190.00	80
11	REMOVE REAR UNDERCARRIAGE PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING REPLACING AFFECTED UNDERCARRIAGE PARTS AND PERFORM COMPUTERISED ALIGNMENT AND STEERING ALIGNMENT (STEERING ANGLE ZEROING)	\$	1,000.00	300 100

TOTAL LABOUR S\$:	\$	9,170.00
TOTAL PARTS S\$:	\$	39,758.00
7% GST	\$	3,424.96
GRAND TOTAL S\$:	\$	52,352.96

3810

Prepared By : -

ANNIE TEW

Motor Claims

TEL: 6571 9642 FAX : 6278 5535

EMAIL: ainee@motorway.com.sg

P- 114,328.54

A1- 3370

L- 3810

Supp- 859.50

22,368.94

1/5- 1750 1250

Steve (LKK)
8322 8813

W/L M/L

15/1/20, 2.00pm

P/P

Ry R/L SM

10 days
12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MS First Capital Insurance Ltd

6 Raffles Quay #21-00

Singapore 048580

Tel:62222311 Fax:62223547

Attn : MOTOR CLAIMS DEPT

SUPPLEMENTARY ESTIMATE

VEHICLE NO. : **SLB3823U**

CHASSIS NO : SALCA2AG7FH541714

ENGINE NO : 015053202234204PT

MAKE / MODEL : LAND ROVER / DISCOVERY SPORT 2.0 SI4 SE 7STR

DATE OF ACCIDENT : 11.01.2020 @ 0725HRS

YOUR INSURED VEHICLE NUMBER : **SHD6897Z**

<u>PARTS DISCRPTION</u>		<u>QTY</u>	<u>List Price</u>	<u>Total List Price</u>
1	REAR BUMPER REFLECTOR LENS LH / <i>SR</i>	1	\$ 475.00	\$ 475.00 /
2	REAR FENDER INNER PANEL LH / <i>07</i>	1	\$ 580.00	\$ 580.00 <i>480/</i>
Total				\$ 1,055.00
LESS 10%				\$ 105.50
TOTAL PARTS				<u>\$ 949.50</u>

*955
-10%
859.50*

Prepared By : -

ANNIE TEW

Motor Claims

TEL: 6571 9642 FAX : 6278 5535

EMAIL: ainee@motorway.com.sg

Steve Chen (LKK Auto)

From: Tew Ai Nee <ainee@motorway.com.sg>
Sent: Monday, March 16, 2020 9:52 AM
To: Steve Chen (LKK Auto)
Subject: RE: SLB3823U - Finalize DOA: 11.01.2020

Dear Steve,

Confirm the COR.
LOD submit to who.

Thanks & Regards
Ainee

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]
Sent: Monday, 16 March, 2020 9:20 AM
To: Tew Ai Nee <ainee@motorway.com.sg>
Subject: SLB3823U - Finalize

Dear Ai Nee,

We have counter check the finalize is \$22,368.04 (P/P, before GST). 12 repair days.

Thanks.

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tew Ai Nee [mailto:ainee@motorway.com.sg]
Sent: Friday, March 13, 2020 9:35 AM
To: Steve Chen (LKK Auto)
Subject: RE: SLB3823U - Finalize

Dear Steve,

Parts	16400.6
supp parts	955
-10%	1735.56
TOTAL PARTS	15620.04