

P: +1,815.20
- 10%

+ 1,687.68

S/N + 60.00

L + 435.00

+ 2,182.68
- 20%

Ys: +1,750

Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
Tel : 91082728

Fax : 64816131

AIG Asia Pacific Insurance Singapore Pte Ltd
78 Shenton Way #07-16
AIG Building
Singapore 079120

Vehicle No : SKG 2076 B
Make : Chevrolet Captiva
Year : 2016

*Not Authorized
L1 Rep & 1750
Resurvey After Rain - 2 days*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear bumper	1705.
1 pc	Rear n/s bumper side retainer	
1 pc	Rear bumper lower garnish	
1 pc	Rear n/s bumper reflector	7 p.c
1 pc	Rear n/s fender arch protector	
1 pc	Rear exhaust silencer	

*photo
photo
photo*

Ret	\$1,175.00	✓
CM	\$95.00	✓
my CM	\$550.20	✓
175.00 CM	\$550.20	✓ 175.00
See	\$185.00	X
R	\$850.80	X
	\$3,406.20	2130.00
Less 10 %	\$340.62	213.00
	\$3,065.58	1917.00

S Nett

3 pcs set	Rear reverse sensor
20 pcs	Clip

\$3.00	\$300.00	X
	\$60.00	✓
	\$360.00	

Labour Charges

Remove/renew the above parts including knocking etc.

\$600.00 2001

To putty & spray paint on accident affected portion.

\$600.00 2201

Check/reconnect wiring.

\$30.00 151

To spray anti rust on accident affected portion.

~ \$180.00 X
Total \$4,835.58 4550

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: