



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref : Page : 1/2
Our Ref : TP0094/12/19 Date : 23/12/2019

THIRD PARTY CLAIM

M/S : NEO POH CHOO
15 ANG MO KIO AVENUE 9
#10-01 SINGAPORE

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SLT1343G - KIA CERATO K3
INSURED : NEO POH CHOO
DATE OF ACCIDENT : 20/12/2019
POLICY NO : A29098037QMY

ENGINE# :
CHASSIS# :

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost \$	U/Price \$	Total \$
Replacement of Parts				
1 front door LH	1@	1083.00	1083.00	1,083.00
2 front door LH hinge top	1@	45.00	45.00	45.00
3 front door LH hinge lower	1@	45.00	45.00	45.00
4 front door check LH	1@	55.00	55.00	55.00
5 front door inner finisher LH	1@	125.00	125.00	125.00
6 front fender LH <i>huc</i>	1@	353.00	353.00	353.00
7 front fender indicator lamp LH	1@	38.00	38.00	38.00
8 front fender inner stand garnish LH	1@	35.00	35.00	35.00
9 front fender inner cowling LH	1@	95.00	95.00	95.00
10 front door side mirror assy LH	1@	511.00	511.00	511.00
11 front lower arm LH	1@	258.00	258.00	258.00
12 front knucklearm LH	1@	340.00	340.00	340.00
13 front knucklearm bearing LH	1@	108.00	108.00	108.00
14 front shock absorber LH	1@	280.00	280.00	280.00
15 front door weatherstrip rubber LH	1@	125.00	125.00	125.00
16 front door black sticker	2@	55.00	55.00	110.00
17 front fender inner cowling clips	10@	4.00	4.00	40.00
18 front door inner finisher clips	8@	4.00	4.00	32.00
				3,678.00

Total Material

\$3,310.20

Special Nett Items

1 front sports rim LH <i>X Repair</i>	1@	480.00	480.00	480.00
				480.00
				0.00

Total S/Nett

\$480.00



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :
Our Ref : TP0094/12/19

Page : 2/2
Date : 23/12/2019

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
<u>Labour & Misc</u>				
1 Remove and install undercarraige				250.00
2 Wheel allignment				100.00
3 Remove and install front bumper, front fender LH, fender inner cowl, front door LH, inner finisher. Knocking door pillar, running board spoiler LH and Restriaghten body.				900.00
4 Spray painting				800.00
5 Check wiring system.				25.00
				<u>2,075.00</u>
Total Labour				<u>\$2,075.00</u>
Nett Total Before Gst				<u>\$5,865.20</u>

Your faithfully

NPH AUTO SERVICE
(Manager)

Gao Qianf - 82880282

LKK

23/12/19.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: