



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :

Our Ref : TP0094/12/19

Page

: 1/2

Date

: 23/12/2019

M/S

: **THIRD PARTY CLAIM**

: NEO POH CHOO

15 ANG MO KIO AVENUE 9

#10-01 SINGAPORE

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SLT1343G - KIA CERATO K3

INSURED : NEO POH CHOO

DATE OF ACCIDENT : 20/12/2019

POLICY NO : A29098037QMY

ENGINE# :

CHASSIS# :

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$

Replacement of Parts

1	front door LH	10	1083.00	1083.00	1,083.00
2	front door LH hinge top	10	45.00	45.00	45.00
3	front door LH hinge lower	10	45.00	45.00	45.00
4	front door check LH	10	55.00	55.00	55.00
5	front door inner finisher LH	10	125.00	125.00	125.00
6	front fender LH	10	353.00	353.00	353.00
7	front fender indicator lamp LH	10	38.00	38.00	38.00
8	front fender inner stand garnish LH	10	35.00	35.00	35.00
9	front fender inner cowling LH	10	95.00	95.00	95.00
10	front door side mirror assy LH	10	511.00	511.00	511.00
11	front lower arm LH	10	258.00	258.00	258.00
12	front knucklearm LH	10	340.00	340.00	340.00
13	front knucklearm bearing LH	10	108.00	108.00	108.00
14	front shock absorber LH	10	280.00	280.00	280.00
15	front door weatherstrip rubber LH	10	125.00	125.00	125.00
16	front door black sticker	20	55.00	55.00	110.00
17	front fender inner cowling clips	100	4.00	4.00	40.00
18	front door inner finisher clips	80	4.00	4.00	32.00

3,678.00

Total Material

Special Nett Items

\$3,310.20

1 front sports rim LH

X Repair

10 480.00 480.00 480.00

480.00

0.00

Total S/Nett

\$480.00



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :
Our Ref : TP0094/12/19

Page : 2/2
Date : 23/12/2019

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
<u>Labour & Misc</u>				
1 Remove and install undercarraige				250.00 X
2 Wheel allignment				100.00 60
3 Remove and install front bumper, front fender LH, fender inner cowl, front door LH, inner finisher. Knocking door pillar, running board spoiler LH and Restriaghten body.				900.00 400
4 Spray painting				800.00 500
5 Check wiring system.				25.00 ✓
				2,075.00
Total Labour				\$2,075.00
Nett Total Before Gst				\$5,865.20

Your faithfully

NPH AUTO SERVICE
(Manager)

Guo Qiang - 82880282
LKK
23/12/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

not added
nln
1/2 @ 2500
3 day.

p- 2379
10%
p- 2141.1
1- 885.00
31.16.10
200
2500.88

FAR EAST TYRES & BATTERIES TRADING

BLOCK 9002 TAMPINES STREET 93

#01-32 528836

SINGAPORE

TEL: 67851902

FAX: 67494328

Work Order:

R002742

VIN:

SLT1343G

Date

24.12.19 10:21 AM



SLT1343G

Kia : Cerato/Forte : 2013- (YD/YDm)
Thrust Line Alignment

Front : Left

Actual	Before	Specified Range
-2°30'	-0°08'	-0°52' 0°08'
4°10'	4°10'	3°31' 4°31'
0°56'	-0°07'	-0°03' 0°09'
19°31'	17°10'	13°06' 14°06'
17°01'	17°01'	12°14' 14°14'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°55'	-0°28'	-0°52' 0°08'
3°56'	3°56'	3°31' 4°31'
-0°10'	-0°11'	-0°03' 0°09'
10°23'	11°46'	13°06' 14°06'
11°18'	11°18'	12°14' 14°14'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-3°25'	0°19'	
0°13'	0°13'	
9°08'	5°24'	
0°46'	-0°18'	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°10'	-1°41'	-2°00' -1°00'
0°13'	0°12'	0°00' 0°27'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°24'	-1°24'	-2°00' -1°00'
0°09'	0°10'	0°00' 0°27'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°16'	-0°17'	
0°22'	0°22'	0°00' 0°54'
0°02'	0°01'	