

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG ASIA PACIFIC INSURANCE PTE L	DATE	: 14/01/2020
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<i>Khanchana.</i>			
VEHICLE DETAILS			
VEHICLE NO	: GBD205G		
MODEL	: NISSAN NV200 1.5L MT ABS AIRBAG 2WD 6DR EURO 5		
CHASSIS NO			<i>VSKYBAM207007785</i>
ACCIDENT DETAILS		DATE	: 13-Jan-20
		TIME	: 19:00HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR LH <i>Dented</i>	1	\$ 2,130.90	\$ <u>2,130.90</u>
2	REAR DOOR GLASS WITH MOULDING LH <i>Neu</i>	1	\$ 2,055.90	\$ 2,055.90
3	REAR DOOR RH <i>Dented</i>	1	\$ 890.30 <i>1285</i>	\$ 890.30 <i>1285</i>
4	REAR DOOR GLASS WITH MOULDING RH <i>Neu</i>	1	\$ 920.00	\$ 920.00
5	REAR DOOR LOGO <i>Neu</i>	1	\$ 63.90	\$ 63.90
6	REAR DOOR EMBLEM 'NV200' <i>Neu</i>	1	\$ 87.90	\$ 87.90
7	REAR DOOR HINGE <i>Neu Neu</i>	4	\$ 99.60	\$ 398.40
8	REAR DOOR CHECKER <i>Neu Neu</i>	2	\$ 87.00	\$ 174.00
9	REAR DOOR EMBLEM 'DCI' <i>Neu</i>	1	\$ 87.90	\$ 87.90
10	REAR DOOR WEATHERSTRIP RH <i>Attn</i>	1	\$ 83.60	\$ 83.60
11	REAR BUMPER <i>Dented</i>	1	\$ 566.80	\$ 566.80
12	REAR BUMPER SIDE RETAINER <i>Neu</i>	2	\$ 52.90	\$ 105.80
13	REAR BUMPER SPONGE <i>Cracked</i>	1	\$ 128.90	\$ 128.90
14	REAR BUMPER TOWING COVER <i>Neu</i>	1	\$ 63.00	\$ 63.00
15	REAR BUMPER REFLECTOR <i>Cracked</i>	2	\$ 52.30	\$ 104.60
16	REAR END PANEL <i>Dented</i>	1	\$ 855.90	\$ <u>855.90</u>
17	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 94.20	\$ 94.20
18	REAR END PANEL WEATHERSTRIP <i>Attn</i>	1	\$ 124.20	\$ 124.20

Door Lock below LH *275* ✓

Door Lock below RH *275* ✓

133

135

19	REAR SPARE TYRE LOCK WITH BOLT <i>new</i>	1	\$ 262.30	\$ 262.30	+
20	TAILLAMP <i>Crul'd</i>	2	\$ 280.90	\$ 561.80	✓
21	TAIL LAMP PANEL <i>Repis</i>	2	\$ 271.50	\$ 543.00	+
22	REAR FLOOR PANEL <i>Repis</i>	1	\$ 2,183.20	\$ 2,183.20	+

5758

5182.20

TOTAL PRICE \$ 12,486.50

LESS 10% \$ 1,248.65

SUB TOTAL PRICE \$ 11,237.85

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Not ne</i>	1	\$ 20.00	\$ 20.00	+
2	REAR BUMPER CLIP <i>new</i>	1	\$ 20.00	\$ 20.00	-
3	TAIL LAMP PANEL SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
4	REAR DOOR SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
5	REAR DOOR STICKER '70km/h <i>ne</i>	1	\$ 50.00	\$ 50.00	15
6	REAR DOOR STICKER 4PAX <i>Ne</i>	1	\$ 50.00	\$ 50.00	15
7	REAR DOOR GLASS SEALANT <i>ne</i>	2	\$ 80.00	\$ 160.00	80
8	REAR END PANEL SEALANT <i>ne</i>	1	\$ 80.00	\$ 80.00	60
9	REAR END PANEL TOP GARNISH CLIP <i>ne</i>	1	\$ 20.00	\$ 20.00	10
10	REAR END PANEL INSULATION SEAL <i>3 MP</i>	1	\$ 150.00	\$ 150.00	+
11	REAR FLOOR PANEL INSULATOR SEAL <i>3 MP</i>	1	\$ 550.00	\$ 550.00	+
12	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	200

TOTAL \$ 1,460.00 400

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 2,000.00	1200	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 2,000.00	1000	
3	Tuff Coat	\$ 250.00	120	
4	WIRING CHECK	\$ 80.00	30	
5	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X	
6	TO REMOVE AND REFIX REAR DOOR MECHANISM (2 DOORS)	\$ 320.00	160	

7	REMOVE & REINSTALL REAR DOOR WINDOW GLASS	\$ 160.00	120	
8	REMOVE AND REFIX REVERSE SENSOR	\$ 160.00	50	

TOTAL

\$5,150.00

2780

TOTAL PARTS COST : \$ 12,697.85
TOTAL LABOUR COST : \$ 5,150.00
TOTAL REPAIR COST : \$ 17,847.85

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Adrian Lj
H/s 15/01/20
08 Days.

total: 8362.20

H/s: 6.7K.

6.7K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: