

**WTS Engineering Pte Ltd**

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163

Company Registration Number: 200505706E

Quotation

DATE: 14/01/20
VEHICLE NO: PA9871Z
DRIVER: NG WENG CHIANG
ATTENTION TO:
PREPARED BY: Chan Soo Lye

LOCATION: Gul Workshop
Q REF No: Q20/01/1110
DEPARTMENT: WTS Bus Department
ACCIDENT DATE: 13/01/20
REF No: JW-0120-140

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Gul Workshop

Q20/01/1110

S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	REAR BUMPER FIBRE	1	2172.9	2,172.90
2	REAR ENGINE COVER FIBRE	1	1945.45	1,945.45
3	ENGINE COVER STRUCTURE	1	1897.5	1,897.50
4	REAR VEHICLE NUMBER PLATE	1	SN 45 50	50.00
5	60 KM STICKER	1	SN 5	5.00
6	REAR ENGINE COVER LOCK RHS AND LHS	2	69.45	138.90
7	REAR LHS TAIL LAMP	1	482.05	482.05
8	LUGGAGE DOOR HANDLE	1	60.2	60.20
9	NUMBER PLATE LAMP	2	51.75	103.50
Labour Costs				
1	TO DISMANTLE AND REMOVE DAMAGED PARTS REPLACE REAR ENGINE COVER, REAR ENGINE COVER STRUCTURE FRAME, REAR BUMPER, REAR TAIL LAMP. REPAIR REAR RHS CORNER PANEL - CRACKED. REPAIR REAR PANEL - CRACKED. REPAIR FRONT BUMPER CRACKED. RE-ALIGNMENT REAR ENGINE COVER.	1	2500	2,500.00
2	TO REPLACE REAR BUMPER, REAR ENGINE COVER, BOTH SIDE CORNER PANEL, REAR PANEL AND FRONT BUMPER, FRONT PANEL STICKER.	1	1800	1,800.00
Spray Paint				
1	Spray Painting	1	1600	1,600.00
	TO PUTTY AND SPRAY PAINTING REAR BUMPER, REAR ENGINE COVER, REAR RHS SIDE CORNER PANEL, REAR BUMPER, REAR PANEL.			5000.
			TOTAL:	12,755.50
			Total Amount	SGD 12,755.50

Remarks:

Signature of Workshop Dpt

Signature of Department Head

Signature of Claim Department

Surveyor Sign:	
Surveyor Name:	Taughlin
Date:	16/1/20

Taughlin 97495746
16/1/20 R440.
Lumpsum
Resurvey after repair
Taughlin @ 11hanto an
a 10 days