

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A**AAD2001-119***Not Authorised
11/1/2020 @ 2250h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

15 JAN 2020

SHF 615A

VF1ABL15AUC278494

RENAULT

LATITUDE

13.1.2020

AIG

27/6/2014

	PART
1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT LH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE LH
1	BUMPER BEAM FRT
1	HEADLAMP LH
1	HEADLAMP PANEL FRT LH
1	FENDER PANEL FRT LH
1	WHEELARCH FRT LH
1	FENDER BRACKET FRT LH
1	FENDER BRACKET LOWER LH
1	FENDER INSULATOR LH
1	FRONT BRACE PANEL
1	BONNET
1	BONNET INSULATOR
1	BONNET STRUT LH
1	BONNET HINGE LH
1	BONNET LOCK
1	BONNET CABLE
1	BONNET CABLE COVER
1	BONNET SEAL OUTER
1	BONNET SEAL INNER

	LIST
\$	<i>Bu</i> 747.20 ✓
\$	<i>SL</i> 344.70 X
\$	<i>SL</i> 394.68 X
\$	<i>Dis</i> 101.40 ✓
\$	<i>SL</i> 10.70 X
\$	<i>SL</i> 292.50 X
\$	<i>SL</i> 147.00 X
\$	<i>SL</i> 207.21 X
\$	<i>R</i> 663.70 X
\$	<i>m/c</i> 743.60 ✓
\$	<i>R</i> 127.70 X
\$	<i>R</i> 414.40 ✓
\$	<i>SL</i> 112.30
\$	<i>SL</i> 38.90
\$	<i>SL</i> 11.80
\$	<i>SL</i> 65.50
\$	<i>R</i> 177.22
\$	<i>R</i> 1,312.70
\$	<i>SL</i> 294.30
\$	<i>SL</i> 53.30
\$	<i>R</i> 236.50
\$	<i>R</i> 152.80
\$	<i>SL</i> 55.20
\$	<i>SL</i> 80.60
\$	<i>SL</i> 83.20
\$	<i>SL</i> 70.10

Trans-cab Auto Services Pte Ltd**AAD2001-119**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A

1	RADIATOR GRILLE	\$	969.90
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	225.36
1	RADIATOR GRILLE FRAME	\$	686.00
1	FRAME FULL SUPPORT PANEL	\$	592.70
1	FRAME FULL SUPPORT BRACKET	\$	41.60
1	AIR CLEANER BOX	\$	464.20
1	AIR CLEANER HOSE	\$	175.85
1	AIR CLEANER LOWER	\$	271.26
1	DOOR PANEL FRT LH	\$	2,844.66
1	DOOR MIRROR ASSY LH	\$	727.90
1	DOOR HARNESS WIRE LH	\$	2,670.00
1	ROCKER PANEL INNER GARNISH LH	\$	466.51
1	ROCKER PANEL INNER LH	\$	1,024.79
1	ROCKER PANEL OUTER LH	\$	1,184.99
1	ROCKER PANEL CENTER LH	\$	990.25
1	LOWER ARM LH L70Y	\$	192.70
1	KNUCKLE ARM LH L70Y	\$	481.50
1	ABSORBER FRT LH L70Y	\$	274.10
1	DRIVESHAFT LH	\$	1,355.70
1	STABILIZER BAR FRT	\$	427.90
1	SUBFRAME OUTER FRT	\$	1,094.20
1	SUBFRAME BRACKET OUTER LH	\$	49.00
1	SUBFRAME BRACKET OUTER RH	\$	49.00
1	A/C CONDENSER	\$	1,537.80
1	AUTO COMPUTER	\$	1,287.30
1	INJECTION COMPUTER	\$	2,706.30
1	RHD HYDRAULIC POWER(RACK&PINION)	\$	3,765.30
1	STEERING PUMP ELECTRIC L70Y	\$	2,026.70
1	FENDER PANEL INNER FRT LH L70Y	\$	858.30
1	FENDER PANEL REINFORCEMENT FRT LH L70Y	\$	642.40
1	WHEEL HOUSING PANEL FRT LH L70Y	\$	2,621.60

TOTAL \$ 39,644.98
10% \$ 3,964.50
\$ 35,680.48

Trans-cab Auto Services Pte Ltd**AAD2001-119**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A**Special Nett**

1 BUMPER CLIP FRT	\$	na 66.00	✓
1 BUMPER BRACKET CLIP FRT LH	\$	na 12.00	}
1 BUMPER SUPPORT CLIP FRT LH	\$	na 10.50	
1 BUMPER GRILLE LOWER CLIP	\$	na 69.00	
1 WHEELARCH CLIP FRT LH	\$	na 30.50	
1 FRAME FULL SUPPORT PANEL CLIP	\$	na 70.00	
1SET FRAME FULL SUPPORT PANEL NUT	\$	na 20.00	
2 FRAME FULL SUPPORT PANEL STUD	\$	na 30.00	
1SET RADIATOR GRILLE SCREW	\$	na 16.00	
1SET RADIATOR GRILLE FRAME CLIP	\$	na 52.00	
1 FRONT LEFT TYRE	\$	pu 300.00	} X
1 FRONT LEFT TYRE RIM	\$	pu 380.00	
1SET Front licence plate with holder	\$	pu 80.00	
1 WINDSCREEN SEALANT	\$	na 253.80	
1 FRONT WINDSCREEN MOULDING	\$	na 120.00	
1 FRONT WINDSCREEN INNER SPONGE SEAL	\$	na 100.00	
6 BONNET INSULATOR CLIP L70Y	\$	na 7.30	
2 BONNET CABLE CLIP L70Y	\$	na 6.31	
2 BONNET CABLE COVER SCREW L70Y	\$	na 10.85	
1 FRONT DOOR STICKER 'Trans-Cab'	\$	na 80.00	
1 FRONT DOOR STICKER 'Classic'	\$	na 80.00	

TOTAL \$ 1,794.27**TOTAL PARTS \$ 37,474.75****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 6,000.00 4000

To transfer of front bumper fittings, attachment and perform water seepage test.

\$ na 170.00 X

Trans-cab Auto Services Pte Ltd**AAD2001-119**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A

To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i> 170.00	<i>X</i>
To transfer of front windscreen glass to facilitate bodywork repair.	\$	<i>4</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	220.00	<i>601</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>4</i> 380.00	<i>X</i>
Putty and spray painting of the affected portion.	\$	6,000.00	<i>4401</i>
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>4</i> 170.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>4</i> 380.00	<i>X</i>
To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>4</i> 170.00	<i>X</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>4</i> 380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To rust-proofing of the affected areas.	\$	170.00	<i>301</i>
To check ABS and brake efficiency, final checking and testing.	\$	<i>4</i> 380.00	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD2001-119**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A

To dismantle and refit aircon assy and attachment,
vacuum and charge-in-gas.

\$ *na* 380.00 X

To vacuum, replace, refix and recharge air condenser

\$ *4* 380.00 X

To pull and jack out chassis frame and correct it to
symmetrical position with the aid of hydraulic
pneumatic jack.

\$ *4* 380.00 X

To remove and renew power steering pump, oil cooler
pipe and final checking and testing.

\$ *4* 440.00 X

TOTAL \$ **16,680.00**

Over All Total \$ **54,154.75**

LUMP SUM (REPAIR DAY)*20 days**2 days*