

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 25988

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0044/2020/NS
Date : 13-Jan-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Niccol Soo Cheng Chee
Address : 69P Jalan Lim Tai See
Singapore 266270
Telephone : HP +65 93867989
Type of Claim : Own Damage Claims
Policy No. : 1800011609
Vehicle No : **SJL 3999 S**
Model Code : Audi A3 Sportsback 1.4 TF
Model / Year : Aug-18
Engine No : CZE 814605
Chassis No : WAUZZZ8V2JA136060
Mileage : -
Date In : -
Estimated By : Johnny Bop / Allan Wu
Accident Date : 10-Jan-20
Place of Accident : Clementi Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJL 3999 S

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight waher assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00 500	
3	To respray front bumper.	\$ 900.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 2,502.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJL 3999 S

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>red</i>	\$ 1,698.00	✓
2	FRONT BUMPER FIXING PARTS	\$ 170.00	✗
3	FRONT BUMPER GUIDE SECTION - LH / rh <i>2</i>	\$ 70.00	✗
4	FRONT BUMPER GRILLE - CENTRE <i>new</i>	\$ 146.00	✗
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 270.00	✗
6	FRONT BUMPER CLOSING ELEMENT - LH <i>new</i>	\$ 270.00	✗
7	RADIATOR GRILLE <i>cut</i>	\$ 1,301.00	✓
8	RADIATOR GRILLE CLOSING ELEMENT <i>?</i>	\$ 174.00	?
9	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	\$ 171.00	✗
10	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>new</i>	\$ 660.00	✗
11	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	\$ 172.00	✗
12	FOAM FILLER PIECE COVER <i>?</i>	\$ 111.00	✗
13	SIGNAL HORN - LH HIGH TONE <i>new</i>	\$ 182.00	✗
14	RADIATOR AIR GUIDE - LH	\$ 22.00	✗
15	RADIATOR AIR GUIDE - UPPER CENTRE <i>new</i>	\$ 11.00	✗
16	AIRCON STICKER <i>new</i>	NEC \$ 7.00	✓
17	CAUTION SIGN STICKER	NEC \$ 13.00	✓
18	FRONT NO PLATE <i>Bent</i>	S/N \$ 40.00	✓
19	SUNDRIES <i>?</i>	\$ 200.00	?

TOTAL SPARE PARTS CHARGES

: \$ 5,688.00

TOTAL LABOUR CHARGES

: \$ 2,502.00

GRAND TOTAL

: \$ 8,190.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian 
Surveyed Date : 16/01/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant