



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

SOMPO INSURANCE SINGAPORE PL  
50 RAFFLES PLACE  
#05-01/06  
SINGAPORE LAND TOWER  
SINGAPORE 048623

INV No. AC2004340  
INV Date 05/06/2020  
Reference CS/SMO20001038/Ayd3q2  
Code SMO



### PROFESSIONAL SERVICE FEE

Vehicle No. SKX 9894X  
Insured Veh. CB 6392H  
Claim No. CMTD2000279/SYH  
Policy No.  
Accident Date 15/01/2020  
Inspection Date 17/01/2020

Description	Total
Survey Inspection	250.00
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>250.00</b>
<b>GST (7%)</b>	<b>17.50</b>
<b>Grand Total</b>	<b>267.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20001038/Ayd3q2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 05-06-2020



Code : SMO

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	CB 6392H	<b>Veh. Inspected</b>	SKX 9894X
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CMTD2000279/SYH	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	YE YONG KANG MELVIN	<b>Assign Date</b>	16/01/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA ALTIS	<b>c.c</b>	1598
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
<b>Chassis No.</b>	MR053REH104538667	<b>Colour</b>	BLACK
<b>Odometer</b>	66841	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	205/55 R16	YOKOHAMA	6 mm
<b>L/H Front Tyre</b>	205/55 R16	YOKOHAMA	6 mm
<b>R/H Rear Tyre</b>	205/55 R16	YOKOHAMA	6 mm
<b>L/H Rear Tyre</b>	205/55 R16	YOKOHAMA	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.
---

### 5. General Information

<b>Accident Date</b>	15/01/2020	<b>Inspection Date</b>	17/01/2020
<b>Survey held at</b>	J-MART MOTOR PTE LTD BLK 5 DEFU LANE 10 #01-578 DEFU INDUSTRIAL PARK C SINGAPORE 539186		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 9894X**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	LH HEADLAMP	CUT	850.00	850.00
1	LH HEADLAMP CHROME	NOT NECESSARY	184.00	-
1	FRT BUMPER	DEFORMED	585.10	585.10
1	FRT BUMPER LH RETAINER	NECESSARY	81.80	81.80
1	FRT BUMPER LH FOG LAMP COVER	NOT NECESSARY	79.00	-
	LESS 25% DISCOUNT		-444.98	-379.23
			1,334.92	1,137.67
1	FRT LH RIM (SN)	CUT	2,409.20	1,000.00
	LESS 25% DISCOUNT		-602.30	-
			1,806.90	1,000.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		500.00	200.00
	SPRAY PAINTING.		500.00	400.00
	WIRING.		30.00	30.00
	ALIGNMENT.		80.00	80.00
			1,110.00	710.00
<b>GRAND TOTAL</b>			<b>4,251.82</b>	<b>2,847.67</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,200.00</b>
---	--	--	-----------------

Report Ref No. CS/SMO20001038/Ayd3q2

**ADRIAN LING WAI PING****B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

