

ASS. REC. BY: Sun Pm

REF:

NTUC CS/INC 20001246/2 v f3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: FBE 3796 SPolicy No. 5104503690 (14/01/2019 - 31/03/2020)Claims No. MT/1082291-002


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB 5808 Z Yr Regn: 2012 / 2019Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius 4 FL c.c. 1795Colour: Maroon A/C: Insured / Std / NI / NASp. Reading: 62.37 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU703089241Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 195 / 65 R15R: 195 / 65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Dunlop

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 15/01/2020 D.O.I. 16/01/2020Survey held at SMRTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SHB 5808 - NJM / INC 1007851 / 11/11/10 D.O.A - 21/04/2010PBE 3796 S - XTPTAX/01/20/2066* Pending for estimate.FBE 3796 S23/4/20 Final fig \$4569.80 confirmed by email (Reel 27.906.10, 8695)

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 23/4 - typist

Report Format:

TP

Lump Sum / L.E.C.

4569.80Days Of Repair: 6Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Section A - Accident Details

Registration Number	SHB5808Z
Case Reference Number	TAX/01/20/2066
Registration Date	20/12/2019
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	LIM THIAM HOE (LIN TIANHE)
Type of Accident	Head In Rear
Accident Date and Time	15/1/2020 2:35 PM
Accident Reported Date and Time	15/1/2020 4:24 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24105334
Special Instruction to ARC, if any	TP/ REAR PORTION/ NTUC - LKK
Prepared Date and Time	22/1/2020 11:14 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,933.00	\$850.00
Total Spray Cost	\$3,312.00	\$550.00
Total Spare Part Cost	\$20,756.32	\$3,069.80
Total Other Cost	\$1,480.00	\$120.00
TOTAL COST	\$27,481.32	\$4,589.80 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	11.0	6.0
Prepared / Adjusted By	Kim Ming Chin	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	30/01/2020 5:03 PM	30/01/2020 5:15 PM
Signature		
Remarks	Initial estimate = 9 days SUP = 2 days	P/P Repair, Before paint photo

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2004-0170	Invoice Number	
Quotation Date	15.04.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR SPARE TYRE PANEL	\$300.00	\$150.00
TO REPAIR PANEL SIDE ROOF LH	\$150.00	\$100.00
TO REPLACE REAR END PANEL	\$300.00	\$200.00
TO REPAIR REAR PORTION	\$1,183.00	\$400.00
Total Labour	\$1,933.00	\$850.00

✓supp
✓supp
✓supp

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$150.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY TROUGH BACK DOOR LH	\$180.00	\$0.00
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
TO RESPRAY LH RAIL ROOF SIDE	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$3,312.00	\$550.00

✓supp
✓supp

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$40.00
TO REMOVE & REFIT EXHAUST	\$120.00	\$0.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00

\$0

TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,480.00	\$120.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price	Discount	Final Price	Estimator	Surveyor
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$485.60	25.00	\$364.20	Approved Replace	Approved Replace
		52599-68030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.50	0.00	\$0.00	Replace	Not Given X
		52462-47030	PAD, REAR BUMPER, NO. 2	2.00	\$4.00	25.00	\$6.00	Replace	Replace
		52462-47130	PAD, REAR BUMPER, NO. 3	2.00	\$11.00	25.00	\$16.50	Replace	Replace
		52101-47030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.30	0.00	\$0.00	Replace	Not Given X
		52462-47020	PAD, REAR BUMPER, NO. 1	2.00	\$4.00	25.00	\$6.00	Replace	Replace
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.50	25.00	\$33.75	Replace	Replace
		52576-47060	RETAINER, RR BUMPER, LH	0.00	\$132.60	0.00	\$0.00	Replace	Not Given X
		52575-47060	RETAINER, RR BUMPER, RH	0.00	\$132.60	0.00	\$0.00	Replace	Not Given X
		52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$374.50	25.00	\$280.88	Replace	Replace
		52169-47070	COVER, GUARD RR BUMPER LOWER	1.00	\$22.00	25.00	\$16.50	Replace	Replace
		52461-47070	PAD, RR BUMPER, CTR	3.00	\$11.00	25.00	\$24.75	Replace	Replace
		52591-47080	SEAL, RR BUMPER, RH	0.00	\$118.30	0.00	\$0.00	Replace	Check X
		52592-47080	SEAL, RR BUMPER, LH	0.00	\$118.30	0.00	\$0.00	Replace	Check X
		52023-47030	REAR BUMPER REINFORCEMENT	0.00	\$332.70	0.00	\$0.00	Replace	Check X
		58398-47050	COVER, REAR FLOOR UNDER, RH	0.00	\$175.10	0.00	\$0.00	Replace	Check X
		66259-47010	COVER, REAR FLOOR UNDER CENTER	0.00	\$229.90	0.00	\$0.00	Replace	Check X
		58399-47030	COVER, REAR FLOOR UNDER, LH	0.00	\$211.90	0.00	\$0.00	Replace	Check X
		81910-47030	REAR BUMPER REFLECTOR ASSY,	0.00	\$39.00	0.00	\$0.00	Replace	Check X
		81920-47030	REAR BUMPER REFLECTOR ASSY,	0.00	\$39.00	0.00	\$0.00	Replace	Check X
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		76801-47170 A1	TAIL GATE BACK DOOR OUTSIDE CARNISH SUB-	0.00	\$913.60	0.00	\$0.00	Replace	Not Given X
		75403-48010	EMBLEM SUB-ASSY REAR	0.00	\$47.90	0.00	\$0.00	Replace	Not Given X
		75441-47220	NAME PLATE (HYBRID), LUGGAGE	0.00	\$54.60	0.00	\$0.00	Replace	Not Given X
		75442-47200	NAME PLATE (PRIUS), LUGGAGE	0.00	\$54.60	0.00	\$0.00	Replace	Not Given X
			SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given X
			STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given X
			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace
			NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace
		76085-47916	SPOILER SUB-ASSY, REAR	0.00	\$1,575.40	0.00	\$0.00	Replace	Not Given X
		81006-47030	LAMP SET, STOP CENTER	0.00	\$192.30	0.00	\$0.00	Replace	Not Given X
		67005-47530	TAIL GATE PANEL SUB-ASSY, BACK DOOR	0.00	\$1,147.80	0.00	\$0.00	Replace	Not Given X
		TMKONG-TAILG	AUTO TAILGATE SYSTEM	0.00	\$2,520.00	0.00	\$0.00	Replace	Not Given X
		69478-47010	TAIL GATE CUSHION, BACK DOOR, RH & LH	0.00	\$9.90	0.00	\$0.00	Replace	Not Given X
		75129-13020	TAIL GATE CUSHION, REAR LICENCE PLATE	0.00	\$2.60	0.00	\$0.00	Replace	Not Given X
		67881-47051	TAIL GATE WEATHERSTRIP, BACK	0.00	\$372.30	0.00	\$0.00	Replace	Check X
		56117-50140	TAIL GATE DAM, BACK DOOR GLASS UPPER	0.00	\$28.90	0.00	\$0.00	Replace	Not Given X
		75571-47011	TAIL GATE MOULDING GLASS, BACK DOOR	0.00	\$35.50	0.00	\$0.00	Replace	Not Given X

cru
 SVC
 nec
 nec
 SVC
 SVC
 nec
 SVC
 SVC
 nec
 SVC
 SVC
 SCR
 SCR
 SVC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63085592
Estimator Telephone Number 6962623
Accident Reporting Number 08602072

Date Generated : 17/04/2020

User ID PohSuan

68105-47292	TAIL GATE GLASS SUB-ASSY, BACK DOOR	0.00	\$1,656.70	0.00	\$0.00	Replace	Not Given	X
64801-47031	TAIL GATE LOWER GLASS SUB-ASSY, BACK	0.00	\$761.40	0.00	\$0.00	Replace	Not Given	X
56117-50140	TAIL GATE DAM, BACK DOOR GLASS UPPER	0.00	\$28.90	0.00	\$0.00	Replace	Not Given	X
75575-47051	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$23.60	0.00	\$0.00	Replace	Not Given	X
75573-47110	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$30.90	0.00	\$0.00	Replace	Not Given	X
75574-47040	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$30.90	0.00	\$0.00	Replace	Not Given	X
	SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
68810-47061	TAIL GATE BACK DOOR HINGE ASSY, LH	0.00	\$61.00	0.00	\$0.00	Replace	Not Given	X
68810-47061	TAIL GATE BACK DOOR HINGE ASSY, RH	0.00	\$61.00	0.00	\$0.00	Replace	Not Given	X
69350-47050	TAIL GATE LOCK ASSY, BACK DOOR	0.00	\$467.00	0.00	\$0.00	Replace	Check	X
69321-47010	TAIL GATE LOCK COVER, BACK DOOR	0.00	\$30.20	0.00	\$0.00	Replace	Not Given	X
69430-52050	TAIL GATE STRIKER ASSY, BACK DOOR	0.00	\$25.80	0.00	\$0.00	Replace	Not Given	X
67750-47080-C0	TAILGATE BOARD ASSY	0.00	\$259.20	0.00	\$0.00	Replace	Not Given	X
64721-47050-C0	TAILGATE BOARD, COVER	0.00	\$24.90	0.00	\$0.00	Replace	Not Given	X
67751-47111-C0	TAILGATE TRIM, LOWER	0.00	\$225.20	0.00	\$0.00	Replace	Not Given	Y
58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$651.00	0.00	\$0.00	Replace	Check	X
64716-47130-C0	END PANEL, COVER, DECK TRIM, REAR	0.00	\$126.70	0.00	\$0.00	Replace	Check	X
64718-47080-C0	END PANEL, COVER, DECK TRIM SERVICE	0.00	\$48.50	0.00	\$0.00	Replace	Check	X
	SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
58311-47130	SPARE TYRE PANEL, PAN, REAR FLOOR	0.00	\$583.40	0.00	\$0.00	Replace	Check	X
64995-47050	BOX, DECK FLOOR, RH	0.00	\$313.60	0.00	\$0.00	Replace	Check	X
64997-47060	BOX, DECK FLOOR, LH	0.00	\$313.00	0.00	\$0.00	Replace	Check	X
58415-47110-C2	BOARD, REAR FLOOR, NO.1	0.00	\$519.00	0.00	\$0.00	Replace	Check	X
64730-47241-C2	PANEL ASSY, DECK TRIM SIDE, RH	0.00	\$355.90	0.00	\$0.00	Replace	Check	X
64740-47191-C3	PANEL ASSY, DECK TRIM SIDE, LH	0.00	\$355.90	0.00	\$0.00	Replace	Check	X
61018-47010	MEMBER SUB-ASSY, RAIL ROOT SIDE REAR LH	1.00	\$288.50	100.00	\$0.00	Replace	Repair	X
81204-47010	LAMP ASSY, LICENSE PLATE	0.00	\$267.60	0.00	\$0.00	Replace	Not Given	X
84840-47040	SWITCH ASSY, BACK DOOR OPENER	0.00	\$179.10	0.00	\$0.00	Replace	Not Given	X
89997-30100	ANTENNA, ELECTRICAL KEY	0.00	\$72.00	0.00	\$0.00	Replace	Check	X
	REVERSE SENSOR, REAR BUMPER	1.00	\$180.00	0.00	\$180.00	Replace	Replace	X
	REVERSE CAMERA (FOR TAILGATE)	0.00	\$230.30	0.00	\$0.00	Replace	Not Given	X
81551-47481	LENS & BODY, REAR COMBINATION LAMP, RH	0.00	\$339.60	0.00	\$0.00	Replace	Check	X
81561-47471	LENS & BODY, REAR COMBINATION LAMP, LH	0.00	\$339.60	0.00	\$0.00	Replace	Check	X
81497-47040	COVER, REAR COMBINATION LAMP, RH	0.00	\$69.90	0.00	\$0.00	Replace	Check	X
81498-47040	COVER, REAR COMBINATION LAMP, LH	0.00	\$69.90	0.00	\$0.00	Replace	Check	X
81457-47020	LENS & BODY, REAR COMBINATION LAMP,	1.00	\$261.00	10.00	\$234.90	Replace	Replace	X
81456-47020	LENS & BODY, REAR COMBINATION LAMP,	0.00	\$261.00	0.00	\$0.00	Replace	Check	X
81580-47070	LAMP ASSY, REAR, RH	1.00	\$293.60	10.00	\$264.24	Replace	Replace	X
81590-47070	LAMP ASSY, REAR, LH	0.00	\$293.60	0.00	\$0.00	Replace	Check	X
82162-47P90	WIRE, FLOOR, NO.2	0.00	\$142.40	0.00	\$0.00	Replace	Not Given	X
51931-47030	CARRIER, SPARE WHEEL	0.00	\$20.80	0.00	\$0.00	Replace	Check	X
61601-47150	PANEL SUB-ASSY, FENDER REAR RH	0.00	\$871.50	0.00	\$0.00	Replace	Not Given	X

SVC

SVC

Short

SVC

CRG

SVC

CRU

SVC

11, >> 8.30

	61602-47180	PANEL SUB-ASSY, FENDER REAR LH	0.00	\$871.50	0.00	\$0.00	Replace	Not Given	X
	61622-47060	TROUGH, BACK DOOR, LH	0.00	\$103.40	0.00	\$0.00	Replace	Not Given	X
	61621-47050	TROUGH, BACK DOOR, RH	0.00	\$103.40	0.00	\$0.00	Replace	Not Given	X
	58327-47040	EXHAUST HEAT SHIELD INSULATOR, MAIN	0.00	\$141.00	0.00	\$0.00	Replace	Not Given	X
	17430-37B20	PIPE ASSY, EXHAUST, TAIL	0.00	\$1,649.00	0.00	\$0.00	Replace	Not Given	X
	17565-22040	SUPPORT, EXHAUST PIPE NO.5	0.00	\$49.10	0.00	\$0.00	Replace	Not Given	X
Total				\$23,742.30		\$1,607.72			

SVC

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023-47030	REAR BUMPER REINFORCEMENT	1.00	\$332.70	25.00	\$249.53	Replace	Replace
		66259-47010	COVER, REAR FLOOR UNDER CENTER	1.00	\$229.90	25.00	\$172.43	Replace	Replace
		58399-47030	COVER, REAR FLOOR UNDER, LH	1.00	\$241.90	25.00	\$181.43	Replace	Replace
		58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	1.00	\$651.00	25.00	\$488.25	Replace	Replace
		89997-30100	ANTENNA, ELECTRICAL KEY	1.00	\$72.00	10.00	\$64.80	Replace	Replace
		81551-47481	LENS & BODY, REAR COMBINATION LAMP, RH	1.00	\$339.60	10.00	\$305.64	Replace	Replace
Total					1,867.10		1,462.08		

PD

MIS

CR4

DD

CR4

SCR

4784.50

3069.20 /

1 850.60 /

2 574.00 650.00

4 741.80 4,569.80

P/P

\$4,569.80

6 days