



**Section A - Accident Details**

Registration Number	SHB5808Z
Case Reference Number	TAX/01/20/2066
Registration Date	20/12/2019
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	LIM THIAM HOE (LIN TIANHE)
Type of Accident	Head to Rear
Accident Date and Time	15/1/2020 2:35 PM
Accident Reported Date and Time	15/1/2020 4:24 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24105334
Special Instruction to ARC, if any	TP/ REAR PORTION/ NTUC - LKK
Prepared Date and Time	22/1/2020 11:14 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,933.00	\$850.00
Total Spray Cost	\$3,312.00	\$550.00
Total Spare Part Cost	\$20,756.32	\$3,069.80
Total Other Cost	\$1,480.00	\$120.00
<b>TOTAL COST</b>	<b>\$27,481.32</b>	<b>\$4,589.80 (P/P)</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	11.0	6.0
Prepared / Adjusted By	Kim Ming Chin	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	30/01/2020 5:03 PM	30/01/2020 5:15 PM
Signature		
Remarks	Initial estimate = 9 days SUP = 2 days	P/P Repair, Before paint photo

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-2004-0170	Invoice Number	
Quotation Date	15.04.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR SPARE TYRE PANEL	\$300.00	\$150.00
TO REPAIR PANEL SIDE ROOF LH	\$150.00	\$100.00
TO REPLACE REAR END PANEL	\$300.00	\$200.00
TO REPAIR REAR PORTION	\$1,183.00	\$400.00
<b>Total Labour</b>	<b>\$1,933.00</b>	<b>\$850.00</b>

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$150.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY TROUGH BACK DOOR LH	\$180.00	\$0.00
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
TO RESPRAY LH RAIL ROOF SIDE	\$180.00	\$100.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$3,312.00</b>	<b>\$550.00</b>

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$40.00
TO REMOVE & REFIT EXHAUST	\$120.00	\$0.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00

TO WASH AND VACUUM	\$60.00	\$0.00
<b>Total Other Costs</b>	<b>\$1,480.00</b>	<b>\$120.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$485.60	25.00	\$364.20	Replace	Replace ✓
		52599-68030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.50	0.00	\$0.00	Replace	Not Given ✗
		52462-47030	PAD, REAR BUMPER, NO.2	2.00	\$4.00	25.00	\$6.00	Replace	Replace ✓
		52462-47130	PAD, REAR BUMPER, NO.3	2.00	\$11.00	25.00	\$16.50	Replace	Replace ✓
		52191-47030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.30	0.00	\$0.00	Replace	Not Given ✗
		52462-47020	PAD, REAR BUMPER, NO.1	2.00	\$4.00	25.00	\$6.00	Replace	Replace ✓
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.50	25.00	\$33.75	Replace	Replace ✓
		52576-47060	RETAINER, RR BUMPER, LH	0.00	\$132.60	0.00	\$0.00	Replace	Not Given ✗
		52575-47060	RETAINER, RR BUMPER, RH	0.00	\$132.60	0.00	\$0.00	Replace	Not Given ✗
		52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$374.50	25.00	\$280.88	Replace	Replace ✓
		52169-47070	COVER, GUARD RR BUMPER LOWER	1.00	\$22.00	25.00	\$16.50	Replace	Replace ✓
		52461-47070	PAD, RR BUMPER, CTR	3.00	\$11.00	25.00	\$24.75	Replace	Replace ✓
		52591-47080	SEAL, RR BUMPER, RH	0.00	\$118.30	0.00	\$0.00	Replace	Check ✗
		52592-47080	SEAL, RR BUMPER, LH	0.00	\$118.30	0.00	\$0.00	Replace	Check ✗
		52023-47030	REAR BUMPER REINFORCEMENT	0.00	\$332.70	0.00	\$0.00	Replace	Check ✗
		58398-47050	COVER, REAR FLOOR UNDER, RH	0.00	\$175.10	0.00	\$0.00	Replace	Check ✗
		66259-47010	COVER, REAR FLOOR UNDER CENTER	0.00	\$229.90	0.00	\$0.00	Replace	Check ✗
		58399-47030	COVER, REAR FLOOR UNDER, LH	0.00	\$241.90	0.00	\$0.00	Replace	Check ✗
		81910-47030	REAR BUMPER REFLECTOR ASSY,	0.00	\$39.00	0.00	\$0.00	Replace	Check ✗
		81920-47030	REAR BUMPER REFLECTOR ASSY,	0.00	\$39.00	0.00	\$0.00	Replace	Check ✗
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		76801-47170-A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	0.00	\$913.60	0.00	\$0.00	Replace	Not Given ✗
		75403-48010	EMBLEM SUB-ASSY REAR	0.00	\$47.90	0.00	\$0.00	Replace	Not Given ✗
		75441-47220	NAME PLATE (HYBRID), LUGGAGE	0.00	\$54.60	0.00	\$0.00	Replace	Not Given ✗
		75442-47200	NAME PLATE (PRIUS), LUGGAGE	0.00	\$54.60	0.00	\$0.00	Replace	Not Given ✗
			SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given ✗
			STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given ✗
			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace ✓
			NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace ✓
		76085-47916	SPOILER SUB-ASSY, REAR	0.00	\$1,575.40	0.00	\$0.00	Replace	Not Given ✗
		81006-47030	LAMP SET, STOP CENTER	0.00	\$192.30	0.00	\$0.00	Replace	Not Given ✗
		67005-47530	TAIL GATE PANEL SUB-ASSY, BACK DOOR	0.00	\$1,147.80	0.00	\$0.00	Replace	Not Given ✗
		TMKONG-TAILG	AUTO TAILGATE SYSTEM	0.00	\$2,520.00	0.00	\$0.00	Replace	Not Given ✓
		69478-47010	TAIL GATE CUSHION, BACK DOOR, RH & LH	0.00	\$9.90	0.00	\$0.00	Replace	Not Given ✗
		75129-13020	TAIL GATE CUSHION, REAR LICENCE PLATE	0.00	\$2.60	0.00	\$0.00	Replace	Not Given ✗
		67881-47051	TAIL GATE WEATHERSTRIP, BACK	0.00	\$372.30	0.00	\$0.00	Replace	Check ✗
		56117-50140	TAIL GATE DAM, BACK DOOR GLASS UPPER	0.00	\$28.90	0.00	\$0.00	Replace	Not Given ✗
		75571-47011	TAIL GATE MOULDING GLASS, BACK DOOR	0.00	\$35.50	0.00	\$0.00	Replace	Not Given ✗

SMRT Accident Vehicle Repair Estimates

Date Generated : 17/04/2020

User ID PohSuan

	68105-47292	TAIL GATE GLASS SUB-ASSY, BACK DOOR	0.00	\$1,656.70	0.00	\$0.00	Replace	Not Given	X
	64801-47031	TAIL GATE LOWER GLASS SUB-ASSY, BACK	0.00	\$761.40	0.00	\$0.00	Replace	Not Given	X
	56117-50140	TAIL GATE DAM, BACK DOOR GLASS UPPER	0.00	\$28.90	0.00	\$0.00	Replace	Not Given	X
	75575-47051	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$23.60	0.00	\$0.00	Replace	Not Given	X
	75573-47110	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$30.90	0.00	\$0.00	Replace	Not Given	X
	75574-47040	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$30.90	0.00	\$0.00	Replace	Not Given	X
		SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
	68810-47061	TAIL GATE BACK DOOR HINGE ASSY, LH	0.00	\$61.00	0.00	\$0.00	Replace	Not Given	X
	68810-47061	TAIL GATE BACK DOOR HINGE ASSY, RH	0.00	\$61.00	0.00	\$0.00	Replace	Not Given	X
	69350-47050	TAIL GATE LOCK ASSY, BACK DOOR	0.00	\$467.00	0.00	\$0.00	Replace	Check	X
	69321-47010	TAIL GATE LOCK COVER, BACK DOOR	0.00	\$30.20	0.00	\$0.00	Replace	Not Given	X
	69430-52050	TAIL GATE STRIKER ASSY, BACK DOOR	0.00	\$25.80	0.00	\$0.00	Replace	Not Given	X
	67750-47080-C0	TAILGATE BOARD ASSY	0.00	\$259.20	0.00	\$0.00	Replace	Not Given	X
	64721-47050-C0	TAILGATE BOARD, COVER	0.00	\$24.90	0.00	\$0.00	Replace	Not Given	X
	67751-47111-C0	TAILGATE TRIM, LOWER	0.00	\$225.20	0.00	\$0.00	Replace	Not Given	X
	58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$651.00	0.00	\$0.00	Replace	Check	X
	64716-47130-C0	END PANEL, COVER, DECK TRIM, REAR	0.00	\$126.70	0.00	\$0.00	Replace	Check	X
	64718-47080-C0	END PANEL, COVER, DECK TRIM SERVICE	0.00	\$48.50	0.00	\$0.00	Replace	Check	X
		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
	58311-47130	SPARE TYRE PANEL, PAN, REAR FLOOR	0.00	\$583.40	0.00	\$0.00	Replace	Check	X
	64995-47050	BOX, DECK FLOOR, RH	0.00	\$313.60	0.00	\$0.00	Replace	Check	X
	64997-47060	BOX, DECK FLOOR, LH	0.00	\$313.00	0.00	\$0.00	Replace	Check	X
	58415-47110-C2	BOARD, REAR FLOOR, NO.1	0.00	\$519.00	0.00	\$0.00	Replace	Check	X
	64730-47241-C2	PANEL ASSY, DECK TRIM SIDE, RH	0.00	\$355.90	0.00	\$0.00	Replace	Check	X
	64740-47191-C3	PANEL ASSY, DECK TRIM SIDE, LH	0.00	\$355.90	0.00	\$0.00	Replace	Check	X
	61018-47010	MEMBER SUB-ASSY, RAIL ROOT SIDE REAR LH	1.00	\$288.50	100.00	\$0.00	Replace	Repair	X
	81204-47010	LAMP ASSY, LICENSE PLATE	0.00	\$287.80	0.00	\$0.00	Replace	Not Given	X
	84840-47040	SWITCH ASSY, BACK DOOR OPENER	0.00	\$179.10	0.00	\$0.00	Replace	Not Given	X
	89997-30100	ANTENNA, ELECTRICAL KEY	0.00	\$72.00	0.00	\$0.00	Replace	Check	X
		REVERSE SENSOR, REAR BUMPER	1.00	\$180.00	0.00	\$180.00	Replace	Replace	X
		REVERSE CAMERA ( FOR TAILGATE)	0.00	\$230.30	0.00	\$0.00	Replace	Not Given	X
	81551-47481	LENS & BODY, REAR COMBINATION LAMP, RH	0.00	\$339.60	0.00	\$0.00	Replace	Check	X
	81561-47471	LENS & BODY, REAR COMBINATION LAMP, LH	0.00	\$339.60	0.00	\$0.00	Replace	Check	X
	81497-47040	COVER, REAR COMBINATION LAMP, RH	0.00	\$69.90	0.00	\$0.00	Replace	Check	X
	81498-47040	COVER, REAR COMBINATION LAMP, LH	0.00	\$69.90	0.00	\$0.00	Replace	Check	X
	81457-47020	LENS & BODY, REAR COMBINATION LAMP,	1.00	\$261.00	10.00	\$234.90	Replace	Replace	X
	81456-47020	LENS & BODY, REAR COMBINATION LAMP,	0.00	\$261.00	0.00	\$0.00	Replace	Check	X
	81580-47070	LAMP ASSY, REAR, RH	1.00	\$293.60	10.00	\$264.24	Replace	Replace	X
	81590-47070	LAMP ASSY, REAR, LH	0.00	\$293.60	0.00	\$0.00	Replace	Check	X
	82162-47P90	WIRE, FLOOR, NO.2	0.00	\$142.40	0.00	\$0.00	Replace	Not Given	X
	51931-47030	CARRIER, SPARE WHEEL	0.00	\$20.80	0.00	\$0.00	Replace	Check	X
	61601-47150	PANEL SUB-ASSY, FENDER REAR RH	0.00	\$871.50	0.00	\$0.00	Replace	Not Given	X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
 60 Woodlands Industrial Park E4, Singapore  
 FAX Number 63685592  
 Estimator Telephone Number 68662623  
 Accident Reporting Number 68662672

Date Generated : 17/04/2020  
 User ID PohSuan

	61602-47180	PANEL SUB-ASSY, FENDER REAR LH	0.00	\$871.50	0.00	\$0.00	Replace	Not Given X
	61622-47060	TROUGH, BACK DOOR, LH	0.00	\$103.40	0.00	\$0.00	Replace	Not Given X
	61621-47050	TROUGH, BACK DOOR, RH	0.00	\$103.40	0.00	\$0.00	Replace	Not Given X
	58327-47040	EXHAUST HEAT SHIELD INSULATOR, MAIN	0.00	\$141.00	0.00	\$0.00	Replace	Not Given X
	17430-37B20	PIPE ASSY, EXHAUST, TAIL	0.00	\$1,649.00	0.00	\$0.00	Replace	Not Given X
	17565-22040	SUPPORT, EXHAUST PIPE NO.5	0.00	\$49.10	0.00	\$0.00	Replace	Not Given X
<b>Total</b>				<b>\$23,742.30</b>		<b>\$1,607.72</b>		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023-47030	REAR BUMPER REINFORCEMENT	1.00	\$332.70	25.00	\$249.53	Replace	Replace
		66259-47010	COVER, REAR FLOOR UNDER CENTER	1.00	\$229.90	25.00	\$172.43	Replace	Replace
		58399-47030	COVER, REAR FLOOR UNDER, LH	1.00	\$241.90	25.00	\$181.43	Replace	Replace
		58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	1.00	\$651.00	25.00	\$488.25	Replace	Replace
		89997-30100	ANTENNA, ELECTRICAL KEY	1.00	\$72.00	10.00	\$64.80	Replace	Replace
		81551-47481	LENS & BODY, REAR COMBINATION LAMP, RH	1.00	\$339.60	10.00	\$305.64	Replace	Replace
<b>Total</b>					<b>1,867.10</b>		<b>1,462.08</b>		

DD  
 MIS  
 CR4  
 DD  
 CR4  
 SCR

3069.80 /  
 + 850.00 /  
 + ~~675.00~~ 650.00  
 -----  
 4 ~~509~~ .80 4,569.80

P/P

\$4,569.80

6 days