

ASS. REG. BY: Sun Pin

REF:


NTYC CS/INC20001046/QVf3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: FBE 37965
 Policy No: 5107503690 (14/01/2019 - 31/03/2020)
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHB 5808 Z Yr Regn: 20/12/2014
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius 4 FL c.c. 1745
 Colour: Maroon A/C: Insured / Std / NI / NA
 Sp. Reading: 62.37 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTDKB3FU703089241

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brakes: Inorder / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rlm / STD A/Rlm or
 Tyre Size: F: 195 / 65 R15
 R: 195 / 65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Dunlop

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 15/01/2020 D.O.I. 16/01/2020
 Survey held at SMRT

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>SHB 5808 - NJM / INC 100785 / MYI / DOA - 21/04/2010 TP</u>
	<u>PBE 37965 - X TAX/01/20/2066</u>
	<u>* Pending for estimate FBE 37965</u>

Date/Time, File Pass to? ☐ : Prel. Report1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Rep. Form: _____

Lump Sum / L.E.I. : _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, SI

Phone

Others

TOTAL

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No.(For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	5107503690		TAN CHANG YOU	S8409278I	GMC	Third Party	FBE3796S	FBE3796S	14/02/2019	31/03/2020

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	369K

Vehicle Details

Vehicle No.:	SHB5808Z
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS SDR HATCHBACK (AUTO)
Primary Colour:	Maroon
Manufacturing Year:	2019
Engine No.:	2ZR2F34032
Chassis No.:	JTDKB3FU703089241
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	20 Dec 2019
First Registration Date:	20 Dec 2019
Transfer Count:	0
Actual ARF Paid:	\$14,530.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Dec 2027
PARF Rebate Amount:	\$10,897.00

Intended COE Rebate Details

COE Expiry Date:	19 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$25,581.00
COE Rebate Amount:	\$25,331.00
Total Rebate Amount:	\$36,228.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 17 Jan 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/01/2020 16:17
Date Of Accident	15/01/2020 14:35
Exact Location Of Accident	CHOA CHU KANG AVE 4 LP 31
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5808Z
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	1XXXXX369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	LIM THIAM HOE
NRIC No	SXXXX812A
Date Of Birth	31/07/1972
Occupation	OUTDOOR
Date Of Driving Pass	24/09/1993
Driving Experience	26 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 11
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : UNKNOWN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name CHOA CHU KANG NPC
 Police Station Address ROAD: 20 CHOA CHU KANG ST 52 #01-02 , POSTCODE: 689286 ,
 COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20200115/2130

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBE3796S
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category MOTORCYCLE
 Name of Driver UNKNOWN
 NRIC/Passport Number
 Contact Number
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

UNKNOWN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBE3796S

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

Choa Chu Kang Ave 4

A - 5HB58082

B - FBE 37965

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
HRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, controlling, handling and/or dealing with my claims (collectively the "Purposes").
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be stored / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders;



Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(If driver is not the policyholder)

Date & Time: 15/01/2020

[Signature]
15/1/2020

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20200115/2130

1 of 3

Report No. T/20200115/2130

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/01/2020 15:42	Vide Report No.: J/20200115/0076	Station Diary No.: 81
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: LIM THIAM HOE			Address: APT BLK 330 WOODLANDS AVENUE 1 #10-445 SINGAPORE 730330		
ID Type / ID No.: NRIC NO / S7226812A			Contact No.: Home/Office: Mobile: 84842129		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 47	Date of Birth: 31/07/1972	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3,4,5 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 15/01/2020 14:35	Type of Location: Straight Road
Location: Along Road 1 CHOA CHU KANG AVENUE 4 In Front of Blk 429 CCK Ave 4. Lamp Post Number: 31				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Light
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBE3796S	Motorcycle				Seriously Damaged	0
SHB5808Z	Car				Seriously Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: Nil		



**SINGAPORE
POLICE FORCE**



T/20200115/2130

3 of 3

Report No. T/20200115/2130

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J/

Sgt 2 CHUA KEE LENG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

15/01/2020 15:42

Officer-In-Charge Of Case:

TP./G.I.T./

SIGNATURE

Sr Staff Sgt CHONG GUAN FATT

Contact No.: 65476083

Classification Of Case:

Authentication Stamp

NP168

Case Details

Case Reference Number :

TAX/01/20/2066

Type of Repair : Accident Repair

Vehicle Registration Number : SHB5808Z

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-10239-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 15/01/2020 06:35 AM

Vehicle Age(In Months) : 1

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	485.60	485.60	25.00	364.20	Replace	1	364.20	Replace	✓ CRU
One Time Key In	Main			STOPPER, RR BUMPER, RH & LH	2	4.50	9.00	25.00	6.75	Replace	0	0	Not Give	✗ X SVC
One Time Key In	Main			PAD, REAR BUMPER, NO.2	2	4.00	8.00	25.00	6.00	Replace	2	6.00	Replace	✓ Neg
One Time Key In	Main			PAD, REAR BUMPER, NO.3	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace	✓ Neg
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.30	22.60	25.00	16.95	Replace	0	0	Not Give	✗ X SVC
One Time Key In	Main			PAD, REAR BUMPER, NO.1	2	4.00	8.00	25.00	6.00	Replace	2	6.00	Replace	✓ Neg
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.50	45.00	25.00	33.75	Replace	10	33.75	Replace	✓ Neg
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	132.60	132.60	25.00	99.45	Replace	0	0	Not Give	✗ X SVC
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	132.60	132.60	25.00	99.45	Replace	0	0	Not Give	✗ X SVC
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	374.50	374.50	25.00	280.88	Replace	1	280.88	Replace	✓ CRU

Total Spare Part Cost 19,294.25

Surveyor Total 1,607.72

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 19,294.25

Final Sur Total 1,607.72

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	22.00	22.00	25.00	16.50	Replace	1	16.50	Replace	✓ Mis
One Time Key In	Main			PAD, RR BUMPER, CTR	3	11.00	33.00	25.00	24.75	Replace	3	24.75	Replace	✓ Nec
One Time Key In	Main			SEAL, RR BUMPER, RH	1	118.30	118.30	25.00	88.72	Replace	0	0	Check	• XSV
One Time Key In	Main			SEAL, RR BUMPER, LH	1	118.30	118.30	25.00	88.72	Replace	0	0	Check	• XSV
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	332.70	332.70	25.00	249.52	Replace	0	0	Check	• XSV
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	175.10	175.10	25.00	131.32	Replace	0	0	Check	• XSV
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	229.90	229.90	25.00	172.43	Replace	0	0	Check	• XSV
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	241.90	241.90	25.00	181.43	Replace	0	0	Check	• XSV
One Time Key In	Main			REAR BUMPER REFLECTOR ASSY, REFLEX, RH	1	39.00	39.00	25.00	29.25	Replace	0	0	Check	• XSV
One Time Key In	Main			REAR BUMPER REFLECTOR ASSY, REFLEX, LH	1	39.00	39.00	25.00	29.25	Replace	0	0	Check	• XSV
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓ Nec
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	913.60	913.60	25.00	685.20	Replace	0	0	Not Give	• XSV
One Time Key In	Main			EMBLEM SUB-ASSY REAR	1	47.90	47.90	25.00	35.92	Replace	0	0	Not Give	• XSV
One Time Key In	Main			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	54.60	54.60	25.00	40.95	Replace	0	0	Not Give	• XSV
One Time Key In	Main			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	54.60	54.60	25.00	40.95	Replace	0	0	Not Give	• XSV
						Total Spare Part Cost		19,294.25		Surveyor Total		1,607.72		
						Lump Sum Discount (%)		0.00		Lump Sum Dis (%)		0		
						Final Spare Part Cost		19,294.25		Final Sur Total		1,607.72		

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	• XSV
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	• XSV
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	1	35.00	Replace	• / SCH
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	1	25.00	Replace	• / SCH
One Time Key In	Main			SPOILER SUB-ASSY, REAR	1	1,575.40	1,575.40	25.00	1,181.55	Replace	0	0	Not Give	• XSV
One Time Key In	Main			LAMP SET, STOP CENTER	1	192.30	192.30	10.00	173.07	Replace	0	0	Not Give	• XSV
One Time Key In	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	1,147.80	1,147.80	25.00	860.85	Replace	0	0	Not Give	• XSV
One Time Key In	Main			AUTO TAILGATE SYSTEM	1	2,520.00	2,520.00	10.00	2,268.00	Replace	0	0	Not Give	• XSV
One Time Key In	Main			TAIL GATE CUSHION, BACK DOOR, RH & LH	1	9.90	9.90	25.00	7.43	Replace	0	0	Not Give	• XSV
One Time Key In	Main			TAIL GATE CUSHION, REAR LICENCE PLATE	2	2.60	5.20	25.00	3.90	Replace	0	0	Not Give	• XSV
One Time Key In	Main			TAIL GATE WEATHERSTRIP, BACK DOOR	1	372.30	372.30	25.00	279.23	Replace	0	0	Check	• XSV
One Time Key In	Main			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	1	28.90	28.90	25.00	21.67	Replace	0	0	Not Give	• XSV
One Time Key In	Main			TAIL GATE MOULDING GLASS, BACK DOOR	1	35.50	35.50	25.00	26.63	Replace	0	0	Not Give	• XSV
One Time Key In	Main			TAIL GATE GLASS SUB-ASSY, BACK DOOR	1	1,656.70	1,656.70	25.00	1,242.53	Replace	0	0	Not Give	• XSV
One Time Key In	Main			TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	1	761.40	761.40	25.00	571.05	Replace	0	0	Not Give	• XSV
One Time Key In	Main			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	1	28.90	28.90	25.00	21.67	Replace	0	0	Not Give	• XSV

Total Spare Part Cost 19,294.25

Surveyor Total 1,607.72

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 19,294.25

Final Sur Total 1,607.72

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS , BACK DOOR	1	23.60	23.60	25.00	17.70	Replace	0	0	Not Give	*XSVC
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS , BACK DOOR , RH	1	30.90	30.90	25.00	23.17	Replace	0	0	Not Give	*XSVC
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS , BACK DOOR , LH	1	30.90	30.90	25.00	23.17	Replace	0	0	Not Give	*XSVC
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	0	0	Not Give	*XSVC
One Time Key In	Main			TAIL GATE BACK DOOR HINGE ASSY, LH	1	61.00	61.00	25.00	45.75	Replace	0	0	Not Give	*XSVC
One Time Key In	Main			TAIL GATE BACK DOOR HINGE ASSY, RH	1	61.00	61.00	25.00	45.75	Replace	0	0	Not Give	*XSVC
One Time Key In	Main			TAIL GATE LOCK ASSY, BACK DOOR	1	467.00	467.00	10.00	420.30	Replace	0	0	Check	*XSVC
One Time Key In	Main			TAIL GATE LOCK COVER , BACK DOOR	1	30.20	30.20	25.00	22.65	Replace	0	0	Not Give	*XSVC
One Time Key In	Main			TAIL GATE STRIKER ASSY, BACK DOOR	1	25.80	25.80	25.00	19.35	Replace	0	0	Not Give	*XSVC
One Time Key In	Main			TAILGATE BOARD ASSY	1	259.20	259.20	25.00	194.40	Replace	0	0	Not Give	*XSVC
One Time Key In	Main			TAILGATE BOARD , COVER	1	24.90	24.90	25.00	18.67	Replace	0	0	Not Give	*XSVC
One Time Key In	Main			TAILGATE TRIM , LOWER	1	225.20	225.20	25.00	168.90	Replace	0	0	Not Give	*XSVC
One Time Key In	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	651.00	651.00	25.00	488.25	Replace	0	0	Check	*XSVC
One Time Key In	Main			END PANEL , COVER, DECK TRIM, REAR	1	126.70	126.70	25.00	95.03	Replace	0	0	Check	*XSVC
One Time Key In	Main			END PANEL , COVER, DECK TRIM SERVICE HOLE	1	48.50	48.50	25.00	36.38	Replace	0	0	Check	*XSVC
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	*XSVC

Total Spare Part Cost 19,294.25

Surveyor Total 1,607.72

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 19,294.25

Final Sur Total 1,607.72

SMRT Recommendation										Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			SPARE TYRE PANEL , PAN, REAR FLOOR	1	583.40	583.40	25.00	437.55	Replace	0	0	Check * XSV
One Time Key In	Main			BOX, DECK FLOOR, RH	1	313.60	313.60	25.00	235.20	Replace	0	0	Check * XSV
One Time Key In	Main			BOX, DECK FLOOR, LH	1	313.00	313.00	25.00	234.75	Replace	0	0	Check * XSV
One Time Key In	Main			BOARD, REAR FLOOR, NO.1	1	519.00	519.00	25.00	389.25	Replace	0	0	Check * XSV
One Time Key In	Main			PANEL ASSY, DECK TRIM SIDE, RH	1	355.90	355.90	25.00	266.92	Replace	0	0	Check * XSV
One Time Key In	Main			PANEL ASSY, DECK TRIM SIDE, LH	1	355.90	355.90	25.00	266.92	Replace	0	0	Check * XSV
One Time Key In	Main			MEMBER SUB-ASSY, RAIL ROOT SIDE REAR LH	1	288.50	288.50	25.00	216.38	Replace	1	0	Repair * X R
One Time Key In	Main			LAMP ASSY, LICENSE PLATE	2	287.80	575.60	10.00	518.04	Replace	0	0	Not Give * XSV
One Time Key In	Main			SWITCH ASSY, BACK DOOR OPENER	1	179.10	179.10	10.00	161.19	Replace	0	0	Not Give * XSV
One Time Key In	Main			ANTENNA, ELECTRICAL KEY	1	72.00	72.00	10.00	64.80	Replace	0	0	Check * XSV
One Time Key In	Main			REVERSE SENSOR, REAR BUMPER	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace * / Show
One Time Key In	Main			REVERSE CAMERA (FOR TAILGATE)	1	230.30	230.30	10.00	207.27	Replace	0	0	Not Give * XSV
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, RH	1	339.60	339.60	10.00	305.64	Replace	0	0	Check * XSV
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, LH	1	339.60	339.60	10.00	305.64	Replace	0	0	Check * XSV
One Time Key In	Main			COVER, REAR COMBINATION LAMP, RH	1	69.90	69.90	25.00	52.43	Replace	0	0	Check * XSV
One Time Key In	Main			COVER, REAR COMBINATION LAMP, LH	1	69.90	69.90	25.00	52.43	Replace	0	0	Check * XSV
Total Spare Part Cost									19,294.25	Surveyor Total 1,607.72			
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0			
Final Spare Part Cost									19,294.25	Final Sur Total 1,607.72			

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
9	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	20	
10	Main	TO REPLACE SUNDRY PARTS	100.00	20	
11	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,480.00	120.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	19,294.25	1,607.72
Total Labour Cost	1,183.00	400.00
Total Spray Painting	2,952.00	300.00
Other	1,480.00	120.00
Overall Total	24,909.25	2,427.72
Lump Sum Repair Option		
Lump Sum Total	0.00	2,427.72
Surveyor Approved Amount		2,427.72
No of Repair Days*	9	4 <i>4 days</i>
Remarks		P/P Repair, Before paint photo
Surveyor Name		Sun Pin (LKK)
Signature		
Survey Date	22/01/2020	

Save

Clear

30/1/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Veron Chen (LKKAUTO)

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Thursday, 12 March 2020 1:11 PM
To: Veron Chen (LKKAUTO); Oi Sun Pin (LKK Auto)
Subject: RE: SHB 5808Z-DOA: 15/1/2020

Hi Veron,

This vehicle still under repair, some of the parts had no stock until now still waiting for spare parts.

Thanks & Regards
Poh Suan

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Thursday, 12 March 2020 12:46 PM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis); Oi Sun Pin (LKK Auto)
Subject: RE: SHB 5808Z-DOA: 15/1/2020

Dear Poh Suan,

Vehicle has been repaired? please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Friday, 14 February 2020 3:28 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com>
Subject: RE: SHB 5808Z-DOA: 15/1/2020

Hi Veron,

This vehicle still under repair, unable to finalize yet.

Thanks & Regards
Poh Suan

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, 11 February 2020 3:27 PM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis); Oi Sun Pin (LKK Auto)
Subject: SHB 5808Z-DOA: 15/1/2020

Dear Poh Suan,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)