



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI17002685/K1ha3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 19-01-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJZ 73J	Veh. Inspected	SHA 1600L
Policy No.	DMPCSN3029301600	Coverage (\$)	0.00
Claim No.	SNM17D00810/C02/3/LKKDS	Excess (\$)	0.00
Assign From		Assign Date	08/02/2017

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40 (A)	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KMHLB41UMHU097753	Colour	BLUE
Odometer	9192	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	8 mm
L/H Front Tyre	205/60 R16	HANKOOK	8 mm
R/H Rear Tyre	205/60 R16	HANKOOK	8 mm
L/H Rear Tyre	205/60 R16	HANKOOK	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/02/2017	Inspection Date	08/02/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1600L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	DENTED		
	FRONT FENDER (RH)		619.00	619.00
	LESS 20% DISCOUNT		-123.80	-123.80
			495.20	495.20
	<u>LABOUR</u>	NOT NECESSARY NOT NECESSARY		
	PANEL BEATING .		500.00	200.00
	SPRAY PAINTING CHARGE .		1,000.00	360.00
	WIRING CHARGE .		50.00	-
	TUFF KOTE.		50.00	-
			1,600.00	560.00
GRAND TOTAL			2,095.20	1,055.20
RECOMMENDED COST OF REPAIRS				1,055.20

Report Ref No. CC3/CT117002685/K1ha3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.