

ASS. REC. BY:

REF: CS/MSG 20001059/ FH302

Special Instruction:

Survivor: RamASSIGNMENT (Office)From (Person): Crystal Le

of

MSGDate/Time: 17.1.2020 10.52A.M

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SHA 8080R

Insured:

EV 7G

at Workshop m/s

Compadugro

Tel:

6214 8316

of

59 Iyong Drive

Policy No:

8 B29125 6A40MY

Claim No:

617701

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15.1.2019

CA / REV / REP. / REV 24 HRS

Date/Time:

17.1.2020 1059A.M

Person Contacted:

Jumani / Lamy

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHA 8080R - CS/FC1 170102701 Tied 3m2 RCM - 22/05/2018
	EV 7G - CS/TP10014533/RC xx RCM - 17/02/2010
2/1 -	Revised via menmen

ASSIGNED BY: Ram

REF: MS1G

## ASSIGNMENT

From \_\_\_\_\_ Date: 17-1-2020

Estimated Cost: \_\_\_\_\_

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHA 8080 R

at Workshop m/s Comfortdelgro

of 59 luyang Drive

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

X	X	X
N/S	O/S	

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SHA 8080 R Yr Regn: 24/11/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Hyundai i40 c.c 1685Colour: Yellow A/C: Insured / Std / NI / NASp. Reading: 346345 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMH LB41UMHVO91118Gen. Cond: Good / (Fair) / Poor / BurntSteering: (Inorder) / Jammed / Leaked / Burnt orBrake: (Inorder) / Jammed / Leaked / Burnt orModi: Nil / S/Rim / (STD A/Rim) orTyre Size: F: 205 / 60 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 15/1/2020 D.O.I. 17/1/2020Survey held at comfortdelgro (luyang)Des. of Damages: (Frt) / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 08 FEB 2020

L/S: \$5950/- with 4 repair days Cred: 6197.44; 51%

confirm on 24/1/2020 with Larry.

Date/Time, File Pass to?

☐ : Preli. Report1) 6/2 Typist☒ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 4Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 200

Transportation: \_\_\_\_\_

S + RS. SI

Photos

Others 11

TOTAL

211Rep. Formel: TPLump Sum / L.B. / C: 5950/-

Our Job Ref No : 305375174

Date : 23. Jan. 2020

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : RAM

Vehicle Reg No. : SHA8080R

Date of Accident: 15. Jan. 2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **MSIG** **EV7G**
2. The finalized amount shall be:
  - (a) Spare Parts after List discount
  - (b) Labour Charges
  - Total for Part-By-Part Repair Cost**
  - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: **\$5,950.00**  
**Final Lumpsum Repair cost**

3. Estimated normal period for repairs: **4** working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : **Larry Ng**

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : **Ram**

Date : **24/1/2020**

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Christina Wong

Date: 21 Jan 2020

## Preliminary Advice

Insured Vehicle No	: EV7G	Accident Date	: 15/01/2020
TP Vehicle No	: SHA8080R	Assignment Date	: 17/01/2020
Make	: HYUNDAI I40	Est. Duration of Repair	: 4.00
Date of Inspection	: 17/01/2020		
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,147.14
Revised Amount	:S\$	8,030.04
Check Items (Estimated)	:S\$	2,826.75
Total	:S\$	10,856.79
Lump Sum Repair	:S\$	

### Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- ( ) The vehicle is economical/not economical for repair.
- ( x ) The above survey was conducted on a 'without prejudice' basis.

## Summer Lee (LKK Auto)

---

**From:** Crystal Lee <crystal\_lee@sg.msig-asia.com>  
**Sent:** Friday, 17 January, 2020 10:52 AM  
**To:** Admin-D (LKKAuto); assignments  
**Cc:** Ong Zi Hui  
**Subject:** Survey Request - Manual Assigned  
**Attachments:** 2985\_001.pdf

### SHA8080R VS EV7G (MSIG) DOA: 15.01.2020 (Vehicle in w/shop)

#### Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,



Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | [crystal\\_lee@sg.msig-asia.com](mailto:crystal_lee@sg.msig-asia.com)



**MSIG**

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)    

A Member of **MS&AD** INSURANCE GROUP

---

**From:** Motor Survey <motorsurvey@sg.msig-asia.com>  
**Sent:** Thursday, 16 January 2020 5:43 PM  
**To:** Crystal Lee <crystal\_lee@sg.msig-asia.com>; Ong Zi Hui <zihui\_ong@sg.msig-asia.com>  
**Cc:** Helene Phua <helene\_phua@sg.msig-asia.com>; Winnie Chua <pingping\_chua@sg.msig-asia.com>  
**Subject:** FW: SHA8080R VS EV7G (MSIG) DOA: 15.01.2020

Dear Crystal/ Zi hui,

Kindly confirm with repairer if the taxi is in.

If yes, outsource this case.

Thanks.

Best Regards

Lee Wee Ho

Assistant Manager, Claims Services (In-House Survey)

D : +65 6643 1347 | F : +65 6225 7402 | [weeho\\_lee@sg.msig-asia.com](mailto:weeho_lee@sg.msig-asia.com)



**MSIG**

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Ng Nyuk Phin <[ngnp@cdge.com.sg](mailto:ngnp@cdge.com.sg)>

**Sent:** Thursday, 16 January 2020 3:42 PM

**To:** Motor Survey <[motorsurvey@sg.msig-asia.com](mailto:motorsurvey@sg.msig-asia.com)>

**Cc:** Lim Kwok Eng <[limke@cdge.com.sg](mailto:limke@cdge.com.sg)>

**Subject:** SHA8080R VS EV7G (MSIG) DOA: 15.01.2020

---

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Motor Claims,

Please see attached Repair Estimate and SAS. Kindly arrange to survey the taxi at 59 Loyang Drive.

Regards,

Larry Ng

ComfortDelgro Engineering Pte Ltd

Loyang Taxi Crash Repair

6214 8316



Think Before Printing

---

**From:** [canon@comfortdelgro.com.sg](mailto:canon@comfortdelgro.com.sg) <[canon@comfortdelgro.com.sg](mailto:canon@comfortdelgro.com.sg)>

**Sent:** Thursday, 16 January 2020 3:39 PM

**To:** Ng Nyuk Phin

**Subject:** Scan Image

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

A member of COMFORTDELGRO

Date/Time: 16.01.2020 15:08 Page : 1

Team: ARC Repair TP(CFSO)1	JOB CARD	Sales Order:	JC NO.: 305375174
CUSTOMER CITYCAB PTE LTD 7010070 383 SIN MING DRIVE Singapore SINGAPORE 575717 65551188 (O)	VAPS	REGN NO.: SHA8080R MAKE: HYUNDAI MODEL I-40 YR OF MANU 24.11.2016 CHASSIS CODE KMHLB41UMHU097118	MILEAGE FUEL E.....1/2.....F DATE/TIME IN 15.01.2020 20:40 TARGET DATE COMPLETION DATE/TIME:
COUNT CARD NO.			

JOB DESCRIPTION	
Accident Date: 15.01.2020 NATURE: 3P 15.01.2020	
S/NO	LABOR CODE
MSLA -	
DESCRIPTION	
17.01/0845 uplit ent. Tue	

CHECKED & PASSED OUT BY:	
SERVICE ADVISOR	CUSTOMER'S SIGNATURE
Acknowledgement Slip	Exit Pass
No.: SHA8080R LARRY	Vehicle No.: SHA8080R
Signature/Date	Name of Service Advisor Date
Returned to Service Reception upon collection	To be kept by Security Guard



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/01/2020 11:41
Date Of Accident	15/01/2020 19:40
Exact Location Of Accident	PIE(AIRPORT) NEAR LP434
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA8080R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	1XXXXX839G
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	CHEE KIAN YEO
NRIC No	SXXXX884G
Date Of Birth	10/08/1956
Occupation	OUTDOOR
Date Of Driving Pass	15/06/1978
Driving Experience	41 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94573187
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 544 WOODLANDS DRIVE 16 #10-93
Postcode	730544
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : - GENDER: : MALE
Passenger 2	NAME: : - GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	EV7G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	AARON GAN
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

FRONT

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number

SMD2627D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

ADONIS CORDELIEUS

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

REAR

No. Of Passenger (Including Driver)

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders

CITYCAR PTE LTD  
CO. REG. NO. 102602839G

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No: \_\_\_\_\_

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 15/1/20 at about 1940hrs when I Vel A was travelling ahead, noticed Vel C brakes lighted and slowed down my vehicle when at the same instant Vel B collided onto the rear of my vehicle which forced my vehicle to collide onto the rear of Vel C

DECLARATION

I/We declare the foregoing particulars are true in every respect.

CITYCAR PTE LTD  
CO. REG. NO. 190502039G

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHA8080R

DATE: 16. Jan. 2020

MAKE : HYUNDAI

MODEL : i40

DOA: 15. Jan. 2020

MSIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper Cover <i>cr</i>			\$562.30
10	Front Bumper Clips <i>rec</i>		\$2.20	\$22.00
1	Radiator Grille <i>Br</i>			\$417.10
1	Headlamp Support Panel <i>2xnn</i>			\$907.40
	Headlamp Support Top Cover <i>xnn</i>			\$222.60
1	Bonnet <i>BUC</i>			\$2,265.90
1	Bonnet Lock <i>1xnn</i>			\$36.90
1/2	Headlamp - LH / RH only <i>scr</i>		\$1,388.00	\$2,776.00
1	A/C Condenser <i>1Bt</i>			\$927.50
1	Radiator Assy <i>1xnn</i>			\$698.30
1	Radiator Fan, Motor, Cowling <i>1xnn</i>			\$792.95
2	Horn units - High / Low <i>1xnn</i>		\$73.80	\$147.60
1	Rear Bumper <i>des</i>			\$553.00
1	Rear Bumper Sponge <i>1xnn</i>			\$103.50
1	Rear Bumper Undercover <i>xnn</i>			\$228.00
10	Rear Bumper Clips <i>rec</i>		\$2.20	\$22.00
	Front LH Fender <i>2x(R)</i>			<del>1,120.00</del>
<b>SUB TOTAL</b>				<b>\$10,683.05</b>
<b>LESS 20%</b>				<b>\$2,136.61</b>
<b>DISCOUNTED TOTAL</b>				<b>\$8,546.44</b>
				6559.9
				52497.92
1	Reverse Sensor <i>1xnn</i>			\$135.70
1	Front License Plate & Casing <i>cr</i>			\$55.00
1	Front License Plate Trim Cover <i>br</i>			\$30.00
1	Advertisement - Rear Bumper <i>rec</i>			\$50.00
1	Advertisement - Rear Fenders RH/LH <i>rec</i>			\$200.00
1	Advertisement - Front Bumper <i>rec</i>			\$50.00
			\$100.00	
<b>Labour Charge</b>				<b>\$520.70</b>
1	Panel Beating			\$1,800.00
1	Spray Painting Charge			\$1,000.00
1	Wiring Charge			\$80.00
1	Remove/Refix A/C and top up gas			\$120.00
1	Tuff Kote			\$80.00
<b>TOTAL LABOUR</b>				<b>\$3,080.00</b>
<b>ESTIMATE TOTAL</b>				<b>\$12,147.14</b>
				12468.82

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

[illegible]

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Jan 2020		17 Jan 2020 11:18 <a href="#">Edit Adj Rpt</a>	<b>S\$5,950.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,950.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>




































  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>AARON GAN WEI TAT</b> , ID: S7938090C, Tel: +6597607607, Email: GANAARON@GMAIL.COM									
Main Claimant: <b>CITYCAB PTE LTD</b> , Co. Reg. No.: 199502839G									
Vehicle Reg. No.: <b>SHA8080R</b>		Date of Loss: 15/01/2020 19:00 - :59 [37 Months and 22 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 617701</b>		Policy/Cover Note No.: B29125694QMY (Comprehensive) Coverage: 24/05/2019 - 31/05/2020							
Vehicle Reg. No. (Insured): <b>EV7G</b>		Policy No. (Claimant):							
		Excess: S\$1,500.00							
Repairer: <b>ComfortDelGro Engineering Pte Ltd (Loyang)</b> 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>PARASURAM SHANMUGAM</b> ] ... [Final Rpt due 16/02/2020]									
Driver/Custodian (Insured): AARON GAN WEI TAT (40 / Male), NRIC: S7938090C, Tel: +6597607607 Email: GANAARON@GMAIL.COM									
Adj Asg. Remarks: on WP Manual assigned to LKK via email on 17/01/2020. (Manual Assign). Liab: NR. Contact: Larry Ng @ 6214 8316.									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SHA8080R (617701)**  
**[EV7G]**  
**TP**  
**CITYCAB PTE LTD**  
**Jan 15 2020 7:00PM**  
**[AARON GAN WEI TAT]**  
**ComfortDelGro Engineering Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/01/20 15:12	Adjuster Immediate Advice	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
2	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
3	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
4	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
5	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
6	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
7	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
8	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
9	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
10	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
11	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
12	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
13	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
14	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
15	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
16	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
17	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
18	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
19	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
20	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
21	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
22	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
23	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
24	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
25	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
26	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
27	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
28	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
29	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
30	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
31	23/01/20 16:22	Front View	 Load JPG	<input checked="" type="checkbox"/>
32	23/01/20 16:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	23/01/20 16:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	23/01/20 16:22	Reinspection Photo	 Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	23/01/20 16:22	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	23/01/20 16:22	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	23/01/20 16:22	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	23/01/20 16:22	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	23/01/20 16:22	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	24/01/20 09:24	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
41	24/01/20 09:24	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
42	24/01/20 09:24	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
43	24/01/20 09:24	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
44	24/01/20 09:24	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
45	24/01/20 09:24	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/01/20 10:45	TPD SHA8080R GIA REPORT(2/3) From:SC - Reg. No: EV7G, Claimant: AARON GAN WEI TAT	Load PDF	
2	17/01/20 10:47	TPD SHA8080R - ESTIMATE REPAIR	Load PDF	
3	17/01/20 10:47	TPD SHA8080R - PRI	Load PDF	
4	17/01/20 10:57	Arrange Survey	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	17/01/20 11:15	Survey Request - Manual Assigned	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/02/20 10:53	Supplementary	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20001059/FTF3E2

Date: 07/02/2020

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

B29125694QMY

Claimant Vehicle No : SHA8080R

Insured Vehicle No : EV7G

Date of Loss: 15/01/2020

Nature of Claim: TP

Claim No: 617701

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA8080R

Make &amp; Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No: D4FDGU693926

Reg. Date: 24/11/2016 (Man. Year: 2016)

Chassis No: KMHLB41UMHU097118

Colour: Yellow

Odometer: 346345 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,388.82	5,632.92	3,755.90	40.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	1,820.00	1,260.00	40.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,468.82</b>	<b>7,452.92</b>	<b>5,015.90</b>	<b>40.23</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,950.00</b>		
(S\$)	12,468.82	5,950.00	6,518.82	52.28
<b>+ GST 7.00/7.00% (S\$)</b>	<b>872.82</b>	<b>416.50</b>	<b>456.32</b>	<b>52.28</b>
<b>Nett Amount (S\$)</b>	<b>13,341.64</b>	<b>6,366.50</b>	<b>6,975.14</b>	<b>52.28</b>

### INSPECTION

Date of Assignment: 17/01/2020

Date Inspected: 17/01/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd  
(Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 4.0 days

---

**Adjuster:** PARASURAM SHANMUGAM**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 07 Feb 2020)
<b>Parts:</b>	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHA8080R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Cracked	562.30 FL	*562.30 FL
2	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*RADIATOR GRILLE	Broken	417.10 FL	*417.10 FL
4	1		*HEADLAMP SUPPORT PANEL	Not Necessary	907.40 FL	*- FL
5	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
6	1		*BONNET	Buckled	2,265.90 FL	*2,265.90 FL
7	1		*BONNET LOCK	Not Necessary	36.90 FL	*- FL
8	1		*HEADLAMP - LH / RH	O/S Scratched	2,776.00 FL	*1,388.00 FL
9	1		*A/C CONDENSER	Bent	927.50 FL	*927.50 FL
10	1		*RADIATOR ASSY	Not Necessary	698.30 FL	*- FL
11	1		*RADIATOR FAN, MOTOR, COWLING	Not Necessary	792.95 FL	*- FL
12	2		*HORN UNITS - HIGH / LOW	Not Necessary	147.60 FL	*- FL
13	1		*REAR BUMPER	Deformed	553.00 FL	*553.00 FL
14	1		*REAR BUMPER SPONGE	Not Necessary	103.50 FL	*- FL
15	1		*REAR BUMPER UNDERCOVER	Not Necessary	228.00 FL	*- FL
16	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
17	1		*FRONT LH FENDER (NPA)	Repair	0.00 FL	*- FL
18	1		*FRONT BUMPER REINFORCEMENT	Cut	402.10 FL	*402.10 FL
19	1		*REVERSE SENSOR	Not Necessary	135.70 FS	*- FS
20	1		*FRONT LICENSE PLATE & CASING	Cracked	55.00 FS	*55.00 FS
21	1		*FRONT LICENSE PLATE TRIM COVER	Broken	30.00 FS	*30.00 FS
22	1		*ADVERTISEMENT - REAR BUMPER	Necessary	50.00 FS	*50.00 FS
23	2		*ADVERTISEMENT - REAR FENDERS RH / LH	Necessary	200.00 FS	*200.00 FS
24	1		*ADVERTISEMENT - FRONT BUMPER	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,605.85</b>	<b>6,944.90</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>2,217.03</b>	<b>1,311.98</b>
<b>Total Parts (\$\$)</b>	<b>9,388.82</b>	<b>5,632.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,800.00	1,120.00
2	SPRAY PAINTING CHARGE	New	1,000.00	600.00
3	WIRING CHARGE	New	80.00	50.00
4	REMOVE / REFIX A/C AND TOP UP GAS	New	120.00	0.00
5	TUFF KOTE	New	80.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,080.00</b>	<b>1,820.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >