

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20001064/UPS3Q2

Date: 25/06/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MCV0001871
Claimant Vehicle No :	JPM5127	Insured Vehicle No :	YP2305C
Date of Loss:	09/01/2020	Nature of Claim:	TP
		Claim No:	MCV2020D0000148

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JPM5127	Engine No:	J2618400
Make & Model:	KIA PREGIO, 2.7 D (M)	Chassis No:	PNAKF5S03CG003488
Reg. Date:	19/07/2013 (Man. Year: 2013)	Odometer:	236024 km
Colour:	Silver		
Engine Capacity:	2665 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185 R14	Rear Tyre Size:	185 R14
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,884.00	3,846.60	3,037.40	44.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,140.00	2,170.00	970.00	30.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,024.00	6,016.60	4,007.40	39.98
Approved Total (Overridden) (S\$)		4,800.00		
Nett Amount (S\$)	10,024.00	4,800.00	5,224.00	52.11
+ Loss of Use (4.0 x S\$30.00/day) (S\$)		120.00		
Nett Liability (S\$)		4,920.00		
Global Sum Settlement (S\$)		4,900.00		

INSPECTION

Date of Assignment:	17/01/2020	
Date Inspected:	17/01/2020 Inspected At:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Mar 2020)	
Parts:	N/A	KIA PREGIO 2.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JPM5127)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,480.00 F	*1,255.00 FL
2	1		*TAILGATE KIA LOGO	Necessary	68.00 F	*68.00 FL
3	1		*TAILGATE INNER LOCK	Not Necessary	250.00 F	*- FL
4	1		*TAILGATE WEATHERSTRIP	Not Necessary	288.00 F	*- FL
5	1		*TAILGATE GLASS MOULDING	Necessary	181.00 F	*181.00 FL
6	1		*REAR BODY PANEL N/S	Badly Dented	1,850.00 F	*1,815.00 FL
7	1		*REAR BUMPER	Repair	799.00 F	*- FL
8	1		*REAR BUMPER SIDE RETAINERS	N/S Twisted	110.00 F	*55.00 FL
9	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
10	2		*TAILLAMPS	Cracked	960.00 F	*850.00 FL
11	1		*TAILGATE DAMPER N/S	Serviceable	288.00 F	*- FL
12	1		*TAILGATE RS STICKER	Not Necessary	50.00 F	*- FL
13	1		*TAILGATE PREGIO STICKER	Not Necessary	60.00 F	*- FL
14	1		*TAILGATE REFLECTOR N/S	Not Necessary	450.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,884.00	4,274.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	427.40
Total Parts (\$\$)	6,884.00	3,846.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	80.00
3	TO DISMANTLE & REFIX REAR BODY PANEL GLASS N/S	New	150.00	100.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
5	TO SPRAY RUST PROOFING	New	100.00	60.00
6	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,280.00	1,000.00
7	TO PUTTY & SPRAY PAINTING	New	1,280.00	850.00
Gross Labour Cost (\$\$)			3,140.00	2,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >