## ...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUBF	OLDER TRA	CKING		- (5)					
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj:	Submitted	Ins Auth'ed	Status	
Main	17 Jan 2020 Edit Reg		17 Jan 2020 00:00 Edit Adj Rpt	S\$1,300.00 Edit Estimates	F - 533,553	,300.00 ew Rpt		Report  Cancel Cas	
,	Main	R	eference	Claim I	Details		Docume	nts	Show All
CLAIM SU	BFOLDER DI	ETAILS				[Created	by adjuster]		
Insured:	KAVITA H	HARICHANDRA B	UDHRANI, ID: S.	2177663G				:	
Main Claimant:	-								
Vehicle Reg No.:	SJT727	1P		Date	of Loss:		0 00:00 - :59 hs and <b>16</b> Days	From LTA Reg Dat	te (Man Yr)]
Claim Type:	TP / 349	99083829SG		Polici Note	//Cover No.:	18000871	18	200	
Vehicle Reg No. (Insured):	SFF2858	В		Polic (Clair	y No. mant):				
				Exce	ss:				
Repairer:	Glockewe	erke (HQ) Blk 21	Kaki bukit road 4 #	01-02, 417810 Ka	ki Bukit	- Tel:			
Handling Insurer:	Kianmeng	.Chan1@aig.com	e Pte. Ltd. (Expre						
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	256-3561 [Han	dled by L	EE HOCK A	NN] [Final	<b>Rpt</b> due 29/01,	/2020]
ASSOCIAT	ED MAIL RE	CEIVED	382 88				,	/iew All Compo	se Case Mail
		: No OI GIA Rep : Request to upl	ort oad TP GIA Repor	t					
ALL ASSO	CIATED TAS	кѕ⊟				View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type Task	Group Subje	ct Handler	Assign	ned By	Completed O	n Created O	n Done?

#### **Claim Documents**

\*SJT7271P (3499083829SG) [SFF2858B] TP

#### Jan 13 2020 12:00AM [KAVITA HARICHANDRA BUDHRANI] Glockewerke

Pho	tos/Images		3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	il Print
1	20/01/20 09:31	Chassis Number	1 Load JPG	
2	20/01/20 09:32	Odometer Reading	1 Load JPG	<b>Y</b>
3	20/01/20 09:32	General View	1 Load JPG	<b>☑</b>
4	20/01/20 09:32	General View	1 Load JPG	<b>V</b>
5	20/01/20 09:32	General View	1 Load JPG	
6	20/01/20 09:32	General View	1 Load JPG	<b>V</b>
7	20/01/20 09:32	General View	■ Load JPG	
8	20/01/20 09:32	General View	■ Load JPG	<b>V</b>
9	20/01/20 09:32	General View	■ Load JPG	<b>✓</b>
10	20/01/20 09:32	General View	Load JPG	<b>V</b>
11	20/01/20 09:32	General View	Load JPG	
12	20/01/20 09:32	General View	1 Load JPG	
13	20/01/20 09:32	General View	1 Load JPG	
14	20/01/20 09:32	General View	Load JPG	<b>∀</b>
15	20/01/20 09:32	General View	Load JPG	· 🗹
16	20/01/20 09:32	General View	1 Load JPG	<b>V</b>
17	20/01/20 09:32	General View	1 Load JPG	<b>Z</b>
18	20/01/20 09:32	General View	1 Load JPG	<b>V</b>
19	20/01/20 09:32	General View	1 Load JPG	
20	20/01/20 09:32	General View	£ Load 3PG	<b>V</b>
21	20/01/20 09:32	General View	Load JPG	
22	20/01/20 09:32	General View	1 Load JPG	· 🔽
23	20/01/20 09:32	General View	1 Load JPG	· 🗹
24	20/01/20 09:32	General View	■ Load JPG	· 🗸
25	20/01/20 09:32	General View	■ Load JPC	
26	20/01/20 09:32	General View	1 Load JPG	· 🔽
27	20/01/20 09:32	General View	1 Load JPG	<b>Z</b>
28	20/01/20 09:32	General View	1 Load JPG	<b>I</b>
29	20/01/20 09:32	General View	1 Load JPG	· 🔽
30	20/01/20 09:32	General View	1 Load JPG	<b>V</b>
31	13/03/20 09:49	After Repair Photo	■ Load JPG	; <b>V</b>
32	13/03/20 09:49	After Repair Photo	€ Load JPG	<b>V</b>
33	13/03/20 09:49	After Repair Photo	1 Load JPC	<b>V</b>
34	13/03/20 09:49	After Repair Photo	■ Load JPC	<b>V</b>
		August (Maria Caracteristic Ca		
Doc	cumentation		1 per page \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	

Photos/Images		3 per p	3 per page 💟		
	107 - 100 - 100	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
No			0	Load PDF	
1	21/01/20 11:48	TP Singapore Accident Statement	- 0	2000	-

## **Documents Checklist**

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			^
			~
Show Remarks To: Handling Insurer  Note: Remarks are private unless you show it to other parties.			

## LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Email: sur@lkkauto.com;assignments@lkkauto.com Tel: 6256-3561 Fax: 6844-8805

## VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/AIG20001090/HTD3E2

Date:

30/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800087118

Claimant Vehicle

SJT7271P

Insured Vehicle No:

SFF2858B

No: Date of Loss:

13/01/2020

Nature of Claim:

TP

Claim No: 3499083829SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SJT7271P

Make & Model:

HYUNDAI HD AVANTE, 1.6 Sunroof (A)

Engine No:

G4FC9U669260

Reg. Date:

28/10/2009 (Man. Year: 2009)

Chassis No: Odometer:

KMHDU41BR9U783422 132652 km

Colour: Engine Capacity: Grey/Silver

1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

No

Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Front Right Side: Continental 5 mm Continental 5 mm Rear Left Side: Rear Right Side: Continental 5 mm Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,954.15	714.24	1,239.91	63.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	900.00	300.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,154.15	1,614.24	1,539.91	48.82
Approved Total (Overridden) (S\$)		1,300.00		
Nett Amount (S\$)	3,154.15	1,300.00	1,854.15	58.78

INSPECTION

Date Inspected:

Date of Assignment:

17/01/2020

17/01/2020

Inspected At:

Glockewerke (HQ)

Blk 21 Kaki bukit road 4 #01-02

Singapore 417810

Estimated Period of Repair:

3.0 days

Adjuster: LEE HOCK ANN

Manager:

DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# **REPAIR DETAILS**

Recommen	ded	Parts
Reconnici	ucu	aito

rt No. Particulars  *REAR RIGHT DOOR	Bent	782.00 FL	*782.00 FL
REAR RIGHT DOOR			102.001 =
*REAR RIGHT FENDER	Repair	980.00 FL	*- FL
	Crumpled	295.00 FL	*110.80 FL
L=ListItemDisc.	Sub Total (S\$) Items 5.00/20.00% (S\$)	<b>2,057.00</b> 102.85	<b>892.80</b> 178.56
	Total Parts (S\$)	1,954.15	714.24
	*REAR RIGHT DOOR HANDLE L=ListItemDisc.	*REAR RIGHT DOOR HANDLE Crumpled  L=ListItemDisc. Sub Total (S\$)  - List Item Discount on L Items 5.00/20.00% (S\$)	*REAR RIGHT PENDER 295.00 FL  *REAR RIGHT DOOR HANDLE Crumpled 295.00 FL  L=ListItemDisc. Sub Total (S\$) 2,057.00  - List Item Discount on L Items 5.00/20.00% (S\$) 102.85

# Recommended Miscellaneous Items There are no new miscellaneous items selected.

### Recommended Labour

	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PROVIDE WORKMANSHIP LABOUR TO REMOVE DAMAGE PARTS FOR ASSESSMENT AND TO NEW BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ADJUST STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT FROM THE ACCIDENT	New	600.00	450.00
2	TO RE-SPRAY PAINTING FOR CHANGE BODYPARTS, REPAIR PORTION AND WHERE CONSISTENT FROM THE ACCIDENT	New	600.00	450.00
	Gross Lab	our Cost (S\$)	1,200.00	900.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >